

OWNER: AIR RESOURCE GROUP
ADDRESS: BOX 3874
 LITTLE ROCK AR 72203
PHONE: 501-219-4690
FAX:

OPERATOR: AIR RESOURCE GROUP
ADDRESS: BOX 3874
 LITTLE ROCK AR 72203
PHONE: 501-219-4690
FAX:

ANALYST: JONATHAN RAMON
EMAIL: JRAMON@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
 316-462-2442 (FAX)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

AIRCRAFT SERIAL/REGNO: 60 098/N797PA **MODEL:** LEARJET 60 (CIMMS) **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 30-JAN-1997		7724.2 A/C HRS	as of 02-NOV-2009	A/C HRS	as of ___/___/___
		5497 AFL	as of 02-NOV-2009	AFL	as of ___/___/___
		2964.1 ACH	as of 13-OCT-2009	ACH	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-CA0033/31B4067-02 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 31-MAR-2004		LAST ACTUALS		CURRENT ACTUAL	
5453.3 ENG. HRS	5453.3 A/C HRS	7494.4 ENG. HRS	as of 02-NOV-2009	ENG. HRS	as of ___/___/___
3928 ENC		5337 ENC	as of 02-NOV-2009	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-CA0034/31B4067-02 **MODEL:** PW305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 31-MAR-2004		LAST ACTUALS		CURRENT ACTUAL	
5453.3 ENG. HRS	5453.3 A/C HRS	7466.8 ENG. HRS	as of 02-NOV-2009	ENG. HRS	as of ___/___/___
3928 ENC		5306 ENC	as of 02-NOV-2009	ENC	as of ___/___/___

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Work Packages

Aircraft HRS: 7724.2 Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	TIME
WORKCARD	PKG #			WARR EXP	NEXT DUE	REMAINING
				ADJ	ACTUAL	MAXLIMIT
CHAPTER 70	STANDARD PRACTICES - ENGINES					
700010	LEFT ENGINE CHANGE INSPECTION-AIRFRAME ITEMS PKG 1	MOS			16-APR-2005	ENGINE CHANGE
	REF:	HRS/MSC E/C			5981.1	
		AFL			4288	
700020	RIGHT ENGINE CHANGE INSPECTION-AIRFRAME ITEMS PKG 2	MOS			16-SEP-2005	ENGINE CHANGE
	REF:	HRS/MSC E/C			6249.4	
		AFL			4477	

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
CHAPTER 05										
TIME LIMITS/MAINTENANCE CHECKS										
+ 05-10-01-A1	PERFORM PHASE A1-300 HOUR	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
	REF: AMM 5-10-01	HRS/MSC	300	+25/-25	7.9		7720.6	8028.5	8053.5	304.3
		AFL					5492			
+ 05-10-02-A2	PERFORM PHASE A2-300 HOUR	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
	REF: AMM 5-10-02	HRS/MSC	300	+25/-25	7.9		7720.6	8028.5	8053.5	304.3
		AFL					5492			
+ 05-10-03-A3	PERFORM PHASE A3-300 HOUR	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
	REF: AMM 5-10-03	HRS/MSC	300	+25/-25	7.9		7720.6	8028.5	8053.5	304.3
		AFL					5492			
+ 05-10-04-A4	PERFORM PHASE A4-300 HOUR	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
	REF: AMM 5-10-04	HRS/MSC	300	+25/-25	7.9		7720.6	8028.5	8053.5	304.3
		AFL					5492			
+ 05-10-05-A5	PERFORM PHASE A5-300 HOUR	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
	REF: AMM 5-10-05	HRS/MSC	300	+25/-25	7.9		7720.6	8028.5	8053.5	304.3
		AFL					5492			
+ 05-10-06-A6	PERFORM PHASE A6-300 HOUR	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
	REF: AMM 5-10-06	HRS/MSC	300	+25/-25	7.9		7720.6	8028.5	8053.5	304.3
		AFL					5492			
+ 05-10-07-B1	PERFORM PHASE B1-600 HOUR	MOS	24	+14d/-14d			30-DEC-2008	30-DEC-2010	13-JAN-2011	419 d
	REF: AMM 5-10-07	HRS/MSC	600	+25/-25			7720.6	8320.6	8345.6	596.4
		AFL					5492			
+ 05-10-08-B2	PERFORM PHASE B2-600 HOUR	MOS	24	+14d/-14d			30-DEC-2008	30-DEC-2010	13-JAN-2011	419 d
	REF: AMM 5-10-08	HRS/MSC	600	+25/-25			7720.6	8320.6	8345.6	596.4
		AFL					5492			
+ 05-10-09-B3	PERFORM PHASE B3-600 HOUR	MOS	24	+14d/-14d			30-DEC-2008	30-DEC-2010	13-JAN-2011	419 d
	REF: AMM 5-10-09	HRS/MSC	600	+25/-25			7720.6	8320.6	8345.6	596.4
		AFL					5492			
+ 05-10-10-B4	PERFORM PHASE B4-600 HOUR	MOS	24	+14d/-14d			30-DEC-2008	30-DEC-2010	13-JAN-2011	419 d
	REF: AMM 5-10-10	HRS/MSC	600	+25/-25			7720.6	8320.6	8345.6	596.4
		AFL					5492			
+ 05-10-11-B5	PERFORM PHASE B5-600 HOUR	MOS	24	+14d/-14d			30-DEC-2008	30-DEC-2010	13-JAN-2011	419 d
	REF: AMM 5-10-11	HRS/MSC	600	+25/-25			7720.6	8320.6	8345.6	596.4
		AFL					5492			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
+ 05-10-12-B6	PERFORM PHASE B6-600 HOUR	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			30-DEC-2008 7720.6 5492	30-DEC-2010 8320.6	13-JAN-2011 8345.6	419 d 596.4
	REF: AMM 5-10-12									
+ 05-10-13-C1	PERFORM PHASE C1-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			30-DEC-2008 7720.6 5492	30-DEC-2012 8920.6	13-JAN-2013 8945.6	1150 d 1196.4
	REF: AMM 5-10-13									
+ 05-10-14-C2	PERFORM PHASE C2-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			30-DEC-2008 7720.6 5492	30-DEC-2012 8920.6	13-JAN-2013 8945.6	1150 d 1196.4
	REF: AMM 5-10-14									
+ 05-10-15-C3	PERFORM PHASE C3-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			30-DEC-2008 7720.6 5492	30-DEC-2012 8920.6	13-JAN-2013 8945.6	1150 d 1196.4
	REF: AMM 5-10-15									
+ 05-10-16-C4	PERFORM PHASE C4-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			30-DEC-2008 7720.6 5492	30-DEC-2012 8920.6	13-JAN-2013 8945.6	1150 d 1196.4
	REF: AMM 5-10-16									
+ 05-10-17-C5	PERFORM PHASE C5-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			30-DEC-2008 7720.6 5492	30-DEC-2012 8920.6	13-JAN-2013 8945.6	1150 d 1196.4
	REF: AMM 5-10-17									
+ 05-10-18-C6	PERFORM PHASE C6-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			30-DEC-2008 7720.6 5492	30-DEC-2012 8920.6	13-JAN-2013 8945.6	1150 d 1196.4
	REF: AMM 5-10-18									
+ 05-10-19-D1	PERFORM PHASE D1-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			17-APR-2006 6598.7 4701	17-APR-2014 8998.7	01-MAY-2014 9023.7	1623 d 1274.5
	REF: AMM 5-10-19									
+ 05-10-20-D2	PERFORM PHASE D2-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			17-APR-2006 6598.7 4701	17-APR-2014 8998.7	01-MAY-2014 9023.7	1623 d 1274.5
	REF: AMM 5-10-20									
+ 05-10-21-D3	PERFORM PHASE D3-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			17-APR-2006 6598.7 4701	17-APR-2014 8998.7	01-MAY-2014 9023.7	1623 d 1274.5
	REF: AMM 5-10-21									
+ 05-10-22-D4	PERFORM PHASE D4-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			17-APR-2006 6598.7 4701	17-APR-2014 8998.7	01-MAY-2014 9023.7	1623 d 1274.5
	REF: AMM 5-10-22									
+ 05-10-23-D5	PERFORM PHASE D5-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			17-APR-2006 6598.7 4701	17-APR-2014 8998.7	01-MAY-2014 9023.7	1623 d 1274.5
	REF: AMM 5-10-23									

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2 Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
+ 05-10-24-D6	PERFORM PHASE D6 2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			17-APR-2006 6598.7 4701	17-APR-2014 8998.7	01-MAY-2014 9023.7	1623 d 1274.5
	REF: AMM 5-10-24									
+ 05-10-25-3000 LDG	INSPECT 3000 LANDING	MOS HRS/MSC AFL					06-OCT-2009 7721.6 5493		8493 8518	2996
	REF: AMM 5-10-25		3000	+25/-25						
+ 05-10-26-6000 LDG	INSPECT MAJOR LANDING GEAR	MOS HRS/MSC AFL					06-OCT-2009 7721.6 5493		11493 11518	5996
	REF: AMM 5-10-26		6000	+25/-25						
+ 05-10-27-12 YR	INSPECT 12 YEAR AIRFRAME	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25	-249		06-OCT-2009 7721.6 5493	30-JAN-2021 11493	13-FEB-2021 11518	4103 d 5996
	REF: AMM 5-10-27		6000	+25/-25						
+ 05-10-28-12000 HR	INSPECT 12000 HOUR AIRFRAME	MOS HRS/MSC AFL	12000	+25/-25			30-JAN-1997 0 0	12000	12025	4275.8
	REF: AMM 5-10-28									
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02										
05-P&W-730005	NO. 1 ENGINE - CLEAN PRIMARY FUEL NOZZLES	MOS HRS/MSC O/C ENC					22-NOV-1996 0 0			
	REF:									
052000	NO. 1 ENGINE - MINOR INSPECTION ITEMS	MOS HRS/MSC ENC	300				30-DEC-2008 7490.8 5332	(7790.8) 8020.6		296.4
	REF:									
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02										
05-P&W-730005	NO. 2 ENGINE - CLEAN PRIMARY FUEL NOZZLES	MOS HRS/MSC O/C ENC					22-NOV-1996 0 0			
	REF:									
052000	NO. 2 ENGINE - MINOR INSPECTION ITEMS	MOS HRS/MSC ENC	300				30-DEC-2008 7436.2 5301	(7736.2) 7993.6		269.4
	REF:									
CHAPTER 08 LEVELING AND WEIGHING										
082000	WEIGHT AND BALANCE	MOS HRS/MSC A/R AFL					28-MAR-2006 6558.4 4675			
	REF: See Workcard									
CHAPTER 20 STANDARD PRACTICES - AIRFRAME										

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
206100	PERFORM PRECIPITATION STATIC (P-STATIC) TEST	MOS					30-JAN-1997		
	REF: AMM 20-61-00	HRS/MSC AFL	O/C				0 0		
CHAPTER 21 AIR CONDITIONING									
+ 05-10-29-H2130007	PERFORM CABIN LEAK RATE CHECK	MOS					30-DEC-2008		
	REF: See Workcard	HRS/MSC AFL	1200 +25/-25				7720.6 5492	8920.6 8945.6	1196.4
05-10-29-L2150053	FUNCTION TEST REFRIGERATION SYSTEM PRESSURE SWITCH	MOS					07-MAR-2008		
	REF: AMM 21-50-05-L2150053	HRS/MSC AFL ACH	600 +25/-25				7450.6 5282 2920.7	3520.7 3545.7	556.6
05-10-29-N2150019	PENETRANT INSPECT AC COMPRESSOR FAN BLADES	MOS					07-MAR-2008		
	REF: NDT PART 5 / 21-50-01	HRS/MSC AFL ACH	1200 +25/-25				7450.6 5282 2920.7	4120.7 4145.7	1156.6
212001	CHECK VALVE:COCKPIT AIR CHECK VALVE 6600423-016	MOS			TSN:0		23-JUL-1997		
	209	HRS/MSC AFL	O/C		TSN:0 TSN:0		15.3 12		
212003	CHECK VALVE:LEFT CABIN AIR CHECK VALVE 3202188-1	MOS			TSN:0		30-JAN-1997		
	SN-UNKNOWN	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
	REF: AMM 21-20-02								
212004	CHECK VALVE:RIGHT CABIN AIR CHECK VALVE 3202188-1	MOS			TSN:0		30-JAN-1997		
	SN-UNKNOWN	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
	REF: AMM 21-20-02								
212005	DIFFUSER:LEFT CABIN OVERHEAD DIFFUSER PN	MOS			TSN:0		30-JAN-1997		
	SN-UNKNOWN	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
	REF: AMM 21-20-03								
212006	DIFFUSER:RIGHT CABIN OVERHEAD DIFFUSER PN	MOS			TSN:0		30-JAN-1997		
	SN-UNKNOWN	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
	REF: AMM 21-20-03								
212007	MOTOR:AFT EVAPORATOR BLOWER MOTOR PN	MOS			TSN:0		30-JAN-1997		
	SN-UNKNOWN	HRS/MSC AFL	O/C		TSN:0 TSN:0		0 0		
	REF:								
212007A	MOTOR:INSPECT AFT EVAPORATOR BLOWER MOTOR BRUSHES	MOS					30-JAN-1997		
	REF:	HRS/MSC AFL	O/C				0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
212008	MOTOR:FWD EVAPORATOR BLOWER MOTOR PN SN-UNKNOWN REF: AMM 21-51-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
212101	BLOWER:CABIN EVAPORATOR BLOWER EM699-1 SN-UNKNOWN REF: AMM 21-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
212104	BLOWER:COCKPIT EVAPORATOR BLOWER EM607-2 501A REF: AMM 21-21-04	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			17-SEP-2003 5383.3 3867		
212105	BOX ASSEMBLY:COCKPIT BLOWER CONTROL BOX ASSEMBLY 6018203-2 SN-UNKNOWN REF: AMM 21-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
212155	MUFFLER ASSEMBLY:LEFT BLEED AIR MUFFLER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
212156	MUFFLER ASSEMBLY:RIGHT BLEED AIR MUFFLER ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
212201	COOLING FAN:LEFT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN PN SN-UNKNOWN REF: AMM 21-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
212202	COOLING FAN:RIGHT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN 030579 SN-UNKNOWN REF: AMM 21-22-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
212205	COOLING FAN:AVIONICS COOLING FAN PN SN-UNKNOWN REF: AMM 21-22-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213001	VALVE:PRIMARY OUTFLOW VALVE 6600812-4 SN-UNKNOWN REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213002	VALVE:SECONDARY OUTFLOW VALVE 6600812-10 SN-UNKNOWN REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213003	SELECTOR:CABIN AIR PRESSURE SELECTOR 2119828-1 SN-UNKNOWN REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
213004	CONTROLLER:CABIN PRESSURE CONTROLLER 2119830-4 38-F0131 REF: AMM 21-30-04	MOS HRS/MSC AFL	O/C				05-OCT-1999 2260.2 1580		
213005	CONTROLLER:MANUAL PRESSURE CONTROLLER 6600812-1 SN-UNKNOWN REF: AMM 21-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213006	FILTER:AIR FILTER 6600812-7 SN-UNKNOWN REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213008	SWITCH:PRESSURIZATION MODE SWITCH 95-6A-15-86-58022 SN-UNKNOWN REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213009	SWITCH:EMERGENCY DEPRESSURIZATION SWITCH 95-6A-14-H6-58284 SN-UNKNOWN REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213010	INDICATOR:CABIN PRESSURE INDICATOR 10403N03C00 B169 REF: AMM 21-30-10	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			23-OCT-1997 220.4 158		
213011	REGULATOR:VACUUM REGULATOR 131402-2 SN-UNKNOWN REF: AMM 21-30-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213012	PUMP:VACUUM PUMP 6019410-10 SN-UNKNOWN REF: AMM 21-30-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213013	CHECK VALVE:VACUUM CHECK VALVE PN SN-UNKNOWN REF: AMM 21-30-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213101	VALVE:LEFT EMERGENCY PRESSURIZATION VALVE 6600252-3 100 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-NOV-1997 270.7 199		
213102	VALVE:RIGHT EMERGENCY PRESSURIZATION VALVE 6600252-3 SN-UNKNOWN REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213103	SWITCH:LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 SN-UNKNOWN REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
213104	SWITCH:RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 SN-UNKNOWN REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213105	CHECK VALVE:LEFT CONDITIONED AIR CHECK VALVE 6600210-5 SN-UNKNOWN REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
213106	CHECK VALVE:RIGHT CONDITIONED AIR CHECK VALVE 6600210-5 7595AC REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
213107	CHECK VALVE:POSITIVE VENTILATION CHECK VALVE 9519-1-1 SN-UNKNOWN REF: AMM 21-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
214001	VALVE:FLOW CONTROL VALVE 320335-3 539 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-MAR-2008 7470.1 5300		
214002	HEAT EXCHANGER:HEAT EXCHANGER 6608060-5 SN-UNKNOWN REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
214101	HEATER:COCKPIT HEATER 7600804-2 SN-UNKNOWN REF: AMM 21-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
214102	SOLENOID:COCKPIT DIVERTER DOOR SOLENOID H2902-024 SN-UNKNOWN REF: AMM 21-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
214103	RESISTOR:COCKPIT DIVERTER DOOR RESISTOR 6018462-1 SN-UNKNOWN REF: AMM 21-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
214104	THERMOSTAT:COCKPIT DIVERTER DOOR THERMOSTAT 4344-145-97 SN-UNKNOWN REF: AMM 21-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
214201	HEATER:LEFT AUXILIARY CABIN HEATER 7026-1 SN-UNKNOWN REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
214202	HEATER:RIGHT AUXILIARY CABIN HEATER 7026-2 SN-UNKNOWN REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
214203	BOX:AUXILIARY HEAT OVERTEMPERATURE MONITOR BOX 6018166-002 SN-UNKNOWN REF: AMM 21-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215001	COMPRESSOR:AIR CONDITIONING COMPRESSOR 5419522-10 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				20-APR-2008 7513.5 5338		
215003	CONDENSER:CONDENSER 6608061-6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215004	RECEIVER/DRYER:RECEIVER/DRYER 7600805-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				20-APR-2008 7513.5 5338		
215005	SWITCH:FREON PRESSURE SWITCH 20-S112-5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215006	EVAPORATOR:COCKPIT EVAPORATOR 6600427-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215008	PRESSURE REGULATOR VALVE:COCKPIT EVAPORATOR PRESSURE REGULATOR VALVE ORIT-6-0/50-5/8-SAE SN-UNKNOWN REF: AMM 21-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215009	EVAPORATOR:CABIN EVAPORATOR 7600802-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215010	VALVE:CABIN EXPANSION VALVE BFF-B-C SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-FEB-2008 7444.8 5277		
215012	BOX:FREON MOTOR CONTROL BOX 5418598-6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215013	CONTACTOR:K61 FREON MOTOR CONTACTOR 6018460-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
215014	CONTACTOR:K62 FREON MOTOR CONTACTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
215015	CONTACTOR:K63 FREON MOTOR CONTACTOR PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
215016	CURRENT SENSOR:FREON MOTOR DIFFERENTIAL CURRENT SENSOR 268-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
215017	HOURLMETER:COMPRESSOR MOTOR HOURLMETER PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
215031	SWITCH:ABSOLUTE PRESSURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
215049	VALVE:COCKPIT EXPANSION VALVE GF-1/2-C SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-FEB-2008 7444.8 5277			
215101	MOTOR:FREON COMPRESSOR DRIVE (R-12) MOTOR 56-1-1 265 REF: AMM 21-50-02	MOS HRS/MSC AFL ACH	O/C	TSN:0 TSN:0 TSO:0			20-APR-2008 7513.5 5338 2920.7			
215101A	MOTOR:PERFORM FREON COMPRESSOR DRIVE (R-12) MOTOR COMPRESSOR MOTOR BRUSH WEAR INSPECTION - 05-10-29-K2150012 REF: AMM 21-50-02-K2150012	MOS HRS/MSC AFL ACH	600	+25/-25			20-APR-2008 7513.5 5338 2920.7	3520.7	3545.7	556.6
215120	FAN:CONDENSER FAN PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
216001	SETTING BOX:REMOTE CABIN TEMPERATURE SETTING BOX MS1826-1K SN-UNKNOWN REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
216002	SELECTOR:CREW TEMPERATURE SELECTOR PN SN-UNKNOWN REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
216003	SELECTOR:CABIN TEMPERATURE SELECTOR 6600423-12 SN-UNKNOWN REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
216004	INDICATOR:TEMPERATURE CONTROL INDICATOR 6608472-1 SN-UNKNOWN REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216005	CONTROLLER:COCKPIT TEMPERATURE CONTROLLER 6600423-2 SN-UNKNOWN REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216006	CONTROLLER:CABIN TEMPERATURE CONTROLLER 6600423-2 SN-UNKNOWN REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216007	SENSOR:COCKPIT TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216008	SENSOR:CABIN TEMPERATURE SENSOR 6600423-3 SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2005 6286.3 4501		
216009	BLOWER:COCKPIT TEMPERATURE SENSOR BLOWER PN SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216010	BLOWER:CABIN TEMPERATURE SENSOR BLOWER 6600231-1 SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216011	SENSOR:COCKPIT SKIN TEMPERATURE SENSOR 6600423-5 SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216012	SENSOR:CABIN SKIN TEMPERATURE SENSOR 6600423-5 SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216013	VALVE:COCKPIT TEMPERATURE CONTROL VALVE 6600423-016 308 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-MAY-1999 1863.6 1288		
216014	VALVE:CABIN TEMPERATURE CONTROL VALVE 6600423-13 SN-UNKNOWN REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216015	MOTOR:COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
216016	MOTOR:CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216017	REGULATOR:SERVO AIR PRESSURE REGULATOR 6600245-3 SN-UNKNOWN REF: AMM 21-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216018	CHECK VALVE:COCKPIT AIR DISTRIBUTION CHECK VALVE PN SN-UNKNOWN REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216019	CHECK VALVE:CABIN AIR DISTRIBUTION CHECK VALVE 6600423-7 SN-UNKNOWN REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216020	SENSOR:COCKPIT DUCT TEMPERATURE SENSOR 6600423-4 SN-UNKNOWN REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216021	SENSOR:CABIN DUCT TEMPERATURE SENSOR 6600423-4 SN-UNKNOWN REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216022	THERMOSTAT:COCKPIT DUCT OVERHEAT THERMOSTAT 3000-141-18 SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216023	THERMOSTAT:CABIN DUCT OVERHEAT THERMOSTAT 3000-141-18 SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216024	BOX:CLIMATE CONTROL BOX 6018448-1 SN-UNKNOWN REF: AMM 21-60-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216025	BOX:PILOT ELECTRICAL EQUIPMENT BOX 6018266-2 SN-UNKNOWN REF: AMM 21-60-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216050	SWITCH:MEMBRANE, CABIN TEMPERATURE SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
216101	INDICATOR:CABIN TEMPERATURE INDICATOR 6608486-1 SN-UNKNOWN REF: AMM 21-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
216102	SENSOR:CABIN TEMPERATURE INDICATOR SENSOR FG106P SN-UNKNOWN REF: AMM 21-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
218105	DUCT ASSEMBLY:LEFT TRANSITION DUCT ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
218106	DUCT ASSEMBLY:RIGHT TRANSITION DUCT ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
CHAPTER 22 AUTO FLIGHT									
221001	CONTROLLER:AUTOPILOT CONTROLLER 501-1679-02 1234 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C				14-JUL-2008 7628.2 5427		
221002	BOX:AUTOPILOT ELECTRICAL BOX 6018309V2-001 271324 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-JUL-2002 4902.9 3463		
221003	ACTUATOR:PITCH SERVO ACTUATOR 622-5027-102 H1RV REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C				15-JUL-2002 4888.4 3457		
221004	MOUNT:PITCH SERVO MOUNT 622-5029-101 SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
221005	BOX ASSY:PITCH TRIM AMPLIFIER BOX ASSY 5418419-8 SN-UNKNOWN REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
221006	ACTUATOR:ROLL SERVO ACTUATOR 622-5027-002 2528 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			01-NOV-1998 1280.7 887		
221007	RELAY BOX:ROLL DISCONNECT RELAY BOX 6018342-1 SN-UNKNOWN REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
221008	RELAY BOX:YAW DISCONNECT RELAY BOX 6018342-2 034126 REF: AMM 22-10-08	MOS HRS/MSC AFL	O/C				25-JUL-2001 4009.3 2832		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
221009	ACTUATOR:YAW SERVO ACTUATOR 622-5027-002 3941 REF: AMM 22-10-09	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			01-NOV-1998 1280.7 887		
221010	MOUNT:YAW SERVO MOUNT 622-5029-101 1591 REF: AMM 22-10-10	MOS HRS/MSC AFL	O/C	TSN:153 TSR:0 TSN:7723.3 TSN:5496			10-OCT-2009 7723.3 5496		
221011	MOUNT:ROLL SERVO MOUNT 622-5029-101 SN-UNKNOWN REF: AMM 22-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
222001	COMPUTER:MACH TRIM COMPUTER 501-1132-04 2150 REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-MAY-2001 3894.4 2733		
222002	ADAPTER:MACH TRIM ADAPTER 902-1-1 SN-UNKNOWN REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
222003	SENSOR:MACH TRIM POSITION (FOLLOW UP) SENSOR 6608436-2 SN-UNKNOWN REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
225001	INTERFACE BOX:YAW FORCE INTERFACE BOX 6018102-004 197201 REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-JUN-2001 3916.3 2756		
225002	SENSOR:PILOT FORCE SENSOR 6608498-3 SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
225003	SENSOR:COPILOT FORCE SENSOR 6608498-3 SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
CHAPTER 23 COMMUNICATIONS									
231101	TRANSCEIVER:NO. 1 VHF-422A TRANSCEIVER 622-7292-101 3144 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C				26-JAN-2002 4424.3 3125		
231102	TRANSCEIVER:NO. 2 VHF-422A TRANSCEIVER 622-7292-101 2954 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C				26-JAN-2002 4424.3 3125		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
231103	ANTENNA:NO. 1 VHF ANTENNA VF10-347 5873 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
231104	ANTENNA:NO. 2 VHF ANTENNA VF10-347 4192 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-JAN-2000 2499.5 1746		
231192	INSULATOR:HF ANTENNA LEADTHRU INSULATOR 17340 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231201	RECEIVER/EXCITER:NO. 1 HF RECEIVER/EXCITER 064-1015-1 29666 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-OCT-2009 7721.6 5493		
231203	COUPLER:PRIMARY POWER AMPLIFIER/ANTENNA COUPLER 064-1017-01 16362 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-OCT-2009 7721.6 5493		
231205	ANTENNA:HF ANTENNA 5489123-2 SN-UNKNOWN REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231207	CONTROL UNIT:NO. 1 HF CONTROL UNIT 064-1016-03 10761 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C				16-NOV-2001 4217.4 2985		
231208	CONTROL UNIT:NO. 2 HF CONTROL UNIT 064-1016-03 SN-UNKNOWN REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231209	ADAPTER:HF AUDIO ADAPTER 2688178-1 SN-UNKNOWN REF: AMM 23-12-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231210	BOX ASSEMBLY:HF COMMUNICATION FUSE BOX ASSEMBLY 071-0022-00 SN-UNKNOWN REF: AMM 23-12-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231211	BREAKER:(CBR8) HF REMOTE BREAKER 10RC1C-25 SN-UNKNOWN REF: AMM 23-12-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231301	TRANSCEIVER:FLITEFONE TRANSCEIVER 400-125-2000 SN-UNKNOWN REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
231302	ANTENNA:FLITEFONE ANTENNA 121-014378-01 SN-UNKNOWN REF: AMM 23-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231303	CONTROL UNIT:COCKPIT FLITEFONE BASE - CONTROL UNIT 300-2291-013 SN-UNKNOWN REF: AMM 23-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231401	CONTROL PANEL:SELCAL CONTROL PANEL 5489328-8 SN-UNKNOWN REF: AMM 23-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
231402	DECODER:SELCAL DECODER 2800-0012-105 3135006 REF: AMM 23-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-AUG-2008 7649.6 5443		
231403	SONALERT:SELCAL SONALERT SC628P SN-UNKNOWN REF: AMM 23-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
235001	CONTROL PANEL:PILOT AUDIO CONTROL PANEL 802-002 492 REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-AUG-2002 4925.2 3479		
235002	CONTROL PANEL:COPILOT AUDIO CONTROL PANEL 802-002 SN-UNKNOWN REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
237001	RECORDER:COCKPIT VOICE (CVR) RECORDER 1601-01-03 594 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-MAR-1999 1686.2 1162		
237002	AMPLIFIER:CVR REMOTE MICROPHONE AMPLIFIER 1615-01 SN-UNKNOWN REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
237003	MICROPHONE:CVR REMOTE AREA MICROPHONE 16101-02 SN-UNKNOWN REF: AMM 23-70-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
237004	SWITCH:CVR INERTIA SWITCH 3L0-453/8 SN-UNKNOWN REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
237021	BEACON:CVR UNDERWATER LOCATOR (ULB) BEACON DK120 SC58111 REF: AMM 25-63-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-DEC-2008 7720.6 5492		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
237021A	BEACON:CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY - 05-10-29-F2565000	MOS HRS/MSC AFL	24	+14d/-14d			30-DEC-2008 7720.6 5492	30-DEC-2010	13-JAN-2011	419 d
	REF: See Workcard									
237021B	BEACON:REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000	MOS HRS/MSC AFL	DUE				30-DEC-2008 7720.6 5492	30-DEC-2014	M 30-DEC-2014	1880 d
	REF: CMM SECTION VI									
237021D	BEACON:PERFORM CVR UNDERWATER LOCATOR (ULB) BEACON INSPECTION OF THE UNDERWATER LOCATING BEACON (DK100, DK120, DK130, DK140, DUKANE CORPORATION) PERFORM ACOUSTICS CHARACTERISTICS CHECK (REFER TO 25-63-00)	MOS HRS/MSC AFL	216	+14d/-14d			30-DEC-2008 7720.6 5492	30-DEC-2026	13-JAN-2027	6263 d
	REF:									
238001	UNIT:NO. 1 RADIO TUNING (RTU) UNIT 622-9856-142 1825	MOS HRS/MSC AFL	O/C				01-MAR-2006			
	REF: AMM 23-80-01									
238002	UNIT:NO. 2 RADIO TUNING (RTU) UNIT 622-9856-142 1479	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		16-APR-2007 7051.5 5008			
	REF: AMM 23-80-01									
239007	MODULE:NO. 1 SWITCHING MODULE MS1804 0832	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		06-OCT-2009 7721.6 5493			
	REF:									
CHAPTER 24 ELECTRICAL POWER										
+ 05-10-29-B2432010	INSPECT MAIN AIRCRAFT BATTERY INSTALLATION	MOS HRS/MSC AFL	6	+14d/-14d			06-OCT-2009 7721.6 5493	06-APR-2010	20-APR-2010	151 d
	REF: AMM 5-10-29									
+ 05-10-29-H2431017	PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION	MOS HRS/MSC AFL	300	+25/-25			30-DEC-2008 7720.6 5492	8020.6	8045.6	296.4
	REF: AMM 24-31-01									
242001	INVERTER:PRIMARY AC POWER INVERTER 6608483-1 1425	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		23-JUL-1997 15.3 12			
	REF: AMM 24-20-01									
242002	INVERTER:SECONDARY AC POWER INVERTER 501-1666-01 SN-UNKNOWN	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
	REF: AMM 24-20-01									
242003	INDICATOR:POWER MONITOR INDICATOR 11003-003 103544	MOS HRS/MSC AFL	O/C				02-APR-2001 3710.2 2614			
	REF: AMM 24-20-03									

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
242005	BOX:ISOLATION PARALLELING BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242009	TRANSFORMER:NO. 1 GROUND FAULT TRANSFORMER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242010	TRANSFORMER:NO. 2 GROUND FAULT TRANSFORMER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242016	PANEL:GENERATOR CONTROL PANEL 6081042-801 SN-UNKNOWN REF: AMM 24-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-NOV-2001 4217.4 2985		
242031	SENSOR:DC AMMETER SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242032	SENSOR:NO. 1 DC CURRENT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242033	SENSOR:NO. 2 DC CURRENT SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242081	INVERTER:1200 VA, 115 VAC, 60 HZ INVERTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242505	INTERRUPTER:GROUND FAULT INTERRUPTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
242507	SWITCH:60HZ POWER SYSTEM ANEROID SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
243001	STARTER/GENERATOR:NO. 1 STARTER/GENERATOR 400SG138Q 2111XL REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	TSO:0 TSO:0			09-APR-2007 7148.4 5003		OVERHAUL 424.2
243001A	STARTER/GENERATOR:OVERHAUL/REPLACE NO. 1 STARTER/GENERATOR BRUSHES - 05-10-29-D2431025 REF:	MOS HRS/MSC AFL	1000				09-APR-2007 7148.4 5003		424.2

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
243002	STARTER/GENERATOR:NO. 2 STARTER/GENERATOR 400SG138Q 2436XL REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	TSO:0 TSO:0 TSO:0			13-FEB-2008 7428.5 5267	8428.5	OVERHAUL 704.3
243002A	STARTER/GENERATOR:OVERHAUL/REPLACE NO. 2 STARTER/GENERATOR BRUSHES - 05-10-29-D2431025 REF:	MOS HRS/MSC AFL	1000			13-FEB-2008 7428.5 5267	8428.5	704.3	
243005	GENERATOR CONTROL UNIT:LEFT (GCU) GENERATOR CONTROL UNIT GCSG505-16 SN-UNKNOWN REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
243006	GENERATOR CONTROL UNIT:RIGHT (GCU) GENERATOR CONTROL UNIT GCSG505-16 SN-UNKNOWN REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
243007	TRANSFORMER:A11 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
243008	TRANSFORMER:2A11 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
243009	TRANSFORMER:A12 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
243010	TRANSFORMER:2A12 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
243011	CURRENT SENSOR:LEFT DC AMMETER CURRENT SENSOR 256-1 1103 REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0		13-JUL-2001 3989.2 2808			
243012	CURRENT SENSOR:RIGHT DC AMMETER CURRENT SENSOR 256-1 SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0			
243049	BATTERY:UPPER LEAD-ACID (CAPTIVE) BATTERY RG380E/60L 40234988 REF: AMM 24-31-01	MOS HRS/MSC AFL	36 1800	TSN:0 TSN:0 TSN:0		30-DEC-2008 7720.6 5492	30-DEC-2011 9520.6	LIFE LIMIT 784 d 1796.4	
243049A	BATTERY:SERVICE UPPER LEAD-ACID (CAPTIVE) BATTERY SUMP JAR - 05-10-29-G1222002 REF: AMM 12-22-00-G1222002	MOS HRS/MSC AFL	N/A			30-JAN-1997 0 0		N/A EQUIPMENT NOT INSTALLED	

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
243049B	BATTERY:CAPACITY CHECK UPPER LEAD-ACID (CAPTIVE) BATTERY	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
		HRS/MSC	600	+25/-25	7720.6		7720.6	8320.6	8345.6	596.4
	REF: AMM 12-22-00-G1222002A	AFL					5492			
243050	BATTERY:LOWER LEAD-ACID (CAPTIVE) BATTERY	MOS	36				30-DEC-2008	30-DEC-2011		LIFE LIMIT
	RG380E/60L	HRS/MSC	1800				7720.6	9520.6		784 d
	40243710	AFL					5492			1796.4
	REF: AMM 24-31-01									
243050A	BATTERY:SERVICE LOWER LEAD-ACID (CAPTIVE) BATTERY	MOS					30-JAN-1997			N/A EQUIPMENT NOT INSTALLED
	SUMP JAR - 05-10-29-G1222002	HRS/MSC	N/A				0			
	REF: AMM 12-22-00-G1222002	AFL					0			
243050B	BATTERY:CAPACITY CHECK LOWER LEAD-ACID (CAPTIVE) BATTERY	MOS	12	+14d/-14d			30-DEC-2008	30-DEC-2009	13-JAN-2010	54 d
		HRS/MSC	600	+25/-25	7720.6		7720.6	8320.6	8345.6	596.4
	REF: AMM 12-22-00-G1222002A	AFL					5492			
243062	BATTERY:NO. 1 EMERGENCY POWER BATTERY	MOS					06-OCT-2009			
	501-1712-02	HRS/MSC	O/C				7721.6			
	3199	AFL					5493			
	REF: AMM 24-32-01									
+ 243062A	BATTERY:OPERATIONAL CHECK NO. 1 EMERGENCY POWER BATTERY	MOS	6	+14d/-14d			06-OCT-2009	06-APR-2010	20-APR-2010	151 d
	EMERGENCY BATTERY - 05-10-29-F1223010	HRS/MSC					7721.6			
	REF: AMM 24-32-01-F1223010	AFL					5493			
+ 243062B	BATTERY:DISCHARGE CHECK NO. 1 EMERGENCY POWER BATTERY	MOS	12	+14d/-14d			06-OCT-2009	06-OCT-2010	20-OCT-2010	334 d
	EMERGENCY BATTERY - 05-10-29-D1223015	HRS/MSC					7721.6			
	REF:	AFL					5493			
243103	INDICATOR:BATTERY TEMPERATURE INDICATOR	MOS					30-JAN-1997			
	51-4226-A3	HRS/MSC	O/C				0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 24-31-03									
244002	MONITOR:GROUND POWER MONITOR	MOS					30-JAN-1997			
	PN	HRS/MSC	O/C				0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 24-40-02									
245001	PANEL:PILOT CIRCUIT BREAKER PANEL	MOS					30-JAN-1997			
	PN	HRS/MSC	O/C				0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 24-50-01									
245002	PANEL:COPILOT CIRCUIT BREAKER PANEL	MOS					30-JAN-1997			
	PN	HRS/MSC	O/C				0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 24-50-01									
245003	SENSOR:LEFT OVERLOAD (CBR2) SENSOR	MOS					30-JAN-1997			
	PN	HRS/MSC	O/C				0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 24-50-03									

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
245004	SENSOR:RIGHT OVERLOAD (CBR2) SENSOR PN SN-UNKNOWN REF: AMM 24-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
CHAPTER 25 EQUIPMENT/FURNISHINGS									
250000	AMPLIFIER:STEREO/PAGE AMPLIFIER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251001	SEAT:PILOT CREW SEAT PN SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251002	SEAT:COPILOT CREW SEAT PN SN-UNKNOWN REF: AMM 25-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251005	HOLDER:PILOT LIGHTED CHART HOLDER PN SN-UNKNOWN REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251006	HOLDER:COPILOT LIGHTED CHART HOLDER PN SN-UNKNOWN REF: AMM 25-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251023	FOOT WARMER ASSY:LEFT OUTBOARD ELECTRIC FOOT WARMER ASSY PN SN-UNKNOWN REF: AMM 25-10-23	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251024	FOOT WARMER ASSY:LEFT INBOARD ELECTRIC FOOT WARMER ASSY PN SN-UNKNOWN REF: AMM 25-10-23	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251025	FOOT WARMER ASSY:RIGHT INBOARD ELECTRIC FOOT WARMER ASSY PN SN-UNKNOWN REF: AMM 25-10-23	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
251026	FOOT WARMER ASSY:RIGHT OUTBOARD ELECTRIC FOOT WARMER ASSY PN SN-UNKNOWN REF: AMM 25-10-23	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252001	SEAT:LEFT FORWARD PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
252002	SEAT:RIGHT FORWARD PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252003	SEAT:LEFT MID PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252004	SEAT:RIGHT MID PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252005	SEAT:LEFT AFT PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252006	SEAT:RIGHT AFT PASSENGER SEAT PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252007	DIVAN:RIGHT PASSENGER DIVAN PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252025	DIFFUSER:RIGHT LOWER DIFFUSER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
252027	DIFFUSER:LEFT LOWER DIFFUSER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
253007	INVERTER:LEFT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
253009	INVERTER:LEFT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
253010	INVERTER:RIGHT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
253012	INVERTER:RIGHT FORWARD COLD CATHODE LAMP INVERTER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
253052	REGULATOR:VOLTAGE REGULATOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
253068	WARMER-LIQUID:WARMER-LIQUID PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
253069	WARMER-LIQUID:WARMER-LIQUID PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
253090	STEREO:AM/FM/CASSETTE STEREO PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
256001	EMERGENCY LOCATOR TRANSMITTER:ARTEX 406 (ELT) 453-5000-(999) SN-UNKNOWN REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C				30-SEP-2003 5387.2 3870			
+ 256001A	EMERGENCY LOCATOR TRANSMITTER:PERFORM FUNCTIONAL TEST OF THE ELT SYSTEM IAW FAR 91.207(D) (REFER TO 25-62-00) 05-10-29-J2563001 REF: AMM 25-62-00	MOS HRS/MSC AFL	12	+14d/-14d			06-OCT-2009 7721.6 5493	06-OCT-2010	20-OCT-2010	334 d
256001B	EMERGENCY LOCATOR TRANSMITTER:REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY - 05-11-00-L2564000 REF:	MOS HRS/MSC AFL	DUE				09-JUL-2008 7620.3 5421	31-AUG-2013 M		1394 d
256001C	EMERGENCY LOCATOR TRANSMITTER:REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH BATTERY (IF INSTALLED) REF:	MOS HRS/MSC AFL	N/A				30-JAN-1997 0 0			NOT INSTALLED
256001D	EMERGENCY LOCATOR TRANSMITTER:REGISTRATION RENEWAL (ELT) EMERGENCY LOCATOR TRANSMITTER REF: CMM NOAA/SARSAT	MOS HRS/MSC AFL	24				30-JAN-1997 0 0	30-JAN-1999		OVD
256001E	EMERGENCY LOCATOR TRANSMITTER:SELF TEST (ELT) EMERGENCY LOCATOR TRANSMITTER ARTEX 406 ELT REF:	MOS HRS/MSC AFL	1				06-OCT-2009 7721.6 5493	06-NOV-2009		ICA 0 d
256001F	EMERGENCY LOCATOR TRANSMITTER:NDT (ELT) EMERGENCY LOCATOR TRANSMITTER ARTEX 406 ANTANNA & EQUIPMENT STRUCTURAL INSPECTION REF:	MOS HRS/MSC AFL	144				30-SEP-2003 5387.2 3870	30-SEP-2015		ICA 2154 d

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
256001G	EMERGENCY LOCATOR TRANSMITTER:GENERAL VISUAL INSPECTION (ELT) EMERGENCY LOCATOR TRANSMITTER ARTEX 406 ANTANNA & EQUIPMENT	MOS					06-OCT-2009			ICA
	REF:	HRS/MSC	1200				7721.6	8921.6		1197.4
		AFL					5493			
256001H	EMERGENCY LOCATOR TRANSMITTER:INSPECTION (ELT) EMERGENCY LOCATOR TRANSMITTER ARTEX 406 12 MONTH INSPECTION & CHECK FOR NEW ADS	MOS	12				30-SEP-2003	30-SEP-2004		OVD
	REF:	HRS/MSC					5387.2			
		AFL					3870			
256003	CONTROLLER:ELT CONTROLLER	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF:									
256010	INTERFACE:ELT/NAV INTERFACE	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF:									
256060	VISUAL INSPECTION ALL CREW & PAX LIFE VEST	MOS	12				12-JUN-2008	12-JUN-2009		INSPECT OVD
	REF:	HRS/MSC					7661.1			
		AFL					5448			
256061	VEST:NO. 1 LIFE VEST	MOS		TSN:0			12-AUG-2008			
	P01074-20	HRS/MSC	O/C	TSN:0			7661.1			
	239916	AFL		TSN:0			5448			
	REF: AMM 25-61-00									
+ 256061A	VEST:INSPECT NO. 1 LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS					12-AUG-2008	12-AUG-2013		1375 d
	REF: See Workcard	MOS	60				7661.1			
		HRS/MSC					5448			
		AFL								
256062	VEST:NO. 2 LIFE VEST	MOS		TSN:0			12-AUG-2008			
	P01074-20	HRS/MSC	O/C	TSN:0			7661.1			
	239896	AFL		TSN:0			5448			
	REF: AMM 25-61-00									
+ 256062A	VEST:INSPECT NO. 2 LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS					12-AUG-2008	12-AUG-2013		1375 d
	REF: See Workcard	MOS	60				7661.1			
		HRS/MSC					5448			
		AFL								
256063	VEST:NO. 3 LIFE VEST	MOS		TSN:0			12-AUG-2008			
	P01074-20	HRS/MSC	O/C	TSN:0			7661.1			
	239844	AFL		TSN:0			5448			
	REF: AMM 25-61-00									
+ 256063A	VEST:INSPECT NO. 3 LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS					12-AUG-2008	12-AUG-2013		1375 d
	REF: See Workcard	MOS	60				7661.1			
		HRS/MSC					5448			
		AFL								

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
256064	VEST:NO. 4 LIFE VEST P01074-20 239894 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-AUG-2008 7661.1 5448		
+ 256064A	VEST:INSPECT NO. 4 LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	60				12-AUG-2008 7661.1 5448	12-AUG-2013	1375 d
256065	VEST:NO. 5 LIFE VEST P01074-20 239878 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-AUG-2008 7661.1 5448		
256065A	VEST:INSPECT NO. 5 LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	60				12-AUG-2008 7661.1 5448	12-AUG-2013	1375 d
256067	VEST:DIVAN #1 LIFE VEST P01074-20 239884 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-AUG-2008 7661.1 5448		
+ 256067A	VEST:INSPECT DIVAN #1 LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	60				12-AUG-2008 7661.1 5448	12-AUG-2013	1375 d
256068	VEST:DIVAN #2 LIFE VEST P01074-20 239917 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-AUG-2008 7661.1 5448		
+ 256068A	VEST:INSPECT DIVAN #2 LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	60				12-AUG-2008 7661.1 5448	12-AUG-2013	1375 d
256070	VEST:LAVATORY LIFE VEST P01074-20 239912 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-AUG-2008 7661.1 5448		
256070A	VEST:INSPECT LAVATORY LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	60				12-AUG-2008 7661.1 5448	12-AUG-2013	1375 d
256071	VEST:PILOT LIFE VEST P01074-20 239877 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-AUG-2008 7661.1 5448		
+ 256071A	VEST:INSPECT PILOT LIFE VEST REF: See Workcard	PER MANUFACTURER'S INSTRUCTIONS MOS HRS/MSC AFL	60				12-AUG-2008 7661.1 5448	12-AUG-2013	1375 d

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
256072	VEST:COPILOT LIFE VEST P01074-20 239883 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-AUG-2008 7661.1 5448		
+ 256072A	VEST:INSPECT COPILOT LIFE VEST REF: See Workcard	MOS HRS/MSC AFL	60 PER MANUFACTURER'S INSTRUCTIONS				12-AUG-2008 7661.1 5448	12-AUG-2013	1375 d
256076	KIT:FIRST AID KIT AFAK 090905029 REF:	MOS HRS/MSC AFL	O/C				20-OCT-2009 7724.2 5497		
256076A	KIT:CONDITION CHECK FIRST AID KIT REF:	MOS HRS/MSC AFL	12 INVENTORY & EXPIRATION DATES				20-OCT-2009 7724.2 5497	20-OCT-2010	348 d
256076B	KIT:INSPECT FIRST AID KIT REF:	MOS HRS/MSC AFL	12 CONTENTS				20-OCT-2009 7724.2 5497	20-OCT-2010	348 d
256116	SWITCH PANEL:ELT REMOTE SWITCH PANEL 345-6196-04 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-SEP-2003 5387.2 3870		
256202	ANTENNA:ELT ANTENNA 110-337 SN-UNKNOWN REF: AMM 25-62-02	MOS HRS/MSC AFL	O/C				30-SEP-2003 5387.2 3870		
257007	DIVERTER:NOSE COMPARTMENT 5418151-16 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
257101	BLOWER:NOSE AVIONICS EXHAUST BLOWER 718ZH SN-UNKNOWN REF: AMM 25-71-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
258010	DIGITAL INTERFACE UNIT:AIRSHOW DIGITAL INTERFACE UNIT 920040 362 REF:	MOS HRS/MSC AFL	O/C				02-JUN-2009 7720.6 5492		
258011	UNIT:COCKPIT CONTROL - AIRSHOW UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
258012	CONTROLLER:AIRSHOW FLIGHT DECK CONTROLLER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
258014	MONITOR:FORWARD AIRSHOW COLOR MONITOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
258015	MONITOR:AFT AIRSHOW COLOR MONITOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
258016	DISPLAY:FORWARD 10.4 LCD COLOR, AIRSHOW 400 DISPLAY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
258017	DISPLAY:AFT 10.4 LCD COLOR, AIRSHOW 400 DISPLAY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
258020	SWITCH PANEL:AIRSHOW 400 VIDEO SWITCH PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
CHAPTER 26 FIRE PROTECTION									
261001	UNIT:NO. 1 FIRE DETECTION CONTROL UNIT 377-02833 SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
261002	UNIT:NO. 2 FIRE DETECTION CONTROL UNIT 377-02833 SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
261006	CONTROL BOX:TAILCONE BLEED AIR OVERHEAT (E267) CONTROL BOX PN SN-UNKNOWN REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
261007	CONTROL BOX:TAILCONE BLEED AIR OVERHEAT (E268) CONTROL BOX PN SN-UNKNOWN REF: AMM 26-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
261051	VALVE:NO. 1 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
261052	VALVE:NO. 2 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
261207	SENSOR ASSEMBLY:BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY FR2222	MOS		TSN:0			23-JUL-1997			
	437	HRS/MSC	O/C	TSN:0			15.3			
	REF: AMM 26-12-01	AFL		TSN:0			12			
262013	BOTTLE:FORWARD FIRE EXTINGUISHER BOTTLE 32700004-1	MOS		TSN:39			27-MAR-2001			
	AE-36107	HRS/MSC	O/C	TSO:0			3689			
	REF: AMM 26-21-03	AFL		TSO:0			2599			
+ 262013A	BOTTLE:INSPECTION FORWARD FIRE EXTINGUISHER BOTTLE CHECK ENGINE FIRE EXTINGUISHER CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 26-21-00)	MOS	6	+14d/-14d			06-OCT-2009	06-APR-2010	20-APR-2010	151 d
		HRS/MSC					7721.6			
	REF: AMM 26-21-00-P2620042	AFL					5493			
+ 262013C	BOTTLE:HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER BOTTLE	MOS	60	+14d/-14d			17-APR-2006	17-APR-2011	01-MAY-2011	527 d
		HRS/MSC					6598.7			
	REF:	AFL					4701			
262014	BOTTLE:AFT FIRE EXTINGUISHER BOTTLE 32700004-1	MOS		TSO:0			27-MAR-2001			
	AE-35977	HRS/MSC	O/C	TSO:0			3689			
	REF: AMM 26-21-03	AFL		TSN:33 TSO:0			2599			
+ 262014A	BOTTLE:INSPECTION AFT FIRE EXTINGUISHER BOTTLE CHECK ENGINE FIRE EXTINGUISHER CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 26-21-00)	MOS	6	+14d/-14d			06-OCT-2009	06-APR-2010	20-APR-2010	151 d
		HRS/MSC					7721.6			
	REF: AMM 26-21-00-P2620042	AFL					5493			
+ 262014C	BOTTLE:HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE	MOS	60	+14d/-14d			17-APR-2006	17-APR-2011	01-MAY-2011	527 d
		HRS/MSC					6598.7			
	REF:	AFL					4701			
262036	SQUIB:FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB 30903823	MOS	72	TSN:0			30-DEC-2008	30-NOV-2013		LIFE LIMIT
	SN-UNKNOWN	HRS/MSC		TSN:0			7720.6			1485 d
	REF: AMM 26-21-04	AFL		TSN:0			5492			
	Manufacture Date: 30-NOV-2007									
262037	SQUIB:AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB 30903823	MOS	72	TSN:0			30-DEC-2008	30-NOV-2013		LIFE LIMIT
	SN-UNKNOWN	HRS/MSC		TSN:0			7720.6			1485 d
	REF: AMM 26-21-04	AFL		TSN:0			5492			
	Manufacture Date: 30-NOV-2007									
262038	SQUIB:FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB 30903823	MOS	72	TSN:0			30-DEC-2008	30-NOV-2013		LIFE LIMIT
	SN-UNKNOWN	HRS/MSC		TSN:0			7720.6			1485 d
	REF: AMM 26-21-04	AFL		TSN:0			5492			
	Manufacture Date: 30-NOV-2007									

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
262039	SQUIB:AFT ENGINE FIRE EXTINGUISHER AFT SQUIB 30903823 SN-UNKNOWN REF: AMM 26-21-04 Manufacture Date: 30-NOV-2007	MOS HRS/MSC AFL	72	TSN:0 TSN:0 TSN:0			30-DEC-2008 7720.6 5492	30-NOV-2013	LIFE LIMIT	1485 d
262041	FIRE EXTINGUISHER:PILOT PORTABLE FIRE EXTINGUISHER 344 W-470313 REF: AMM 26-20-00	MOS HRS/MSC AFL	O/C	TSN:84 TSN:2668.2 TSN:1915			06-OCT-2009 7721.6 5493			
+ 262041B	FIRE EXTINGUISHER:HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER 5-10-29-R2620030 REF:	MOS HRS/MSC AFL	144				21-OCT-2002	21-OCT-2014		1810 d
262041C	FIRE EXTINGUISHER:INTERNAL VISUAL INSPECTION PILOT PORTABLE FIRE EXTINGUISHER PER MANUFACTURE INSTRUCTIONS REF:	MOS HRS/MSC AFL	72				07-AUG-2009	31-AUG-2015	INSPECT	2124 d
262042	FIRE EXTINGUISHER:COPILOT PORTABLE FIRE EXTINGUISHER 344 W-470312 REF: AMM 26-20-00	MOS HRS/MSC AFL	O/C	TSN:84 TSN:2668.2 TSN:1915			06-OCT-2009 7721.6 5493			
+ 262042B	FIRE EXTINGUISHER:HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030 REF:	MOS HRS/MSC AFL	144				21-OCT-2002	21-OCT-2014		1810 d
262042C	FIRE EXTINGUISHER:INTERNAL VISUAL INSPECTION COPILOT PORTABLE FIRE EXTINGUISHER PER MANUFACTURES INSTRUCTIONS REF:	MOS HRS/MSC AFL	72				07-AUG-2009	31-AUG-2015		2124 d
262045	SWITCH:NO. 1 ENGINE FIRE - PULL SWITCH 865201-3 SN-UNKNOWN REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
262046	SWITCH:NO. 2 ENGINE FIRE - PULL SWITCH 865201-3 SN-UNKNOWN REF: AMM 26-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
262051	EXTINGUISHER:CABIN PORTABLE FIRE EXTINGUISHER A352 W-506831 REF: AMM 26-20-00	MOS HRS/MSC AFL	O/C	TSN:84 TSN:2638.48 TSN:1891			06-OCT-2009 7721.6 5493			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
+ 262051B	EXTINGUISHER:HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER 05-10-29-R2620030	MOS HRS/MSC AFL	144			21-OCT-2002	21-OCT-2014	1810 d	
262051C	EXTINGUISHER:INTERNAL VISUAL INSPECTION CABIN PORTABLE FIRE EXTINGUISHER PER MANUFACTURS INSTRUCTIONS	MOS HRS/MSC AFL	72			06-AUG-2009	31-AUG-2015	2124 d	
E2610020A (s)	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT PKG 1	MOS HRS/MSC AFL	E/C			PKG 16-APR-2005 5981.1 4288	ENGINE CHANGE		
E2610020B (s)	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT PKG 2	MOS HRS/MSC AFL	E/C			PKG 16-SEP-2005 6249.4 4477	ENGINE CHANGE		
CHAPTER 27 FLIGHT CONTROLS									
+ 05-10-29-H2750044L	INSPECT LEFT FLAP CAM FOLLOWER BEARING - DETAILED	MOS HRS/MSC AFL	1200	+25/-25		30-DEC-2008 7720.6 5492	8920.6 8945.6	1196.4	
+ 05-10-29-H2750044R	INSPECT RIGHT FLAP CAM FOLLOWER BEARING - DETAILED	MOS HRS/MSC AFL	1200	+25/-25		30-DEC-2008 7720.6 5492	8920.6 8945.6	1196.4	
05-11-00-E2710010L	REPLACE LEFT AILERON DRIVE YOKE BOLT (NAS1104-38D)	MOS HRS/MSC AFL	3600			17-OCT-2006 6804.7 4841	10404.7	2680.5	
05-11-00-E2710010R	REPLACE RIGHT AILERON DRIVE YOKE BOLT (NAS1104-38D)	MOS HRS/MSC AFL	3600			17-OCT-2006 6804.7 4841	10404.7	2680.5	
05-11-00-E2710013L	REPLACE LEFT AILERON CENTER HINGE BOLT (AN4H12A)	MOS HRS/MSC AFL	3600			06-OCT-2009 7721.6 5493	11321.6	3597.4	
05-11-00-E2710013R	REPLACE RIGHT AILERON CENTER HINGE BOLT (AN4H12A)	MOS HRS/MSC AFL	3600			06-OCT-2009 7721.6 5493	11321.6	3597.4	

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2710020L	REPLACE LEFT AILERON CLEVIS BOLT (NAS464P4)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				7721.6 5493	27721.6		19997.4
05-11-00-E2710020R	REPLACE RIGHT AILERON CLEVIS BOLT (NAS464P4)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				7721.6 5493	27721.6		19997.4
05-11-00-E2710022L	REPLACE LEFT AILERON SECTOR (5425105)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710022R	REPLACE RIGHT AILERON SECTOR (5425105)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710024L	REPLACE LEFT AILERON CLEVIS (2324517)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710024R	REPLACE RIGHT AILERON CLEVIS (2324517)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710026L	REPLACE LEFT AILERON YOKE ASSY (2324511)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710026R	REPLACE RIGHT AILERON YOKE ASSY (2324511)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710028L	REPLACE LEFT AILERON BEARING SUPPORT ASSY (5425016)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710028R	REPLACE RIGHT AILERON BEARING SUPPORT ASSY (5425016)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2710031L	REPLACE LEFT AILERON HINGE BRACKET ASSY (2322530)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2710031R	REPLACE RIGHT AILERON HINGE BRACKET ASSY (2322530)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2720020	REPLACE RUDDER HINGE BOLTS (NAS6205 & NAS464P5)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2720022	REPLACE RUDDER SECTOR BEARING ASSY (5435052)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2720026	REPLACE RUDDER HINGE BRACKETS (5431005 & 5431056)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2730021L	REPLACE LEFT ELEVATOR BELLCRANKS (2331511)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2730021R	REPLACE RIGHT ELEVATOR BELLCRANKS (2331511)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2730022L	REPLACE LEFT ELEVATOR UPPER PUSH-PULL TUBES (5435013)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2730022R	REPLACE RIGHT ELEVATOR UPPER PUSH-PULL TUBES (5435013)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2730024L	REPLACE LEFT ELEVATOR HINGE BOLTS (AN4H11A)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2730024R	REPLACE RIGHT ELEVATOR HINGE BOLTS (AN4H11A)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2740010	REPLACE HORZ STAB HINGE PIN (2331028)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E2750002L	REPLACE LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	MOS					30-DEC-2008			
	REF:	HRS/MSC AFL	1200	+25/-25			7720.6 5492	8920.6	8945.6	1196.4
05-11-00-E2750002R	REPLACE RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	MOS					30-DEC-2008			
	REF:	HRS/MSC AFL	1200	+25/-25			7720.6 5492	8920.6	8945.6	1196.4
05-11-00-E2750035L	REPLACE LEFT FLAP SECTOR (2625031)	MOS					06-OCT-2009			
	REF:	HRS/MSC AFL	6000	+25/-25			7721.6 5493	11493	11518	5996
05-11-00-E2760059L	REPLACE LEFT SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14)	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4217.2 2985	8717.2		993
05-11-00-E2760059R	REPLACE RIGHT SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14)	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4217.2 2985	8717.2		993
05-11-00-E2760061L	REPLACE LEFT SPOILER ACTUATOR ARM (2422511)	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4217.4 2985	8717.4		993.2
05-11-00-E2760061R	REPLACE RIGHT SPOILER ACTUATOR ARM (2422511)	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4217.4 2985	8717.4		993.2
05-11-00-E2760062L	SPOILER:REPLACE LEFT ASSEMBLY SPOILER SPOILER ACTUATOR BOLT (NAS464P4)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				7721.6 5493	12221.6		4497.4

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2760062R	SPOILER:REPLACE RIGHT ASSEMBLY SPOILER	SPOILER	ACTUATOR BOLT (NAS464P4)							LIFE LIMIT
		MOS					06-OCT-2009			
	REF:	HRS/MSC	4500				7721.6	12221.6		4497.4
		AFL					5493			
05-11-00-E2760063L	SPOILER:REPLACE LEFT ASSEMBLY SPOILER	SPOILER	CENTER PIVOT BOLT (NAS464P5)							LIFE LIMIT
		MOS					06-OCT-2009			
	REF:	HRS/MSC	4500				7721.6	12221.6		4497.4
		AFL					5493			
05-11-00-E2760063R	SPOILER:REPLACE RIGHT ASSEMBLY SPOILER	SPOILER	CENTER PIVOT BOLT (NAS464P5)							LIFE LIMIT
		MOS					06-OCT-2009			
	REF:	HRS/MSC	4500				7721.6	12221.6		4497.4
		AFL					5493			
05-11-00-E2760064LI	SPOILER:REPLACE LEFT ASSEMBLY SPOILER	SPOILER	HINGE BOLT (AN4-13)							LIFE LIMIT
		MOS					06-OCT-2009			
	REF:	HRS/MSC	4500				7721.6	12221.6		4497.4
		AFL					5493			
05-11-00-E2760064LO	SPOILER:REPLACE LEFT ASSEMBLY SPOILER	SPOILER	HINGE BOLT (AN4-13)							LIFE LIMIT
		MOS					06-OCT-2009			
	REF:	HRS/MSC	4500				7721.6	12221.6		4497.4
		AFL					5493			
05-11-00-E2760064RI	SPOILER:REPLACE RIGHT ASSEMBLY SPOILER	SPOILER	HINGE BOLT (AN4-13)							LIFE LIMIT
		MOS					06-OCT-2009			
	REF:	HRS/MSC	4500				7721.6	12221.6		4497.4
		AFL					5493			
05-11-00-E2760064RO	SPOILER:REPLACE RIGHT ASSEMBLY SPOILER	SPOILER	HINGE BOLT (AN4-13)							LIFE LIMIT
		MOS					06-OCT-2009			
	REF:	HRS/MSC	4500				7721.6	12221.6		4497.4
		AFL					5493			
05-11-00-F2730030	REPLACE PRIMARY ELEVATOR CONTROL SYSTEM CABLES									LIFE LIMIT
		MOS					17-APR-2006			
	REF:	HRS/MSC	2400				6598.7	8998.7		1274.5
		AFL					4701			
05-11-00-G2740011	REPLACE HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6)									LIFE LIMIT
		MOS	144				06-OCT-2009	06-OCT-2021		4352 d
	REF:	HRS/MSC					7721.6			
		AFL	6000				5493	11493		5996
05-11-00-G2750034L	REPLACE LEFT WING FLAP SECTOR MOUNTING BOLT									
		MOS	144	+14d/-14d			06-OCT-2009	30-JAN-2021	13-FEB-2021	4103 d
	REF:	HRS/MSC					7721.6			
		AFL	6000	+25/-25			5493	11493	11518	5996

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-G2750034R	REPLACE RIGHT WING FLAP SECTOR MOUNTING BOLT	MOS	144	+14d/-14d	-249		06-OCT-2009	30-JAN-2021	13-FEB-2021	4103 d
	REF:	HRS/MSC					7721.6			
		AFL	6000	+25/-25			5493	11493	11518	5996
05-11-00-L2750027LI	REPLACE LEFT INBOARD FLAP TRACK ASSY (6022515)	MOS					16-NOV-2001			LIFE LIMIT
	REF:	HRS/MSC					4217.5			
		AFL	20000				2985	22985		17488
05-11-00-L2750027LO	REPLACE LEFT OUTBOARD FLAP TRACK ASSY (6022515)	MOS					16-NOV-2001			LIFE LIMIT
	REF:	HRS/MSC					4217.5			
		AFL	20000				2985	22985		17488
05-11-00-L2750027RI	REPLACE RIGHT INBOARD FLAP TRACK ASSY (6022515)	MOS					16-NOV-2001			LIFE LIMIT
	REF:	HRS/MSC					4217.5			
		AFL	20000				2985	22985		17488
05-11-00-L2750027RO	REPLACE RIGHT OUTBOARD FLAP TRACK ASSY (6022515)	MOS					16-NOV-2001			LIFE LIMIT
	REF:	HRS/MSC					4217.5			
		AFL	20000				2985	22985		17488
05-11-00-L2750033L	REPLACE LEFT LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516)	MOS					30-JAN-1997			LIFE LIMIT
	REF:	HRS/MSC					0			
		AFL	10000				0	10000		4503
05-11-00-L2750033R	REPLACE RIGHT LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516)	MOS					30-JAN-1997			LIFE LIMIT
	REF:	HRS/MSC					0			
		AFL	10000				0	10000		4503
05-11-00-M2710021LI	REPLACE LEFT INBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					06-OCT-2009			LIFE LIMIT
	REF:	HRS/MSC	20000				7721.6	27721.6		19997.4
		AFL					5493			
05-11-00-M2710021LO	REPLACE LEFT OUTBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					06-OCT-2009			LIFE LIMIT
	REF:	HRS/MSC	20000				7721.6	27721.6		19997.4
		AFL					5493			
05-11-00-M2710021RI	REPLACE RIGHT INBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					06-OCT-2009			LIFE LIMIT
	REF:	HRS/MSC	20000				7721.6	27721.6		19997.4
		AFL					5493			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-M2710021RO	REPLACE RIGHT OUTBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				7721.6 5493	27721.6		19997.4
05-11-00-M2730031	REPLACE HINGE ASSEMBLIES (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD)(LOCATED ON HORIZONTAL STABILIZER ASSEMBLY)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-M2750049LI	REPLACE LEFT INBOARD FLAP SUPPORT FITTING	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4217.5 2985	22985		17488
05-11-00-M2750049LO	REPLACE LEFT OUTBOARD FLAP SUPPORT FITTING	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4217.5 2985	22985		17488
05-11-00-M2750049RI	REPLACE RIGHT INBOARD FLAP SUPPORT FITTING	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4217.5 2985	22985		17488
05-11-00-M2750049RO	REPLACE RIGHT OUTBOARD FLAP SUPPORT FITTING	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4217.5 2985	22985		17488
05-11-00-N2750025	REPLACE INBOARD FLAP TRACK HINGE FITTING (ON FLAP) (2625023)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				7721.6 5493	11493		5996
05-11-00-N2750026	REPLACE OUTBOARD FLAP TRACK HINGE FITTING (ON FLAP) (2625024)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				7721.6 5493	11493		5996
05-11-00-N2750051	REPLACE INBOARD FLAP HINGE FITTING (6025022)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		14503
05-11-00-N2750052	REPLACE OUTBOARD FLAP HINGE FITTING (6025021)	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		14503

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-R2760079L	REPLACE LEFT SPOILER ACTUATOR ATTACH FITTING AND BOLT	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	10000				0 0	10000		2275.8
05-11-00-R2760079R	REPLACE RIGHT SPOILER ACTUATOR ATTACH FITTING AND BOLT	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	10000				0 0	10000		2275.8
270505	PANEL ASSY:TRIM SWITCH PANEL ASSY 6018201-1	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-00-01	AFL		TSN:0			0			
271013	TAB ASSEMBLY:AILERON TRIM TAB ASSEMBLY 2324028-116	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-10-04	AFL		TSN:0			0			
271015	TAB ASSEMBLY:LEFT AILERON BALANCE TAB ASSEMBLY 2324028-83	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-10-03	AFL		TSN:0			0			
271016	TAB ASSEMBLY:RIGHT AILERON BALANCE TAB ASSEMBLY 2324028-84	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-10-03	AFL		TSN:0			0			
271019	ACTUATOR:AILERON TRIM ACTUATOR 6600156-13	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-10-11	AFL		TSN:0			0			
271025	WHEEL:PILOT CONTROL WHEEL 2415151-13	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-10-01	AFL		TSN:0			0			
271026	WHEEL:COPILOT CONTROL WHEEL 2415151-14	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-10-01	AFL		TSN:0			0			
271027	COLUMN:PILOT CONTROL COLUMN PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 27-30-06	AFL		TSN:0			0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
271028	COLUMN:COPILOT CONTROL COLUMN PN SN-UNKNOWN REF: AMM 27-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
271031	POTENTIOMETER:AILERON TRIM TAB ACTUATOR POTENTIOMETER 53C3-1000S SN-UNKNOWN REF: AMM 27-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
271126	INDICATOR:AILERON TRIM POSITION INDICATOR 6608217-21 099 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12			
271131	SENSOR:LEFT AILERON POSITION SENSOR PN SN-UNKNOWN REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
271132	SENSOR:RIGHT AILERON POSITION SENSOR 501-1123-02 SN-UNKNOWN REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
271701	AILERON:LEFT AILERON 2424000-243 SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0	20000		12275.8
271702	AILERON:RIGHT AILERON 2424000-242 SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0	20000		12275.8
272001	RUDDER:RUDDER 5433000-16 SN-UNKNOWN REF: AMM 27-20-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0	20000		12275.8
272005	SECTOR:AFT RUDDER SECTOR 5435051-13 SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
272007	TAB:RUDDER TRIM TAB 5433300-29 SN-UNKNOWN REF: AMM 27-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
272013	ACTUATOR:RUDDER TRIM TAB ACTUATOR 6600156-10 SN-UNKNOWN REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
272020	POTENTIOMETER:RUDDER TRIM TAB POTENTIOMETER JA1D056S102UA(1K) SN-UNKNOWN REF: AMM 27-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
272026	INDICATOR:RUDDER TRIM INDICATOR 6608217-20 SN-UNKNOWN REF: AMM 27-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
272031	ACTUATOR:PILOT RUDDER PEDAL ACTUATOR PN SN-UNKNOWN REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
272032	ACTUATOR:COPILOT RUDDER PEDAL ACTUATOR PN SN-UNKNOWN REF: AMM 27-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
273001	ELEVATOR:LEFT ELEVATOR 2434000-151 SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0	20000	LIFE LIMIT 12275.8
273002	ELEVATOR:RIGHT ELEVATOR 2434000-152 SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0	20000	LIFE LIMIT 12275.8
273013	COMPUTER:STALL WARNING COMPUTER 54301-3L SN-UNKNOWN REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
273017	SHAKER:PILOT STICK SHAKER 6608289-3 SN-UNKNOWN REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
273018	SHAKER:COPILOT STICK SHAKER 6608289-3 SN-UNKNOWN REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
273101	TRANSDUCER:PILOT STALL WARNING TRANSDUCER 25147A-12 GST0433D REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JAN-2004 5452.7			
273102	TRANSDUCER:COPILOT STALL WARNING TRANSDUCER 25147A-12 GST03893 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-NOV-2001 4239.2 2998			
273105	INDICATOR:PILOT ANGLE-OF-ATTACK (AOA) INDICATOR 25147A-12 GST02029 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			22-MAY-1999 1912 1323			
273106	INDICATOR:COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR 6608515-2 SN-UNKNOWN REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
273110	VANE:ANGLE-OF-ATTACK (AOA) VANE 3065227 SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
274001	HORIZONTAL STABILIZER:HORIZONTAL STABILIZER 2332000-61 SN-UNKNOWN REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
274003	CONTROLLER:HORIZONTAL STABILIZER ACTUATOR CONTROLLER 6608444-2 123A REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-SEP-2000 3241.5 2279			
274010	DETECTOR:TRIM-IN-MOTION DETECTOR 6608446-2 SN-UNKNOWN REF: AMM 27-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
274013	ACTUATOR:HORIZONTAL STABILIZER ACTUATOR 5435005-028 005 REF: AMM 27-40-02	MOS HRS/MSC AFL	600	TSO:0 TSO:0 TSO:0			30-DEC-2008 7720.6 5492	8320.6		596.4
274062	INDICATOR:PITCH TRIM INDICATOR 6608514-1 SN-UNKNOWN REF: AMM 27-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
274070	SWITCH:STABILIZER POSITION SWITCH PN SN-UNKNOWN REF: AMM 27-40-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
274072	SENSOR:STABILIZER POSITION SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275001	FLAP ASSEMBLY:LEFT FLAP ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	10000	TSR:0 TSR:0 TSN:2357			01-NOV-2000 3338.7 2357	10000		4503
275002	FLAP ASSEMBLY:RIGHT FLAP ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	10000	TSR:0 TSR:0 TSN:2357			01-NOV-2000 3338.7 2357	10000		4503
275010	BOX ASSY:FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSY 6018336-3 509866 (E) REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-AUG-2002 4925.2 3479			
275012	POTENTIOMETER:FLAP POSITION POTENTIOMETER RV4SAYSD102A SN-UNKNOWN REF: AMM 27-50-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-FEB-2007 7006.4 4977			
275015	SENSOR:LEFT RUDDER POSITION SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275016	SENSOR:RIGHT RUDDER POSITION SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275019	SWITCH:LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH 2625045-23 92814 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-AUG-2000 3134.1 2203			
275020	SWITCH:RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH 2625045-32 SN-UNKNOWN REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
275021	SWITCH:LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275022	SWITCH:RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275031	VALVE:FLAP CONTROL (FLAP/SPOILER) VALVE 6600362-1 632 REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			01-DEC-1999 2399 1671			
275036	VALVE:FLAP RESTRICTOR VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275037	ACTUATOR:LEFT FLAP ACTUATOR 6600493-1 SN-UNKNOWN REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275038	ACTUATOR:RIGHT FLAP ACTUATOR 6600493-1 SN-UNKNOWN REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275200	INDICATOR:FLAP POSITION INDICATOR 6608475-004 072 REF: AMM 27-50-10	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-SEP-1999 2225 1567			
275213	RELIEF VALVE:FLAP PRESSURE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
275217	CHECK VALVE:FLAP ACTUATION CHECK VALVE AN6207-4 SN-UNKNOWN REF: AMM 27-50-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
276001	SPOILER:LEFT ASSEMBLY SPOILER 2422510-137 W1574S REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	TSN:95 TSN:3504.4 TSN:2508			06-OCT-2009 7721.6 5493		LIFE LIMIT 8717.2	993

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
276002	SPOILER:RIGHT ASSEMBLY SPOILER 2422510-136 W1548S REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	TSN:95 TSN:3504.4 TSN:2508			06-OCT-2009 7721.6 5493	8717.2	LIFE LIMIT	993
276005	SERVO VALVE:LEFT SPOILER FLOW CONTROL SERVO VALVE PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
276006	SERVO VALVE:RIGHT SPOILER FLOW CONTROL SERVO VALVE PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
276010	COMPUTER:SPOILER COMPUTER 501-1133-11 1406 REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			19-AUG-2008 7662.5 5453			
276013	ACTUATOR:LEFT SPOILER ACTUATOR 2417015-5 1317 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	TSR:0 TSN:7722.1 TSR:0			07-OCT-2009 7722.1 5494	10000	LIFE LIMIT	2275.8
276014	ACTUATOR:RIGHT SPOILER ACTUATOR 2417015-5 1318 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	TSN:153 TSN:7722.1 TSN:5494			07-OCT-2009 7722.1 5494	10000	LIFE LIMIT	2275.8
276037	SENSOR:LEFT SPOILER POSITION SENSOR 501-1123-02 SN-UNKNOWN REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
276038	SENSOR:RIGHT SPOILER POSITION SENSOR 501-1123-02 SN-UNKNOWN REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
276043	POTENTIOMETER:SPOILER POTENTIOMETER 3585-S-1-103 SN-UNKNOWN REF: AMM 27-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
276049	INDICATOR:SPOILER POSITION INDICATOR 6608476-3 150 REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-2000 2706.4 1884			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
276128	VALVE:SPOILER MANIFOLD VALVE PN SN-UNKNOWN REF: AMM 27-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
276265	BOX:WHEEL SPEED DETECTION BOX PN SN-UNKNOWN REF: AMM 27-60-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
F2710036	REPLACE PRIMARY AILERON CONTROL CABLES REF:	MOS HRS/MSC AFL	2400				17-APR-2006 6598.7 4701	LIFE LIMIT 8998.7	1274.5
F2720029	REPLACE PRIMARY RUDDER CONTROL CABLES REF:	MOS HRS/MSC AFL	2400	+25/-25			17-APR-2006 6598.7 4701	LIFE LIMIT 8998.7	9023.7 1274.5
L2750028	REPLACE INBOARD NOSE ROLLER TRACK (2322511) REF:	MOS HRS/MSC AFL	20000				30-JAN-1997 0 0	LIFE LIMIT 20000	14503
L2750029	REPLACE OUTBOARD NOSE ROLLER TRACK (2322512) REF:	MOS HRS/MSC AFL	20000				30-JAN-1997 0 0	LIFE LIMIT 20000	14503
N2750032	REPLACE UPPER FLAP SECTOR BRACKET ASSEMBLY (6022511-1, -2, -801, AND -802) REF:	MOS HRS/MSC AFL	3000				16-NOV-2001 4217.4 2985	LIFE LIMIT 5985	488
CHAPTER 28 FUEL									
05-10-29-F2820012	CLEAN/CHECK LOW PRESSURE FUEL FILTERS REF:	MOS HRS/MSC AFL	-				13-FEB-2008 7428.5 5267		
+ 05-10-29-L2812002L	INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602 REF:	MOS HRS/MSC AFL	24	+14d/-14d			13-FEB-2008 7428.5 5267	13-FEB-2010	27-FEB-2010 99 d
+ 05-10-29-L2812002R	INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602 REF:	MOS HRS/MSC AFL	24	+14d/-14d			13-FEB-2008 7428.5 5267	13-FEB-2010	27-FEB-2010 99 d

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
+ 05-10-29-L2812010L	INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA	MOS	24	+14d/-14d			13-FEB-2008	13-FEB-2010	27-FEB-2010	99 d
	REF:	HRS/MSC AFL					7428.5 5267			
+ 05-10-29-L2812010R	INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA	MOS	24	+14d/-14d			13-FEB-2008	13-FEB-2010	27-FEB-2010	99 d
	REF:	HRS/MSC AFL					7428.5 5267			
+ 05-10-29-L2812020L	INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION	MOS	24	+14d/-14d			13-FEB-2008	13-FEB-2010	27-FEB-2010	99 d
	REF:	HRS/MSC AFL					7428.5 5267			
+ 05-10-29-L2812020R	INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION	MOS	24	+14d/-14d			13-FEB-2008	13-FEB-2010	27-FEB-2010	99 d
	REF:	HRS/MSC AFL					7428.5 5267			
05-11-00-G2820003	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AICRAFT (PRESSURE)	MOS								
	REF:	HRS/MSC AFL	O/C				-249 06-OCT-2009 7721.6 5493			
280002	PANEL ASEMBLY:FUEL CONTROL SWITCH PANEL ASEMBLY	MOS								
	PN	MOS								TSN:0
	SN-UNKNOWN	HRS/MSC	O/C							0
	REF: AMM 28-00-02	AFL								0
280003	VALVE:LEFT WING DEFUEL VALVE	MOS								
	PN	MOS								TSN:0
	SN-UNKNOWN	HRS/MSC	O/C							0
	REF: AMM 28-00-03	AFL								0
280004	VALVE:RIGHT WING DEFUEL VALVE	MOS								
	PN	MOS								TSN:0
	SN-UNKNOWN	HRS/MSC	O/C							0
	REF: AMM 28-00-03	AFL								0
281007	VALVE:LEFT CHECK, CROSSFLOW VALVE	MOS								
	PN	MOS								TSN:0
	SN-UNKNOWN	HRS/MSC	O/C							0
	REF:	AFL								0
281008	VALVE:RIGHT CHECK, CROSSFLOW VALVE	MOS								
	PN	MOS								TSN:0
	SN-UNKNOWN	HRS/MSC	O/C							0
	REF:	AFL								0

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
281201	FUEL CELL:AFT FUSELAGE FUEL CELL 6600501-003 1 REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-OCT-2009 7721.6 5493		
281202	FUEL CELL:FORWARD FUSELAGE FUEL CELL 6600500-005 004 REF: AMM 28-12-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-OCT-2009 7721.6 5493		
281283	VALVE:FUSELAGE DRAIN VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281301	FLOAT VALVE:LEFT WING FUEL VENT FLOAT VALVE PN SN-UNKNOWN REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281302	FLOAT VALVE:RIGHT WING FUEL VENT FLOAT VALVE PN SN-UNKNOWN REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281303	FLOAT VALVE:FUSELAGE FUEL VENT FLOAT VALVE PN SN-UNKNOWN REF: AMM 28-13-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281305	ARRESTOR:LEFT WING FLAME ARRESTOR PN SN-UNKNOWN REF: AMM 28-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281306	ARRESTOR:RIGHT WING FLAME ARRESTOR PN SN-UNKNOWN REF: AMM 28-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281307	RELIEF VALVE:LEFT FUEL CELL PRESSURE RELIEF VALVE RV62-2 07-0130234 REF: AMM 28-13-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
281308	RELIEF VALVE:RIGHT FUEL CELL PRESSURE RELIEF VALVE RV62-2 07-0130235 REF: AMM 28-13-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
281309	ARRESTOR:FUSELAGE FLAME ARRESTOR PN SN-UNKNOWN REF: AMM 28-13-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281401	PUMP:LEFT FUSELAGE CELL TRANSFER PUMP 2380060-050 C-320 REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			07-JAN-2007 6954.2 4936		
281402	PUMP:RIGHT FUSELAGE CELL TRANSFER PUMP 2380060-43 SN-UNKNOWN REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281403	JET PUMP:LEFT INBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281404	JET PUMP:RIGHT INBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281405	JET PUMP:LEFT CENTER WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281406	JET PUMP:RIGHT CENTER WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281407	JET PUMP:LEFT OUTBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281408	JET PUMP:RIGHT OUTBOARD WING SCAVENGE JET PUMP PN SN-UNKNOWN REF: AMM 28-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281409	PUMP:LEFT SCAVENGE PUMP 2380060-42 SN-UNKNOWN REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
281410	PUMP:RIGHT SCAVENGE PUMP 2380060-42 SN-UNKNOWN REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281411	VALVE:LEFT FUEL TRANSFER VALVE 6600355-2 SN-UNKNOWN REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281412	VALVE:RIGHT FUEL TRANSFER VALVE 6600355-2 SN-UNKNOWN REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281413	VALVE:CROSSFLOW VALVE 6600355-2 SN-UNKNOWN REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281414	FLOAT SWITCH:FUSELAGE HIGH-LEVEL FLOAT SWITCH L14F-47 SN-UNKNOWN REF: AMM 28-14-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281415	SWITCH:LEFT FUEL TRANSFER PRESSURE INDICATING SWITCH PN SN-UNKNOWN REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281416	SWITCH:RIGHT FUEL TRANSFER PRESSURE INDICATING SWITCH PN SN-UNKNOWN REF: AMM 28-14-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281417	FLOAT SWITCH:LEFT WING HIGH-LEVEL FLOAT SWITCH PN SN-UNKNOWN REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281418	FLOAT SWITCH:RIGHT WING HIGH-LEVEL FLOAT SWITCH PN SN-UNKNOWN REF: AMM 28-14-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281419	FLOAT SWITCH:LEFT WING LOW-LEVEL FLOAT SWITCH PN SN-UNKNOWN REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
281420	FLOAT SWITCH:RIGHT WING LOW-LEVEL FLOAT SWITCH PN SN-UNKNOWN REF: AMM 28-14-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
281421	BOX:FUEL FILL AND TRANSFER BOX 6018255-3 SN-UNKNOWN REF: AMM 28-14-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282001	JET PUMP:LEFT INBOARD JET PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282002	JET PUMP:RIGHT INBOARD JET PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282003	PUMP:LEFT STANDBY PUMP 2380060-48 SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282004	PUMP:RIGHT STANDBY PUMP 2380060-48 SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282005	FILTER ASSEMBLY:LEFT FUEL FILTER ASSEMBLY PN SN-UNKNOWN REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282006	FILTER ASSEMBLY:RIGHT FUEL FILTER ASSEMBLY PN SN-UNKNOWN REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282007	SHUTOFF VALVE:LEFT ENGINE FUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282008	SHUTOFF VALVE:RIGHT ENGINE FUEL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
282009	SHUTOFF VALVE:LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE 6600354-3 706134 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12		
282010	SHUTOFF VALVE:RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE 6600354-4 80722146 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			09-JAN-2000 2482.6 1734		
282011	RELIEF VALVE:LEFT ENGINE RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282012	RELIEF VALVE:RIGHT ENGINE RELIEF VALVE PN SN-UNKNOWN REF: AMM 28-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282013	RELAY PANEL:FUEL CONTROL RELAY PANEL PN SN-UNKNOWN REF: AMM 28-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282015	VALVE:LEFT WING PILOT VALVE PN SN-UNKNOWN REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282016	VALVE:RIGHT WING PILOT VALVE PN SN-UNKNOWN REF: AMM 28-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282017	SHUTOFF VALVE:LEFT WING REFUELING SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282018	SHUTOFF VALVE:RIGHT WING REFUELING SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282019	VALVE:FUSELAGE PILOT VALVE 2780610-102 SN-UNKNOWN REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
282020	VENT VALVE:FUSELAGE VENT VALVE 2780610-102 SN-UNKNOWN REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282021	CHECK VALVE:REFUELING CHECK VALVE 2780623-101 SN-UNKNOWN REF: AMM 28-20-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282022	SHUTOFF VALVE:REFUELING SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282023	VALVE:FUEL SOLENOID VALVE 2780613-101 SN-UNKNOWN REF: AMM 28-20-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282024	ADAPTER:PRESSURE REFUELING ADAPTER PN SN-UNKNOWN REF: AMM 28-20-16	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282025	VALVE:LEFT PRECHECK VALVE PN SN-UNKNOWN REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282026	VALVE:RIGHT PRECHECK VALVE PN SN-UNKNOWN REF: AMM 28-20-17	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
282027	CONTROL PANEL:PRESSURE REFUELING CONTROL PANEL PN SN-UNKNOWN REF: AMM 28-20-18	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284001	FUEL PROBE:LEFT INBOARD WING (MT5) FUEL PROBE 2326014-11 SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284002	FUEL PROBE:RIGHT INBOARD WING (MT6) FUEL PROBE 2326014-12 SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
284003	FUEL PROBE:LEFT OUTBOARD WING (MT7) FUEL PROBE PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284004	FUEL PROBE:RIGHT OUTBOARD WING (MT8) FUEL PROBE PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284005	FUEL PROBE:LEFT INBOARD WING EXTENSION STA 189 (MT9) FUEL PROBE PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284006	FUEL PROBE:RIGHT INBOARD WING EXTENSION STA 189 (MT10) FUEL PROBE PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284007	FUEL PROBE:LEFT OUTBOARD WING EXTENSION STA 244 (MT11) FUEL PROBE PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284008	FUEL PROBE:RIGHT OUTBOARD WING EXTENSION STA 244 (MT12) FUEL PROBE PN SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284009	FUEL PROBE:FUSELAGE (MT18) FUEL PROBE 0118KTU01 SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284011	PRESSURE SWITCH:LEFT ENGINE LOW FUEL PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284012	PRESSURE SWITCH:RIGHT ENGINE LOW FUEL PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 28-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
284013	INDICATOR:FUEL QUANTITY INDICATOR PN SN-UNKNOWN REF: AMM 28-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

CHAPTER 29 HYDRAULIC POWER

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES(EXCLUDING HOSES FOR THE LANDING GEAR AND THE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)	MOS			-249		06-OCT-2009		
	REF:	HRS/MSC AFL	O/C				7721.6 5493		
05-11-00-L2910020	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS	MOS					06-NOV-2001		
	REF: AMM 29-10-03-L2910020	HRS/MSC AFL	O/C				4217.4 2985		
290002	PRESSURE REGULATOR:HYDRAULIC PRESSURE REGULATOR 859A-4BT	MOS		TSN:0			06-NOV-2006		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			6847.5		
	REF: AMM 29-00-02	AFL		TSN:0			4870		
290003	RESERVOIR:HYDRAULIC RESERVOIR 5417007-30	MOS		TSN:0			30-JAN-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-00-03	AFL		TSN:0			0		
290005	CHECK VALVE:PRESSURE REGULATOR CHECK VALVE 496-402-1/4	MOS		TSN:0			16-NOV-2001		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			4217.4		
	REF: AMM 29-00-05	AFL		TSN:0			2985		
291001	SHUTOFF VALVE:LEFT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE PN	MOS		TSN:0			30-JAN-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-01	AFL		TSN:0			0		
291002	SHUTOFF VALVE:RIGHT ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE PN	MOS		TSN:0			30-JAN-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-01	AFL		TSN:0			0		
291003	PUMP:LEFT ENGINE DRIVEN HYDRAULIC PUMP PN	MOS		TSN:0			30-JAN-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-02	AFL		TSN:0			0		
291004	PUMP:RIGHT ENGINE DRIVEN HYDRAULIC PUMP PN	MOS		TSN:0			30-JAN-1997		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 29-10-02	AFL		TSN:0			0		
291005	FILTER ASSEMBLY:HYDRAULIC PRESSURE FILTER ASSEMBLY M8815/3-10	MOS		TSN:0			24-MAR-2004		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			5453.3		
	REF: AMM 29-10-03	AFL		TSN:0			3927		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
291006	FILTER ASSEMBLY:HYDRAULIC RETURN FILTER ASSEMBLY M8815/3-10 SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-MAR-2004 5453.3 3927		
291007	ACCUMULATOR:HYDRAULIC SYSTEM ACCUMULATOR 2617049-1 SN-UNKNOWN REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
291008	ACCUMULATOR:HYDRAULIC THRUST REVERSER ACCUMULATOR PN SN-UNKNOWN REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
291010	PANEL:HYDRAULIC GROUND SERVICE PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
291015	VENT VALVE:HYDRAULIC RELIEF VENT VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
291020	RELIEF VALVE:HYDRAULIC RESERVOIR RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
291220	ISOLATION VALVE:THRUST REVERSER ISOLATION VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
291225	RELIEF VALVE:HYDRAULIC PRESSURE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
292001	PUMP:AUXILIARY HYDRAULIC PUMP MP-500 SN-UNKNOWN REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
293001	TRANSDUCER:HYDRAULIC PRESSURE MT15 TRANSDUCER 123091-1 SN-UNKNOWN REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
293002	PRESSURE SWITCH:AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH 730626 F1025 REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-JUN-2000 2910.4 2041			
293003	INDICATOR:HYDRAULIC PRESSURE INDICATOR 6608401-13 SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
293005	PRESSURE SWITCH:LEFT HYDRAULIC PUMP PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
293006	PRESSURE SWITCH:RIGHT HYDRAULIC PUMP PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
293010	PRESSURE GAUGE:HYDRAULIC SYSTEM PRESSURE GAUGE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
293015	PRESSURE GAUGE:THRUST REVERSER HYDRAULIC PRESSURE GAUGE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
CHAPTER 30 ICE AND RAIN PROTECTION										
300001	BOX:COPILOT ELECTRICAL EQUIPMENT BOX 6018294-005 MRP340147-01 REF: AMM 30-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-APR-2002 4662.1 3275			
301001	VALVE:WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE 6600259-3 GWD32164 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-OCT-2009 7723.3 5496			
301002	SENSOR:WING RT10 ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301003	SENSOR:WING (SPARE 2RT10) ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
301004	SENSOR:WING (SPARE 3RT10) ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301005	THERMOSWITCH:WING OVERHEAT WARNING THERMOSWITCH 6600141-1 SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301006	INDICATOR:WING TEMPERATURE INDICATOR PN SN-UNKNOWN REF: AMM 30-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301007	BYPASS VALVE:LEFT WING ANTI-ICE BYPASS VALVE PN SN-UNKNOWN REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301008	BYPASS VALVE:RIGHT WING ANTI-ICE BYPASS VALVE PN SN-UNKNOWN REF: AMM 30-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301009	SWITCH:LEFT WING BLEED AIR OVERHEAT SWITCH PN SN-UNKNOWN REF: AMM 30-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301010	SWITCH:RIGHT WING BLEED AIR OVERHEAT SWITCH PN SN-UNKNOWN REF: AMM 30-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301011	SWITCH:WING UNDERHEAT WARNING SWITCH PN SN-UNKNOWN REF: AMM 30-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301014	VALVE:WING ANTI-ICE VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301015	CHECK VALVE:LEFT WING ANTI-ICE CHECK VALVE PN SN-UNKNOWN REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
301016	CHECK VALVE:RIGHT WING ANTI-ICE CHECK VALVE 1H95-8 3AP25 REF: AMM 30-10-08	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-DEC-2008 7720.6 5492			
301101	CONTROLLER:HORIZONTAL STABILIZER ANTI-ICE CONTROLLER 6608485-1 9917003 REF: AMM 30-11-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-OCT-2007 7280.1 5163			
301103	BLANKET:LEFT HORIZONTAL STABILIZER HEAT BLANKET 4065-3481 SN-UNKNOWN REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301104	BLANKET:RIGHT HORIZONTAL STABILIZER HEAT BLANKET 4065-3481 07-26418 REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-OCT-2007 7280.1 5163			
301109	CIRCUIT BREAKER:CBR9 REMOTE CIRCUIT BREAKER PN SN-UNKNOWN REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301110	CIRCUIT BREAKER:CBR10 REMOTE CIRCUIT BREAKER PN SN-UNKNOWN REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
301111	CIRCUIT BREAKER:CBR11 REMOTE CIRCUIT BREAKER PN SN-UNKNOWN REF: AMM 30-11-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
302101	SHUTOFF VALVE:LEFT NACELLE ANTI-ICE SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
302102	SHUTOFF VALVE:RIGHT NACELLE ANTI-ICE SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 30-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
302103	PRESSURE SWITCH:LEFT NACELLE ANTI-ICE PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
302104	PRESSURE SWITCH:RIGHT NACELLE ANTI-ICE PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 30-21-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
303001	MONITOR:LEFT PITOT HEAT MONITOR 6608317-7 SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
303002	MONITOR:RIGHT PITOT HEAT MONITOR 6608317-7 SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
303003	MONITOR:STANDBY PITOT HEAT MONITOR PN SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
304001	SHUTOFF VALVE:WINDSHIELD ANTI-ICE SHUTOFF VALVE 6600201-1 2340 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C				07-FEB-2006 6454.7 4611		
304002	VALVE:WINDSHIELD ANTI-ICE MODULATING VALVE PN SN-UNKNOWN REF: AMM 30-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
304003	VALVE:WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE 6600203-1 SN-UNKNOWN REF: AMM 30-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
304004	HEAT EXCHANGER:WINDSHIELD ANTI-ICE HEAT EXCHANGER 6600351-2 SN-UNKNOWN REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
304005	SENSOR:WINDSHIELD ANTI-ICE TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 30-40-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
304007	THERMOSWITCH:LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH 6600141-3 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
304008	THERMOSWITCH:RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH 6600141-3 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
304009	THERMOSWITCH:LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH 6600141-13 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
304010	THERMOSWITCH:RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH 6600141-13 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
304101	TANK ASSY:ALCOHOL SUPPLY TANK ASSY 5419751-11 SN-UNKNOWN REF: AMM 30-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
304102	FLOAT SWITCH:ALCOHOL ANTI-ICE FLOAT SWITCH L14F-74 SN-UNKNOWN REF: AMM 30-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
304104	RELIEF VALVE:ALCOHOL PRESSURE RELIEF VALVE 6608260-3 SN-UNKNOWN REF: AMM 30-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
304105	SHUTOFF VALVE:ANTI-ICE THREE-WAY SHUTOFF VALVE 6608258-2 SN-UNKNOWN REF: AMM 30-41-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
304106	PRESSURE REGULATOR VALVE:ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE 6608257-1 1167A REF: AMM 30-41-06	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493			
304203	RELAY BOX:WINDSHIELD DEFOG RELAY BOX 3118318-3 SN-UNKNOWN REF: AMM 30-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
308001	LAMP:LEFT ICE DETECT LAMP 6839 SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-MAY-2001 3894.8 2733			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
308002	LAMP:RIGHT ICE DETECT LAMP PN-UNKNOWN SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2006 6748.2 4804		
E3020001A (s)	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 1 REF:	MOS HRS/MSC AFL	E/C				PKG 16-APR-2005 5981.1 4288		ENGINE CHANGE
E3020001B (s)	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 2 REF:	MOS HRS/MSC AFL	E/C				PKG 16-SEP-2005 6249.4 4477		ENGINE CHANGE
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
311006	PANEL ASSEMBLY:TEST SWITCH PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 31-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
311007	PANEL:PILOT DISPLAY CONTROL (DCP) PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
311008	PANEL:COPILOT DISPLAY CONTROL (DCP) PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
311009	PANEL:LEFT CURSOR CONTROL (CCP) PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
311010	PANEL:RIGHT CURSOR CONTROL (CCP) PANEL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
312001	CLOCK:PILOT CREW CLOCK M877 SN-UNKNOWN REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
312001A	CLOCK:REPLACE PILOT CREW CLOCK BATTERY REF: CMM STANDARD AND OPTIONAL FEATURES	MOS HRS/MSC AFL	24				27-JUL-2007 7163.1 5078	27-JUL-2009	OVD

?-Insufficient Information
(EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
312002	CLOCK:COPILOT CREW CLOCK M877 17488 REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C				31-AUG-2007 7222.5 5120			
312002A	CLOCK:REPLACE COPILOT CREW REF: CMM STANDARD AND OPTIONAL FEATURES	CLOCK BATTERY MOS HRS/MSC AFL	24				27-JUN-2007 7163.1 5078	27-JUN-2009		OVD
313001	RECORDER:FLIGHT DATA (FDR) RECORDER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
313018	SWITCH:FDR INERTIA, CVR/FDR SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
313103	ACCELEROMETER:MULTI-AXIAL ACCELEROMETER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
314002	CAGE:IAPS CARD CAGE PN SN-UNKNOWN REF: AMM 31-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
314004	CONTROLLER:IAPS ENVIRONMENTAL (IEC) CONTROLLER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
314007	MODULE:NO. 1 OPTIONS CONTROL MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
314008	MODULE:NO. 2 OPTIONS CONTROL MODULE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
314011	CARD:1A PWR-851A POWER SUPPLY CARD 622-8365-003 1607 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
314012	CARD:2A PWR-851A POWER SUPPLY CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
314013	CARD:1B PWR-851A POWER SUPPLY CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
314014	CARD:2B PWR-851A POWER SUPPLY CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
314021	CARD:1A FLIGHT CONTROL CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
314022	CARD:2A FLIGHT CONTROL CARD PN SN-UNKNOWN REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
314041	CARD:1A INPUT/OUTPUT CONCENTRATOR CARD 622-9343-221 1900 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493		
314042	CARD:2A INPUT/OUTPUT CONCENTRATOR CARD 622-9343-221 1901 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493		
314043	CARD:1B INPUT/OUTPUT CONCENTRATOR CARD 622-9343-221 1902 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493		
314044	CARD:2B INPUT/OUTPUT CONCENTRATOR CARD 622-9343-221 1903 REF: AMM 31-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493		
314047	UNIT:NO. 1 CONFIGURATION STRAPPING (CSU) UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
314048	UNIT:NO. 2 CONFIGURATION STRAPPING (CSU) UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
314101	UNIT:DATA ACQUISITION UNIT PN SN-UNKNOWN REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
314110	UNIT:MINI-FLIGHT DATA ACQUISITION (MFDAU) UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
315101	CONTROL UNIT:AURAL WARNING CONTROL UNIT 6608108-2 SN-UNKNOWN REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
315102	GENERATOR:TONE GENERATOR 6608445-3 SN-UNKNOWN REF: AMM 31-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
315103	MIXER:AURAL WARNING MIXER 1882-1 SN-UNKNOWN REF: AMM 31-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
315201	PANEL:GLARESHIELD ANNUNCIATOR PANEL PN SN-UNKNOWN REF: AMM 31-52-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
315203	UNIT ASSEMBLY:MASTER CAUTION/WARNING TRIGGER UNIT ASSEMBLY PN SN-UNKNOWN REF: AMM 31-52-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316001	DISPLAY:PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-006 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316002	DISPLAY:COPILOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-006 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
316003	DISPLAY:MULTIFUNCTION DISPLAY 622-9434-026 2840 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12		
316004	DISPLAY:MULTIFUNCTION DISPLAY 622-9434-026 3249 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C				04-JAN-2008 7390.7 5235		
316005	CONTROL PANEL:PILOT EFIS CONTROL PANEL PN SN-UNKNOWN REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316006	CONTROL PANEL:COPILOT EFIS CONTROL PANEL PN SN-UNKNOWN REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316011	TRAY:NO. 1 DISPLAY IMT-871 TRAY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316012	TRAY:NO. 2 DISPLAY IMT-871 TRAY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316013	TRAY:NO. 3 DISPLAY IMT-871 TRAY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316014	TRAY:NO. 4 DISPLAY IMT-871 TRAY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316101	DISPLAY UNIT:SENSOR DISPLAY UNIT PN SN-UNKNOWN REF: AMM 31-61-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
316102	DRIVER UNIT:SENSOR DISPLAY DRIVER UNIT PN SN-UNKNOWN REF: AMM 31-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
316201	UNIT:NO. 1 FILE SERVER (FSU) UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
316202	UNIT:NO. 2 FILE SERVER (FSU) UNIT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
316203	EXTERNAL COMPENSATION UNIT (ECU-3000):NO. 1 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
316204	EXTERNAL COMPENSATION UNIT (ECU-3000):NO. 2 FILE SERVER EXTERNAL COMPENSATION UNIT (ECU-3000) PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
316301	PANEL ASSEMBLY:MAINTENANCE WARNING PANEL ASSEMBLY PN SN-UNKNOWN REF: AMM 31-63-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
CHAPTER 32 LANDING GEAR										
05-11-00-E3211066	REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4) - MOS HRS/MSC REF:	AFL	6000	+25/-25			30-JAN-1997 0 0	6000	6025	503
05-11-00-E3211084L	REPLACE LEFT MLG ACTUATOR ATTACH PIN (5441101) MOS HRS/MSC REF:	AFL	20000				30-JAN-1997 0 0	20000		LIFE LIMIT 14503
05-11-00-E3211084R	REPLACE RIGHT MLG ACTUATOR ATTACH PIN (5441101) MOS HRS/MSC REF:	AFL	20000				30-JAN-1997 0 0	20000		LIFE LIMIT 14503
05-11-00-E3211092L	REPLACE LEFT MLG UPPER BEARING (7600839) MOS HRS/MSC REF:	AFL	6000				16-NOV-2001 4217.2 2985	8985		LIFE LIMIT 3488
05-11-00-E3211092R	REPLACE RIGHT MLG UPPER BEARING (7600839) MOS HRS/MSC REF:	AFL	6000				16-NOV-2001 4217.2 2985	8985		LIFE LIMIT 3488

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E3211093L	REPLACE LEFT MLG LOWER BEARING (6041105)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				7721.6 5493	11493		5996
05-11-00-E3211093R	REPLACE RIGHT MLG LOWER BEARING (6041105)	MOS					06-OCT-2009		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				7721.6 5493	11493		5996
05-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR	MOS					17-APR-2006			
	REF:	HRS/MSC AFL	O/C				6598.7 4701			
05-11-00-G3233007	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS.	MOS					30-DEC-2008			
	REF:	HRS/MSC AFL	O/C				7720.6 5492			
05-11-00-G3243040	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN WHEEL WELL AREA	MOS					16-NOV-2001			
	REF:	HRS/MSC AFL	O/C				4217.2 2985			
05-11-00-M3211091L	REPLACE LEFT MLG UPPER BEARING RETENTION PIN (6041110-002, -003, AND -004)	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				4217.2 2985	8985		3488
05-11-00-M3211091R	REPLACE RIGHT MLG UPPER BEARING RETENTION PIN (6041110-002, -003, AND -004)	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				4217.2 2985	8985		3488
321001	STRUT:ASSEMBLY, LEFT MAIN LANDING GEAR STRUT 6041100-029	MOS		TSN:153 TSR:0			06-OCT-2009		LIFE LIMIT	
	007	HRS/MSC		TSN:7721.6			7721.6			
	REF: AMM 32-11-00	AFL	16500	TSN:5493 TSR:0			5493	16500		11003
		ACH								
321002	STRUT:ASSEMBLY, RIGHT MAIN LANDING GEAR STRUT 6041100-030	MOS		TSN:153 TSR:0			06-OCT-2009		LIFE LIMIT	
	005	HRS/MSC		TSN:7721.6 TSR:0			7721.6			
	REF: AMM 32-11-00	AFL	16500	TSN:5493 TSR:0			5493	16500		11003
321003	ARM:LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM 2341119-5	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 32-11-01	AFL		TSN:0			0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
321004	ARM:RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM 2341119-5 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321005	ARM:LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM 2341119-1 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321006	ARM:RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM 2341119-1 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321501	RESTRICTOR:LEFT HYDRAULIC, GEAR RETRACTION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321502	RESTRICTOR:RIGHT HYDRAULIC, GEAR RETRACTION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321511	RESTRICTOR:LEFT HYDRAULIC, GEAR EXTENSION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321512	RESTRICTOR:RIGHT HYDRAULIC, GEAR EXTENSION RESTRICTOR PN SN-UNKNOWN REF: AMM 32-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321515	RESTRICTOR:LEFT HYDRAULIC RESTRICTOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
321516	RESTRICTOR:RIGHT HYDRAULIC RESTRICTOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
322001	STRUT:ASSEMBLY, NOSE GEAR STRUT 2342100-19 102 REF: AMM 32-21-00	MOS HRS/MSC AFL		TSN:153 TSN:7721.6 TSN:5493			06-OCT-2009 7721.6 5493		LIFE LIMIT 10000	4503

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
322002	STRUT:NOSE LANDING GEAR & STEERING ASSEMBLY STRUT									LIFE LIMIT
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC		TSN:0			0			
	REF:	AFL	10000	TSN:0			0	10000		4503
323019	SWITCH:LEFT MAIN LANDING GEAR SQUAT SWITCH									
	426EN9-8	MOS		TSN:0			16-AUG-2008			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			7662.2			
	REF: AMM 32-30-03	AFL		TSN:0			5450			
323020	SWITCH:RIGHT MAIN LANDING GEAR SQUAT SWITCH									
	426EN9-8	MOS		TSN:0			16-AUG-2008			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			7662.2			
	REF: AMM 32-30-03	AFL		TSN:0			5450			
323031	ACTUATOR:LEFT MAIN LANDING GEAR ACTUATOR									LIFE LIMIT
	2327100-028	MOS		TSN:153 TSR:0			06-OCT-2009			
	KI0021	HRS/MSC		TSN:7721.6 TSR:0			7721.6			
	REF: AMM 32-31-01	AFL	20000	TSN:5493 TSR:0			5493	20000		14503
323032	ACTUATOR:RIGHT MAIN LANDING GEAR ACTUATOR									LIFE LIMIT
	2327100-028	MOS		TSN:153 TSR:0			06-OCT-2009			
	KI0018	HRS/MSC		TSN:7721.6 TSR:0			7721.6			
	REF: AMM 32-31-01	AFL	20000	TSN:5493			5493	20000		14503
323036	PIN:LEFT MAIN LANDING GEAR ACTUATOR ATTACH PIN									
	5441101-1	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF:	AFL		TSN:0			0			
323037	PIN:RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PIN									
	5441101-1	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF:	AFL		TSN:0			0			
323043	ACTUATOR:LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR									
	6600085-009	MOS		TSO:0			06-OCT-2009			
	0727	HRS/MSC	O/C	TSO:0			7721.6			
	REF: AMM 32-31-03	AFL		TSO:0			5493			
323044	ACTUATOR:RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR									
	6600085-8	MOS		TSR:0			15-APR-2002			
	0814R	HRS/MSC	O/C	TSR:0			4699.1			
	REF: AMM 32-31-03	AFL		TSR:0			3313			
323052	PANEL ASSEMBLY:LANDING GEAR CONTROL PANEL ASSEMBLY									
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 32-30-06	AFL		TSN:0			0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
323055	ACTUATOR:LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323056	ACTUATOR:RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323057	ACTUATOR:LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR PN SN-UNKNOWN REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323058	ACTUATOR:RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR FREEFALL ACTUATOR PN SN-UNKNOWN REF: AMM 32-33-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323073	ACTUATOR:NOSE LANDING GEAR ACTUATOR 2317100-016 K10019 REF: AMM 32-32-01	MOS HRS/MSC AFL ACH	10000	TSR:0 TSN:7721.6 TSR:0 TSN:5493			06-OCT-2009 7721.6 5493	10000	LIFE LIMIT	4503
323079	ACTUATOR:UPLOCK, NOSE LANDING GEAR ACTUATOR 2417016-1 SN-UNKNOWN REF: AMM 32-32-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323080	ACTUATOR:UPLOCK, NOSE LANDING GEAR FREEFALL ACTUATOR PN SN-UNKNOWN REF: AMM 32-33-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323098	VALVE:GEAR DOOR CONTROL VALVE PN SN-UNKNOWN REF: AMM 32-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323099	VALVE:SELECT, LANDING GEAR VALVE 48C48641 0777 REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			10-OCT-1999 2279.2 1591			
323105	SHUTTLE VALVE:NOSE LANDING GEAR SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
323110	SHUTTLE VALVE:NOSE LANDING GEAR UPLATCH SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323205	SHUTTLE VALVE:LEFT MAIN LANDING GEAR EXTEND SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323210	SHUTTLE VALVE:RIGHT MAIN LANDING GEAR EXTEND SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323222	PILLAR:LEFT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR 2441123-17 SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0	20000		14503
323223	PILLAR:RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR 2341123-17 SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0	20000		14503
323305	SHUTTLE VALVE:LEFT MAIN LANDING GEAR DOOR SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323310	SHUTTLE VALVE:RIGHT MAIN LANDING GEAR DOOR SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323315	SHUTTLE VALVE:LEFT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323320	SHUTTLE VALVE:RIGHT MAIN LANDING GEAR DOOR UPLATCH SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
323401	VALVE:AFT EMERGENCY GEAR BLOWDOWN EXTENSION VALVE PN SN-UNKNOWN REF: AMM 32-33-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
323402	VALVE:FORWARD EMERGENCY GEAR FREEFALL EXTENSION VALVE PN SN-UNKNOWN REF: AMM 32-33-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
323405	VALVE:LEFT CHECK, FREEFALL VALVE PN SN-UNKNOWN REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
323406	VALVE:RIGHT CHECK, FREEFALL VALVE PN SN-UNKNOWN REF: AMM 32-33-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
323409	RESTRICTOR:UPPER EMERGENCY GEAR EXTENSION RESTRICTOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
323410	RESTRICTOR:LOWER EMERGENCY GEAR EXTENSION RESTRICTOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
323430	SHUTTLE VALVE:NO. 1 EMERGENCY AIR BLOWDOWN SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324001	TIRE:NOSE TIRE 184F10-2 70890561 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				11-DEC-2007 7359.3 5215		
324007	WHEEL:ASSEMBLY, NOSE WHEEL 9544207-4 AUG99-8963 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				29-SEP-2008 7707 5483		
324013	TIRE:NO. 1 MAIN LANDING GEAR TIRE 178K43-1 71860788 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				25-JAN-2008 7421.5 5259		
324014	TIRE:NO. 2 MAIN LANDING GEAR TIRE 178K43-1 71840874 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				25-JAN-2008 7421.5 5259		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
324015	TIRE:NO. 3 MAIN LANDING GEAR TIRE 301-321-870 70600896 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-AUG-2007 7205.7 5109		
324016	TIRE:NO. 4 MAIN LANDING GEAR TIRE 301-321-870 70610900 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-AUG-2007 7205.7 5109		
324037	WHEEL:NO. 1 MAIN LANDING GEAR WHEEL 5011740 DEC00-1530 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				29-SEP-2008 7707 5483		
324037A	WHEEL:NDT INSPECT NO. 1 MAIN LANDING GEAR WHEEL REF:	MOS HRS/MSC AFL	O/C				30-JAN-1997 0 0		
324038	WHEEL:NO. 2 MAIN LANDING GEAR WHEEL 5011740 JAN00-1263 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				29-SEP-2008 7707 5483		
324038A	WHEEL:NDT INSPECT NO. 2 MAIN LANDING GEAR WHEEL REF:	MOS HRS/MSC AFL	O/C				30-JAN-1997 0 0		
324039	WHEEL:NO. 3 MAIN LANDING GEAR WHEEL 5011740 FEB94-267 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				29-SEP-2008 7707 5483		
324039A	WHEEL:NDT INSPECT NO. 3 MAIN LANDING GEAR WHEEL REF:	MOS HRS/MSC AFL	O/C				30-JAN-1997 0 0		
324040	WHEEL:NO. 4 MAIN LANDING GEAR WHEEL 5011740 FEB97-700 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				29-SEP-2008 7707 5483		
324040A	WHEEL:NDT INSPECT NO. 4 MAIN LANDING GEAR WHEEL REF:	MOS HRS/MSC AFL	O/C				30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
324048	BRAKE:NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE 5003096-7 APR93-3485 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-DEC-2008 7720.6 5492		
324049	BRAKE:NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE 5003096-7 MAR99-5033 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-DEC-2008 7720.6 5492		
324050	BRAKE:NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE 5003096-7 MAR69-720 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-DEC-2008 7720.6 5492		
324051	BRAKE:NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE 5003096-7 JAN85-247 REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-DEC-2008 7720.6 5492		
324061	VALVE:NO. 1 POWER BRAKE, PILOTS VALVE 3321200-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324062	VALVE:NO. 2 POWER BRAKE, PILOTS VALVE 6081041-804 9671052 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-APR-2000 2754 1912		
324063	VALVE:NO. 1 POWER BRAKE, COPILOTS VALVE 6081041-804 9681057 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-APR-2000 2754 1912		
324064	VALVE:NO. 2 POWER BRAKE, COPILOTS VALVE 3321200-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324085	FUSE:NO. 1 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324086	FUSE:NO. 2 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
324109	FUSE:NO. 3 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324110	FUSE:NO. 4 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324133	VALVE:AFT PARKING BRAKE VALVE 3329 SN-UNKNOWN REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324134	VALVE:FWD PARKING BRAKE VALVE 3329 SN-UNKNOWN REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324145	TRANSDUCER:NO. 1 WHEEL SPEED TRANSDUCER PN-UNKNOWN SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-SEP-1998 1130.9 771		
324146	TRANSDUCER:NO. 2 WHEEL SPEED TRANSDUCER 40-911 SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324147	TRANSDUCER:NO. 3 WHEEL SPEED TRANSDUCER 40-911 SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324148	TRANSDUCER:NO. 4 WHEEL SPEED TRANSDUCER 40-911 SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324169	VALVE:LEFT ANTI-SKID VALVE 39-309-1 SN-UNKNOWN REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324170	VALVE:RIGHT ANTI-SKID VALVE 39-309-1 SN-UNKNOWN REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
324175	CONTROL:ANTI-SKID CONTROL 42-379-1 SN-UNKNOWN REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324413	BOX ASSY:PARK BRAKE ANNUNCIATOR BOX ASSY 2618481-3 SN-UNKNOWN REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324501	VALVE:EMERGENCY BRAKE CONTROL VALVE 63500-2 SN-UNKNOWN REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324505	SHUTTLE VALVE:LEFT MAIN LANDING GEAR BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324510	SHUTTLE VALVE:RIGHT MAIN LANDING GEAR BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324601	SHUTTLE VALVE:NO. 1 MAIN LANDING GEAR BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324602	SHUTTLE VALVE:NO. 2 MAIN LANDING GEAR BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324603	SHUTTLE VALVE:NO. 3 MAIN LANDING GEAR BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
324604	SHUTTLE VALVE:NO. 4 MAIN LANDING GEAR BRAKE SHUTTLE VALVE PN SN-UNKNOWN REF: AMM 32-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
325001	ACTUATOR:NOSE WHEEL STEERING ACTUATOR 501-1711-02 1064 REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			13-MAR-2002 4591.4 3229		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
325005	COMPUTER:NOSE WHEEL STEERING COMPUTER 501-1708-02 1152 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C				23-DEC-1999 2446.3 1711			
325015	SENSOR:LEFT RUDDER POSITION SENSOR PN SN-UNKNOWN REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
325016	SENSOR:RIGHT RUDDER POSITION SENSOR PN SN-UNKNOWN REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
325019	GEARBOX:NOSE WHEEL STEERING ACTUATOR GEARBOX 3142025-1 SN-UNKNOWN REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
325020	ASSEMBLY:NOSE WHEEL STEERING FOLLOW UP ASSEMBLY PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
325024	FOLLOWUP:RIGHT NOSE WHEEL STEERING FOLLOWUP PN SN-UNKNOWN REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
325025	FOLLOWUP:LEFT NOSE WHEEL STEERING FOLLOWUP PN SN-UNKNOWN REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
325628	VALVE:AFT EMERGENCY GEAR CONTROL VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
326011	RELAY BOX:SQUAT SWITCH RELAY BOX PN SN-UNKNOWN REF: AMM 32-30-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
E3211074	REPLACE LEFT MLG UPPER BEARINGS (6041104) REF:	MOS HRS/MSC AFL					16-NOV-2001 4217.5 2985		LIFE LIMIT 5985	488

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
E3211074	REPLACE RIGHT MLG UPPER BEARINGS (6041104)	MOS					16-NOV-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	3000				4217.5 2985	5985		488
CHAPTER 33 LIGHTS										
331201	POWER SUPPLY:LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY	MOS		TSN:0			30-DEC-2008			
	6900115	HRS/MSC	O/C	TSN:0			7720.6			
	6225	AFL		TSN:0			5492			
	REF: AMM 33-12-02	AFL		TSN:0						
331202	POWER SUPPLY:RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY	MOS		TSN:0			30-JAN-1997			
	6608477-1	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-12-02	AFL		TSN:0						
331401	CONTROL BOX:PILOT DIMMING CONTROL BOX	MOS		TSN:0			30-JAN-1997			
	6018145-1	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-14-01	AFL		TSN:0						
331402	CONTROL BOX:COPILOT DIMMING CONTROL BOX	MOS		TSN:0			30-JAN-1997			
	6018145-1	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-14-01	AFL		TSN:0						
331403	CONTROL BOX:CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX	MOS		TSN:0			30-JAN-1997			
	2618289-14	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-14-01	AFL		TSN:0						
331404	CONTROL BOX:PEDESTAL DIMMING CONTROL BOX	MOS		TSN:0			30-JAN-1997			
	2618289-14	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-14-01	AFL		TSN:0						
331405	CONTROL BOX:FUEL QUANTITY INDICATOR DIMMING CONTROL BOX	MOS		TSN:0			30-JAN-1997			
	2618289-14	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-14-01	AFL		TSN:0						
331406	CONTROL BOX:CDU LAMP DIMMING CONTROL BOX	MOS		TSN:0			30-JAN-1997			
	2618262-9	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-14-01	AFL		TSN:0						
332009	CONTROL:INDIRECT LIGHTING CONTROL	MOS		TSN:0			30-JAN-1997			
	MS1836	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 33-20-09	AFL		TSN:0						

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
332010	MODULE:ALTERNATE/MOMENTARY SWITCHING MODULE MS1881 0162 REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-FEB-2002 4460.2 3157		
332014	CONTROL:ZONE BACK LIGHTING CONTROL MS1839-2 0261 REF: AMM 33-20-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12		
334101	LIGHT ASSEMBLY:LEFT LANDING AND TAXI LIGHT ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-MAR-2008		
334102	LIGHT ASSEMBLY:RIGHT LANDING AND TAXI LIGHT ASSEMBLY PN-UNKNOWN SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-MAR-2008		
334201	LIGHT ASSEMBLY:LEFT NAVIGATION LIGHT ASSEMBLY 30-1728-1 SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
334202	LIGHT ASSEMBLY:RIGHT NAVIGATION LIGHT ASSEMBLY 30-1728-2 SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
334301	LIGHT:UPPER STROBE/BEACON LIGHT GE16386-9-2 018 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-MAY-2000 2867.2 2016		
334302	LIGHT:LOWER STROBE/BEACON LIGHT GE 16386-9-1 098 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			06-OCT-2009 7721.6 5493		
334401	LIGHT ASSEMBLY:WING ICE INSPECTION LIGHT ASSEMBLY GLJ-111 SN-UNKNOWN REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-AUG-2006 6748.2 4804		
334501	LIGHT:RECOGNITION LIGHT Q4681 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-AUG-2007 7193.4 5101		

CHAPTER 34 NAVIGATION

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION	NEXT DUE		TIME REMAINING
							COMPLIANCE (ENH)	ACTUAL	MAX LIMIT	
+ 05-10-30-RVSM-L3411015	PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (REFER TO 34-17-00)	MOS HRS/MSC AFL	12 +14d/-14d				30-DEC-2008 7720.6 5492	30-DEC-2009	13-JAN-2010	54 d
34-00-FAR-91.171	CHECK VOR FAR 91.171	DAYS HRS/MSC AFL	O/C				23-DEC-1998 1436.6 995			
34-00-FAR-91.217	PERFORM ALTITUDE DATA TRANSMISSION TEST	MOS HRS/MSC AFL	A/R				27-FEB-2005 5870.7 4210			
34-00-FAR-91.411	RECERTIFY PITOT-STATIC SYSTEM	MOS HRS/MSC AFL	24				06-OCT-2009 7721.6 5493	06-OCT-2011		699 d
341001	PROCESSOR UNIT:TCAS PROCESSOR UNIT 622-8971-422 5830	MOS HRS/MSC AFL	O/C				20-MAY-2002 4820.3 3400			
341020	PROBE:LEFT PITOT/STATIC PROBE 856KR7 232017	MOS HRS/MSC AFL	15000	+25/-25	TSN:0 TSN:0 TSN:0		30-DEC-2008 7720.6 5492	22720.6	22745.6	LIFE LIMIT 14996.4
341020A	PROBE:VERIFY LEFT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (REFER TO 34-11-02) 5-10-30-N3411016	MOS HRS/MSC AFL	24	+14d/-14d			30-DEC-2008 7720.6 5492	30-DEC-2010	13-JAN-2011	419 d
+ 341020B	PROBE:DETAILED VISUAL INSPECTION LEFT PITOT/STATIC PROBE (REFER TO 34-11-02) 5-10-30-N3411064	MOS HRS/MSC AFL	24	+14d/-14d			30-DEC-2008 7720.6 5492	30-DEC-2010	13-JAN-2011	419 d
341025	PROBE:RIGHT PITOT/STATIC PROBE 856KR8 SN-UNKNOWN	MOS HRS/MSC AFL	15000	+25/-25	TSN:0 TSN:0 TSN:0		30-JAN-1997 0 0	15000	15025	LIFE LIMIT 7275.8
341025A	PROBE:VERIFY RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (REFER TO 34-11-02) 5-10-30-N3411016	MOS HRS/MSC AFL	24	+14d/-14d			30-DEC-2008 7720.6 5492	30-DEC-2010	13-JAN-2011	419 d

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2 Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
+ 341025B	PROBE:DETAILED VISUAL INSPECTION RIGHT PITOT/STATIC PROBE (REFER TO 34-11-02) 5-10-30-N3411064	MOS HRS/MSC AFL	24 +14d/-14d				30-DEC-2008 7720.6 5492	30-DEC-2010 13-JAN-2011	419 d
341111	ALTIMETER:STANDBY ALTIMETER 8047-500-53 02090100B REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C				19-DEC-2008 7720.6 5492		
+ 341111A	ALTIMETER:RECERTIFY STANDBY ALTIMETER	MOS HRS/MSC AFL	24				30-DEC-2008 7720.6 5492	30-DEC-2010	419 d
341133	COMPUTER:NO. 1 AIR DATA COMPUTER 822-0386-426 2332 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C				19-DEC-2008 7720.6 5492		
+ 341133A	COMPUTER:RECERTIFY NO. 1 AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM NO. 1	MOS HRS/MSC AFL	24				30-DEC-2008 7720.6 5492	30-DEC-2010	419 d
341134	COMPUTER:NO. 2 AIR DATA COMPUTER 822-0386-426 2986 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C				19-DEC-2008 7720.6 5492		
+ 341134A	COMPUTER:RECERTIFY NO. 2 AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM NO. 2	MOS HRS/MSC AFL	24				30-DEC-2008 7720.6 5492	30-DEC-2010	419 d
341801	INDICATOR:STANDBY MACH/AIRSPEED INDICATOR 2C131(02B7C9) 319 REF: AMM 34-18-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-APR-2006 6598.7 4701		
342015	SENSOR:DISPLAY UNIT SENSOR 622-9735-002 843 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12		
342401	COMPASS:MAGNETIC COMPASS C-2350L4-M23 SN-UNKNOWN REF: AMM 34-24-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
342410	COMPUTER:NO. 1 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400 2768 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
342411	COMPUTER:NO. 2 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400 3522 REF: AMM 34-26-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
342501	INDICATOR:STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR 501-1567-02 1381 REF: AMM 34-25-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			21-MAR-2008 7470.1 5300		
344111	ANTENNA:LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 23216 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12		
344112	ANTENNA:UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 23135 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12		
344205	RECEIVER/TRANSMITTER/ANTENNA:WEATHER RADAR (RTA-844) RECEIVER/TRANSMITTER/ANTENNA 622-9302-003 3458 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C				22-SEP-2008 7697.6 5474		
344807	CONTROL PANEL:PILOT EFIS RADAR CONTROL PANEL 1015-1-11 798 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
344808	CONTROL PANEL:COPILOT EFIS RADAR CONTROL PANEL 1015-1-11 799 REF: AMM 34-61-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
345001	RECEIVER:NO. 1 ADF (ADF-462) RECEIVER 622-7382-101 SN-UNKNOWN REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
345005	COMPUTER:KGP 860 GA-EGPWS (ENHANCED GROUND PROXIMITY WARNING SYSTEM) 066-01197-0205 3339 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-FEB-2005 5852.6 4198		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
345011	TRANSCEIVER:NO. 1 DME TRANSCEIVER 622-7309-101 3084 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			24-SEP-1997 143.4 103		
345012	TRANSCEIVER:NO. 2 DME TRANSCEIVER 622-7309-101 3113 REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
345013	ANTENNA:ADF, DUAL (ANT-462B) ANTENNA 622-7384-001 2RBBB REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
345021	RECEIVER:NO. 1 VHF (VIR 432) RECEIVER 622-7194-101 498X REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C				22-JUL-2008 7633 5432		
345022	RECEIVER:NO. 2 VHF (VIR 432) RECEIVER 622-7194-101 5204 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C				21-MAR-2008 7470.1 5300		
345031	COMPUTER:NO. 1 NAVIGATION COMPUTER 1190-01-1110 SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
345032	COMPUTER:NO. 2 NAVIGATION COMPUTER 1190-01-1110 SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
345079	TRANSPONDER:PRIMARY ATC/MODE S TDR-94D TRANSPONDER 622-9210-003 4798 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
+ 345079A	TRANSPONDER:RECERTIFY PRIMARY ATC TRANSPONDER 91.413 REF:	MOS HRS/MSC AFL	24				19-DEC-2008 7720.6 5492	19-DEC-2010	408 d
345080	TRANSPONDER:SECONDARY ATC/MODE S TDR-94D TRANSPONDER 622-9210-003 192 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
+ 345080A	TRANSPONDER:RECERTIFY SECONDARY ATC TRANSPONDER 91.413	MOS	24				19-DEC-2008	19-DEC-2010	408 d	
	REF:	HRS/MSC AFL					7720.6 5492			
345085	CONTROL ADAPTER:NO. 1 ATC TRANSPONDER CONTROL ADAPTER	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 34-56-03									
345086	CONTROL ADAPTER:NO. 2 ATC TRANSPONDER CONTROL ADAPTER	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 34-56-03									
345091	ANTENNA:NO. 1 TRANSPONDER/DME ANTENNA	MOS		TSN:0			30-JAN-1997			
	C1100-2	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 34-56-02									
345092	ANTENNA:NO. 2 TRANSPONDER/DME ANTENNA	MOS		TSN:0			30-JAN-1997			
	C1100-2	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 34-56-02									
346015	CDU:NO. 1 UNS-1C+ FMS CDU	MOS		TSO:0			06-OCT-2009			
	10172-41-011	HRS/MSC	O/C	TSO:0			7721.6			
	241	AFL		TSO:0			5493			
	REF: See Workcard									
346016	CDU:NO. 2 UNS-1C+ FMS CDU	MOS		TSO:0			06-OCT-2009			
	10172-41-011	HRS/MSC	O/C	TSO:0			7721.6			
	386	AFL		TSO:0			5493			
	REF: See Workcard									
346021	UNIT:PRIMARY FMS DATA TRANSFER (DTU) UNIT	MOS		TSN:0			06-OCT-2009			
	1408-00-1	HRS/MSC	O/C	TSN:0			7721.6			
	480	AFL		TSN:0			5493			
	REF: AMM 34-61-04									
346025	MODULE:NO. 1 FMS CONFIGURATION MODULE	MOS		TSN:0			06-OCT-2009			
	10171	HRS/MSC	O/C	TSN:0			7721.6			
	5488	AFL		TSN:0			5493			
	REF:									
346026	MODULE:NO. 2 FMS CONFIGURATION MODULE	MOS		TSN:0			06-OCT-2009			
	10171	HRS/MSC	O/C	TSN:0			7721.6			
	5632	AFL		TSN:0			5493			
	REF:									

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
347510	ANTENNA:FORWARD GPS ANTENNA 10708 5739 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
347511	ANTENNA:AFT GPS ANTENNA 10708 5738 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2009 7721.6 5493		
349985	UNIT:FLUX DETECTOR UNIT 622-5812-001 30978 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-OCT-2004 5731.5 4105		
CHAPTER 35 OXYGEN									
05-10-29-R3500019	CYLINDER:HYDROSTATIC TEST/INSPECT NOSE OXYGEN CYLINDER KEVLAR WRAPPED OXYGEN CYLINDER	MOS HRS/MSC AFL	36				31-JAN-2007 7720.6 5492	31-JAN-2010	86 d
350003	TRANSDUCER:NOSE OXYGEN SYSTEM PRESSURE TRANSDUCER 124058-2000 SN-UNKNOWN REF: AMM 35-00-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
350005	REGULATOR ASSEMBLY:NOSE OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY 172270-04 SN-UNKNOWN REF: AMM 35-00-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
350007	INDICATOR:NOSE OXYGEN PRESSURE INDICATOR PN SN-UNKNOWN REF: AMM 35-00-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
351001	MASK:PILOT OXYGEN MASK MC10-15-107 17309 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-AUG-2008 7662.2 5450		
351001A	MASK:OVERHAUL PILOT OXYGEN MASK MOS HRS/MSC AFL		72				31-AUG-2008 7662.2 5450	31-AUG-2014	1759 d
351002	MASK:COPILOT OXYGEN MASK MC10-15-107 102789 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			16-AUG-2008 7662.2 5450		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
351002A	MASK:OVERHAUL COPILOT OXYGEN MASK	MOS	72				31-JUL-2008	31-JUL-2014	1728 d
	REF:	HRS/MSC AFL					7662.2 5450		
351025	PRESSURE SWITCH:OXYGEN SYSTEM PRESSURE SWITCH	MOS		TSN:0			30-JAN-1997		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 35-00-07								
351071	BOX:PILOT CREW OXY MASK BOX	MOS		TSN:0			30-JAN-1997		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF:								
351072	BOX:COPILOT CREW OXY MASK BOX	MOS		TSN:0			30-JAN-1997		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF:								
352006	CYLINDER:NOSE OXYGEN CYLINDER	MOS	180	TSN:23			30-DEC-2008	31-JAN-2022	4469 d
	176270-40	HRS/MSC		TSN:0			7720.6		
	4974	AFL		TSN:0			5492		
	REF: AMM 35-00-01								
	Manufacture Date: 31-JAN-2007								
352027	VALVE:PASSENGER OXYGEN CONTROL VALVE	MOS		TSN:0			30-JAN-1997		
	P21004	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 35-20-03								
352031	VALVE:FORWARD SELECTOR, OXYGEN VALVE	MOS		TSN:0			30-JAN-1997		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 35-00-05								
352032	VALVE:AFT SELECTOR, OXYGEN VALVE	MOS		TSN:0			30-JAN-1997		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 35-00-05								
352033	VALVE:RIGHT AFT SELECTOR, OXYGEN VALVE	MOS		TSN:0			30-JAN-1997		
	PN	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 35-00-06								
352040	EQUIPMENT:PROTECTIVE BREATHING EQUIPMENT	MOS	120	+14d/-14d	TSN:0		30-AUG-2006	29-FEB-2016	LIFE LIMIT M 14-MAR-2016 2306 d
	802300-14	HRS/MSC			TSN:0		6748.2		
	PBE0206001078	AFL			TSN:0		4804		
	REF:								

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
353001	BOX:L1 OXYGEN MASK DROP BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
353002	BOX:R1 OXYGEN MASK DROP BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
353003	BOX:L2 OXYGEN MASK DROP BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
353004	BOX:R3 OXYGEN MASK DROP BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
353005	BOX:L3 OXYGEN MASK DROP BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
353006	BOX:R4 OXYGEN MASK DROP BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
353007	BOX:R2 OXYGEN MASK DROP BOX PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
CHAPTER 36 PNEUMATIC									
05-11-00-M3610011	REPLACE ENGINE BLEED AIR CHECK VALVES MOS HRS/MSC REF:	O/C AFL					30-DEC-2008 7720.6 5492	N/A BY SERIAL NUMBER	
360001	REPLACE LEFT ENGINE PYLON BLEED AIR SEALS MOS HRS/MSC REF: AMM 36-10-01	1200 AFL	+25/-25				30-DEC-2008 7720.6 5492	8920.6	8945.6 1196.4
360002	REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS MOS HRS/MSC REF: AMM 36-10-01	1200 AFL	+25/-25				30-DEC-2008 7720.6 5492	8920.6	8945.6 1196.4

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
360003	REPLACE TAILCONE BLEED AIR SEALS (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) (REFER TO 36-10-01)	MOS					30-DEC-2008			
		HRS/MSC	1200	+25/-25			7720.6	8920.6	8945.6	1196.4
	REF: AMM 36-10-01	AFL					5492			
361001	VALVE:NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE 23E64-2	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 36-10-04	AFL		TSN:0			0			
361002	VALVE:NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE 10E87-1	MOS					01-DEC-1999			
	GWD12234	HRS/MSC	O/C				2399			
	REF: AMM 36-10-04	AFL					1671			
361007	CONTROL BOX:LEFT MIXING VALVE CONTROL BOX 5418553-18	MOS					26-JAN-2008			
	692090B	HRS/MSC	O/C				7422.9			
	REF:	AFL					5262			
361007	BOX:LEFT MIXING VALVE CONTROL BOX PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 36-10-05	AFL		TSN:0			0			
361008	CONTROL BOX:RIGHT MIXING VALVE CONTROL BOX 5418553-18	MOS					25-JAN-2008			
	692090B	HRS/MSC	O/C				7421.8			
	REF:	AFL					5260			
361008	BOX:RIGHT MIXING VALVE CONTROL BOX PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 36-10-05	AFL		TSN:0			0			
361011	VALVE:LEFT BLEED AIR MIXING VALVE PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 36-10-02	AFL		TSN:0			0			
361011	VALVE:LEFT ENGINE BLEED AIR MIXTURE VALVE 1H106-9	MOS		TSO:0			26-JAN-2008			
	12AP72	HRS/MSC	O/C	TSO:0			7422.9			
	REF:	AFL		TSO:0			5262			
361012	VALVE:RIGHT BLEED AIR MIXING VALVE PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 36-10-02	AFL		TSN:0			0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
361012	VALVE:RIGHT ENGINE BLEED AIR MIXTURE VALVE 1H106-9 11AP55 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-NOV-2006 6847.5 4870		
361013	CHECK VALVE:NO. 1 BLEED AIR CHECK VALVE 6608295-3 3453 REF: AMM 21-30-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-DEC-2008 7720.6 5492		
361014	CHECK VALVE:NO. 2 BLEED AIR CHECK VALVE 6608295-3 3500 REF: AMM 21-30-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-DEC-2008 7720.6 5492		
361017	CHECK VALVE:NO. 1 BLEED AIR (1 1/4) CHECK VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
361018	CHECK VALVE:NO. 2 BLEED AIR (1 1/4) CHECK VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
361037	BOTTLE:NO. 1 (UPPER) EMERGENCY AIR BOTTLE 23111425 384 REF: AMM 36-15-01 Manufacture Date: 30-JUN-1999	MOS HRS/MSC AFL	180	TSN:0 TSO:0 TSN:0 TSO:0 TSN:0			15-JUN-2007 7105.8 5047	30-JUN-2014	SCRAP 1697 d
+ 361037A	BOTTLE:VISUAL INSPECTION NO. 1 EMERGENCY AIR BOTTLE AND HYDROSTATIC TEST REF:	MOS HRS/MSC AFL	36				13-JUN-2007 7105.8 5047	13-JUN-2010	219 d
+ 361037B	BOTTLE:X-RAY NO. 1 EMERGENCY AIR BOTTLE REF:	MOS HRS/MSC AFL	36				13-JUN-2007 7105.8 5047	13-JUN-2010	219 d
361038	BOTTLE:NO. 2 (LOWER) EMERGENCY AIR BOTTLE 23111425 306 REF: AMM 36-15-01 Manufacture Date: 30-JUN-1998	MOS HRS/MSC AFL	180	TSN:0 TSO:0 TSO:0 TSO:0			15-JUN-2007 7105.8 5047	30-JUN-2013	SCRAP 1332 d
+ 361038A	BOTTLE:VISUAL INSPECTION NO. 2 EMERGENCY AIR BOTTLE AND HYDROSTATIC TEST REF:	MOS HRS/MSC AFL	36				13-JUN-2007 7105.8 5047	13-JUN-2010	219 d

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION	NEXT DUE		TIME REMAINING
							COMPLIANCE (ENH)	ACTUAL	MAX LIMIT	
+ 361038B	BOTTLE:X-RAY NO. 2 EMERGENCY AIR BOTTLE	MOS	36				13-JUN-2007	13-JUN-2010		219 d
	REF:	HRS/MSC AFL					7105.8 5047			
361125	CHECK VALVE:LEFT TAILCONE BLEED AIR CHECK VALVE	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 36-10-03									
361126	CHECK VALVE:RIGHT TAILCONE BLEED AIR CHECK VALVE	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 36-10-03									
362001	INDICATOR:LANDING GEAR/BRAKE PRESSURE INDICATOR	MOS		TSN:0			30-JAN-1997			
	6608401-12	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 36-20-01									
362003	TRANSDUCER:PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER	MOS		TSN:0			30-JAN-1997			
	123091-5	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 36-20-02									
362004	TRANSDUCER:SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSDUCER	MOS		TSN:0			30-JAN-1997			
	123091-5	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 36-20-02									
362011	THERMOSTAT:NO. 1 ENGINE HI-LIMIT BLEED AIR THERMOSTAT	MOS					29-SEP-2000			
	6600141-3	HRS/MSC	O/C				3421.5			
	SN-UNKNOWN	AFL					2279			
	REF: AMM 36-20-03									
362012	THERMOSTAT:NO. 2 ENGINE HI-LIMIT BLEED AIR THERMOSTAT	MOS		TSN:0			29-SEP-2000			
	6600141-3	HRS/MSC	O/C	TSN:0			3421.5			
	SN-UNKNOWN	AFL		TSN:0			2279			
	REF: AMM 36-20-03									
362019	SWITCH:NO. 1 INBOARD OVERHEAT SWITCH	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 36-20-04									
362020	SWITCH:NO. 2 INBOARD OVERHEAT SWITCH	MOS		TSN:0			30-JAN-1997			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	AFL		TSN:0			0			
	REF: AMM 36-20-04									

CHAPTER 45 CENTRAL MAINT SYSTEM

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
451001	COMPUTER:MAINTENANCE DIAGNOSTIC (MDC) COMPUTER									
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF:	AFL		TSN:0			0			
CHAPTER 49 AIRBORNE AUXILIARY POWER										
49APU1	APU:APU									
	PN	MOS		TSN:0			30-JAN-1997			
49.APU1	SN-UNKNOWN	HRS/MSC	E/C	TSN:0			0			
	REF:	AFL		TSN:0			0			
CHAPTER 52 DOORS										
+ 05-10-29-L5210025	VISUAL INSPECTION EXTERIOR LWR DOOR STRUCTURE/HINGE FOR CORROSION									
		MOS	24	+14d/-14d			13-FEB-2008	13-FEB-2010	27-FEB-2010	99 d
	REF:	HRS/MSC					7428.5			
		AFL					5267			
521001	DOOR:UPPER PASSENGER/CREW DOOR									
	5410501-104	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-10-00	AFL		TSN:0			0			
521002	DOOR:LOWER PASSENGER/CREW DOOR									
	5410536-26	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-10-00	AFL		TSN:0			0			
521003	HANDLE:UPPER PASSENGER/CREW DOOR HANDLE									
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-10-02	AFL		TSN:0			0			
521004	LOCK ASSEMBLY:UPPER PASSENGER/CREW DOOR LOCK ASSEMBLY									
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-10-03	AFL		TSN:0			0			
521006	DAMPER:UPPER PASSENGER/CREW DOOR DAMPER									
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-10-06	AFL		TSN:0			0			
521008	HANDLE:LOWER PASSENGER/CREW DOOR HANDLE									
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-10-08	AFL		TSN:0			0			
521010	CABLE:FORWARD PASSENGER/CREW LOWER DOOR CABLE									
	PN	MOS		TSN:0			30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 52-10-10	AFL		TSN:0			0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
521011	CABLE:AFT PASSENGER/CREW LOWER DOOR CABLE PN SN-UNKNOWN REF: AMM 52-10-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
521012	DAMPER:LOWER PASSENGER/CREW DOOR DAMPER 6600425-2 599 REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-JUL-1997 15.3 12			
522000	DOOR:EMERGENCY EXIT / BAGGAGE DOOR PN SN-UNKNOWN REF: AMM 52-20-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
522002	HANDLE:EMERGENCY EXIT / BAGGAGE DOOR HANDLE 5411536-45 SN-UNKNOWN REF: AMM 52-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
522007	SNUBBER:EMERGENCY EXIT DOOR FORWARD SNUBBER PN SN-UNKNOWN REF: AMM 52-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
522008	SNUBBER:EMERGENCY EXIT DOOR AFT SNUBBER PN SN-UNKNOWN REF: AMM 52-20-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
522025	DAMPER:EMERGENCY EXIT/BAGGAGE DAMPER 12754-0012-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
522032	WINDOW:ASSEMBLY, EMERGENCY EXIT/BAGGAGE DOOR WINDOW 6600405-7 SN-UNKNOWN REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
522032A	WINDOW:PRISM CHECK ASSEMBLY, EMERGENCY EXIT/BAGGAGE DOOR WINDOW 05-10-29-M5600008 REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C				30-JAN-1997 0 0			
523101	DOOR:TAILCONE BAGGAGE DOOR 6011551-1 SN-UNKNOWN REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
523102	HANDLE:TAILCONE BAGGAGE HANDLE PN SN-UNKNOWN REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
524001	PERFORM AFT AVIONICS DOOR GAP AND MISMATCH INSPECTION (REFER TO 52-40-01) REF: AMM 52-40-01-N5240000	MOS HRS/MSC AFL	24 +14d/-14d				30-DEC-2008 7720.6 5492	30-DEC-2010 13-JAN-2011	419 d
524003	DOOR:LEFT FORWARD NOSE AVIONICS DOOR PN SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
524004	DOOR:RIGHT FORWARD NOSE AVIONICS DOOR PN SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
524005	DOOR:LEFT AFT NOSE AVIONICS DOOR PN SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
524006	DOOR:RIGHT AFT NOSE AVIONICS DOOR PN SN-UNKNOWN REF: AMM 52-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
524007	DOOR:TAILCONE AVIONICS DOOR PN SN-UNKNOWN REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
527005	BOX ASSEMBLY:CREW DOOR WARNING BOX ASSEMBLY 5418316-8 SN-UNKNOWN REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
527006	BOX ASSEMBLY:EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY 5418316-10 441193 REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-MAY-2001 3894.4 2733		
528001	DOOR:LEFT INBOARD MAIN LANDING GEAR DOOR 5422162-23 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
528002	DOOR:RIGHT INBOARD MAIN LANDING GEAR DOOR 6022161-806 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2005 6286.3 4501			
528003	DOOR:LEFT OUTBOARD MAIN LANDING GEAR DOOR 5422152-11 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
528004	DOOR:RIGHT OUTBOARD MAIN LANDING GEAR DOOR MS25083-2BB3 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-APR-2006 6598.7 4701			
528101	DOOR:LEFT NOSE LANDING GEAR DOOR 5410450-19 SN-UNKNOWN REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
528102	DOOR:RIGHT NOSE LANDING GEAR DOOR 5410450-20 SN-UNKNOWN REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
CHAPTER 53 FUSELAGE										
05-10-30-RVSM-N5313000	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (REFER TO 53-11-01) REF: AMM 53-11-01-N5313000	MOS HRS/MSC AFL	24	+14d/-14d			30-DEC-2008 7720.6 5492	30-DEC-2010	13-JAN-2011	419 d
05-11-00-E5322000	REPLACE KEELBEAM ATTACHMENT BOLTS REF:	MOS HRS/MSC AFL	144	+14d/-14d	-249		06-OCT-2009 7721.6 5493	30-JAN-2021	13-FEB-2021	4103 d 5996
531001	BULKHEAD:AFT PRESSURE BULKHEAD PN SN-UNKNOWN REF: AMM 53-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
534001	ATTACH FITTING:NO. 1 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING 6011153 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
534002	ATTACH FITTING:NO. 2 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING 6011153 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	MAX LIMIT	
534003	ATTACH FITTING:NO. 1 ENGINE AFT ENGINE MOUNT ATTACH FITTING 6011173 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
534004	ATTACH FITTING:NO. 2 ENGINE AFT ENGINE MOUNT ATTACH FITTING 6011173 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
535001	RADOME:RADOME 5410420-25 SN-UNKNOWN REF: AMM 53-50-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
CHAPTER 55 STABILIZERS										
553001	VERTICAL STABILIZER:VERTICAL STABILIZER PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
CHAPTER 56 WINDOWS										
+ 05-10-29-C5610022L	WINDSHIELD:INSPECT LEFT WINDSHIELD OPTICAL PRISM MOS HRS/MSC REF: NDT PART 4 / 56-10-01	C/C AFL					17-APR-2006 6598.7 4701			
+ 05-10-29-C5610022R	WINDSHIELD:INSPECT RIGHT WINDSHIELD OPTICAL PRISM MOS HRS/MSC REF: NDT PART 4 / 56-10-01	C/C AFL					17-APR-2006 6598.7 4701			
561001	WINDSHIELD:LEFT WINDSHIELD 6600394-1 SWU1052 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C				16-NOV-2001 4217.5 2985			
561002	WINDSHIELD:RIGHT WINDSHIELD 6600394-2 SWU-470 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
561009	WINDOW:LEFT COCKPIT CREW WINDOW 6600403-5 SWU307 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
561010	WINDOW:RIGHT COCKPIT CREW WINDOW 6600402-3 SWU-618 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2 Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
561010A	WINDOW:PRISM CHECK RIGHT COCKPIT CREW WINDOW	MOS								
	REF:	HRS/MSC AFL	C/C							
562011	WINDOW:LEFT NO. 1 CABIN WINDOW 6600405-10 3799	MOS					24-MAR-2004 5453.3			
	REF: AMM 56-20-01	HRS/MSC AFL	O/C				3927			
+ 562011A	WINDOW:PRISM CHECK LEFT NO. 1 CABIN WINDOW	MOS	05-10-29-M5600008				17-APR-2006 6598.7			
	REF: NDT PART 4 / 56-30-01	HRS/MSC AFL	C/C				4701			
562013	WINDOW:LEFT NO. 2 CABIN WINDOW LA6600405-20 1981	MOS		TSN:0			13-FEB-2008 7428.5			
	REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0			5267			
562013A	WINDOW:PRISM CHECK LEFT NO. 2 CABIN WINDOW	MOS	05-10-29-M5600008				13-FEB-2008 7428.5	8028.5	8053.5	304.3
	REF: NDT PART 4 / 56-30-01	HRS/MSC AFL	600 +25/-25		7428.5		5267			
562015	WINDOW:LEFT NO. 3 CABIN WINDOW 6600405-20 2354	MOS		TSN:0			30-DEC-2008 7720.6			
	REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0			5492			
562015A	WINDOW:PRISM CHECK LEFT NO. 3 CABIN WINDOW	MOS	05-10-29-M5600008				30-DEC-2008 7720.6	8320.6	8345.6	596.4
	REF: NDT PART 4 / 56-30-01	HRS/MSC AFL	600 +25/-25		7720.6		5492			
562017	WINDOW:LEFT NO. 4 CABIN WINDOW LA6600405-20 2582	MOS		TSN:0			01-SEP-2009 7721.6			
	REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0			5493			
562017A	WINDOW:PRISM CHECK LEFT NO. 4 CABIN WINDOW	MOS	05-10-29-M5600008				01-SEP-2009 7721.6	8321.6	8346.6	597.4
	REF: NDT PART 4 / 56-30-01	HRS/MSC AFL	600 +25/-25		7721.6		5493			
562019	WINDOW:LEFT NO. 5 CABIN WINDOW LA6600405-19 2283	MOS		TSN:0			01-SEP-2009 7721.6			
	REF: AMM 56-20-01	HRS/MSC AFL	O/C	TSN:0			5493			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
562019A	WINDOW:PRISM CHECK LEFT NO. 5 CABIN WINDOW LA6600405-20 2590 REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	600	+25/-25			01-SEP-2009 7721.6 5493	8321.6 8346.6	597.4
562022	WINDOW:RIGHT NO. 1 CABIN WINDOW LA6600405-20 2590 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-SEP-2009 7721.6 5493		
562022A	WINDOW:PRISM CHECK RIGHT NO. 1 CABIN WINDOW LA6600405-20 2590 REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	600	+25/-25			01-SEP-2009 7721.6 5493	8321.6 8346.6	597.4
562024	WINDOW:RIGHT NO. 2 CABIN WINDOW 6600405-10 4074 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C				24-MAR-2004 5453.3 3927		
562024A	WINDOW:PRISM CHECK RIGHT NO. 2 CABIN WINDOW 6600405-10 4074 REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C				17-APR-2006 6598.7 4701		
562026	WINDOW:RIGHT NO. 3 CABIN WINDOW LA6600405-20 1987 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2008 7428.5 5267		
562026A	WINDOW:PRISM CHECK RIGHT NO. 3 CABIN WINDOW LA6600405-20 1987 REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	600	+25/-25			13-FEB-2008 7428.5 5267	8028.5 8053.5	304.3
562028	WINDOW:RIGHT NO. 4 CABIN WINDOW LA6600405-20 2588 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-SEP-2009 7721.6 5493		
562028A	WINDOW:PRISM CHECK RIGHT NO. 4 CABIN WINDOW LA6600405-20 2588 REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	600	+25/-25			01-SEP-2009 7721.6 5493	8321.6 8346.6	597.4
562030	WINDOW:RIGHT NO. 5 CABIN WINDOW LA6600405-20 2587 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-SEP-2009 7721.6 5493		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2 Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	MAX LIMIT	
562030A	WINDOW:PRISM CHECK RIGHT NO. 5 CABIN WINDOW	MOS	05-10-29-M5600008							
	REF: NDT PART 4 / 56-30-01	HRS/MSC AFL	600 +25/-25		7721.6		01-SEP-2009 7721.6 5493	8321.6	8346.6	597.4
CHAPTER 57 WINGS										
+ 05-10-29-L5720012L	PERFORM LEFT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION	MOS					30-JAN-1997			
	REF: NDT PART 3 / 57-40-03	HRS/MSC AFL	10000 +25/-25				0 0	10000	10025	4503
+ 05-10-29-L5720012R	PERFORM RIGHT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION	MOS					30-JAN-1997			
	REF: NDT PART 3 / 57-40-03	HRS/MSC AFL	10000 +25/-25				0 0	10000	10025	4503
570001	WING:LEFT WING PN SN-UNKNOWN REF: AMM 57-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
570002	WING:RIGHT WING PN SN-UNKNOWN REF: AMM 57-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
572001	WINGLET ASSEMBLY:LEFT WINGLET ASSEMBLY 2822650-44 0056 REF: AMM 57-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-JUN-2002 4833 3413			
572002	WINGLET ASSEMBLY:RIGHT WINGLET ASSEMBLY 2822650-44 0056 REF: AMM 57-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			04-JUN-2002 4833 3413			
572003	LEADING EDGE:LEFT WING LEADING EDGE PN SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
572004	LEADING EDGE:RIGHT WING LEADING EDGE PN SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
572025	FITTING:LEFT FRONT WINGLET SPAR FITTING PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
572026	FITTING:RIGHT FRONT WINGLET SPAR FITTING PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
572027	FITTING:LEFT AFT WINGLET SPAR FITTING PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
572028	FITTING:RIGHT AFT WINGLET SPAR FITTING PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

CHAPTER 71		POWER PLANT								
05-11-00-E7120049L	REPLACE NO. 1 ENGINE AFT MOUNT ATTACH BOLTS	MOS					30-JAN-1997			LIFE LIMIT
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-E7120049R	REPLACE NO. 2 ENGINE AFT MOUNT ATTACH BOLTS	MOS					30-JAN-1997			LIFE LIMIT
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
05-11-00-G7110021L	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS					17-APR-2006			NOT APPLICABLE
	REF:	HRS/MSC AFL	O/C				6598.7 4701			
05-11-00-G7110021R	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS					17-APR-2006			NOT APPLICABLE
	REF:	HRS/MSC AFL	O/C				6598.7 4701			
05-11-00-G7110022L	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)	MOS					17-APR-2006			NOT APPLICABLE
	REF:	HRS/MSC AFL	O/C				6598.7 4701			
05-11-00-G7110022R	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)	MOS					17-APR-2006			NOT APPLICABLE
	REF:	HRS/MSC AFL	O/C				6598.7 4701			
05-11-00-M7120048L	REPLACE NO. 1 ENGINE FWD MOUNT ATTACH BOLTS	MOS					30-JAN-1997			LIFE LIMIT
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	MAX LIMIT	
05-11-00-M7120048R	REPLACE NO. 2 ENGINE FWD MOUNT ATTACH BOLTS	MOS					30-JAN-1997		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		12275.8
+ 710011	PERFORM MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE-AIRFRAME RELATED INSPECTION ITEMS-LEFT	MOS					16-APR-2005		ENGINE CHANGE	
	REF:	HRS/MSC AFL	DUE				5981.1 4288			
+ 710012	PERFORM MAJOR ENGINE INSPECTION/UNSCHEDULED ENGINE CHANGE AIRFRAME RELATED INSPECTION ITEMS-RIGHT	MOS					16-SEP-2005		ENGINE CHANGE	
	REF:	HRS/MSC AFL	DUE				6249.4 4477			
712001	FITTING:LEFT ENGINE FORWARD INTERMEDIATE FITTING 6011154	MOS					30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 71-20-01	AFL		TSN:0			0			
712002	FITTING:RIGHT ENGINE FORWARD INTERMEDIATE FITTING 6011154	MOS					30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 71-20-01	AFL		TSN:0			0			
712005	ISOLATOR:LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-505	MOS					30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 71-20-05	AFL		TSN:0			0			
712006	ISOLATOR:RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-505	MOS					30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 71-20-05	AFL		TSN:0			0			
712007	ISOLATOR:LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-501	MOS					30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 71-20-05	AFL		TSN:0			0			
712008	ISOLATOR:RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-501	MOS					30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 71-20-05	AFL		TSN:0			0			
712009	BEAM:NO. 1 ENGINE FORWARD BEAM 6011153	MOS					30-JAN-1997			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF:	AFL		TSN:0			0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
712010	BEAM:NO. 2 ENGINE FORWARD BEAM 6011153 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712011	BEAM:NO. 1 ENGINE AFT BEAM 6011170 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712012	BEAM:NO. 2 ENGINE AFT BEAM 6011170 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712015	LINK:LEFT ENGINE LOWER AFT MOUNT LINK 266-0807-505 SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712015	STABILIZER:NO. 1 ENGINE FORWARD STABILIZER 6011160 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712016	STABILIZER:NO.2 ENGINE FORWARD STABILIZER 6011160 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712016	LINK:RIGHT ENGINE LOWER AFT MOUNT LINK 266-0807-505 SN-UNKNOWN REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712035	YOKE:NO. 1 ENGINE FORWARD MOUNT YOKE 266-0803-501 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712036	YOKE:NO. 2 ENGINE FORWARD MOUNT YOKE 266-0803-501 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
712039	LINK:NO. 1 ENGINE AFT UPPER MOUNT LINK 266-0807-505 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
712040	LINK:NO. 2 ENGINE AFT UPPER MOUNT LINK 266-0807-505 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
712043	MOUNT:NO. 1 ENGINE FORWARD MOUNT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
712044	MOUNT:NO. 2 ENGINE FORWARD MOUNT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
712045	MOUNT:NO. 1 ENGINE AFT MOUNT RF71-02-11 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
712046	MOUNT:NO. 2 ENGINE AFT MOUNT RF71-02-11 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
712291	ISOLATOR:NO. 1 ENGINE AFT ISOLATOR 266D0820-503 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
712292	ISOLATOR:NO. 2 ENGINE AFT ISOLATOR 266D0820-503 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
71EN1 71.EN1	ENGINE:NO. 1 ENGINE 31B4067-02 PCE-CA0033 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:5453.3			31-MAR-2004 5453.3 3928			
71EN2 71.EN2	ENGINE:NO. 2 ENGINE 31B4067-02 PCE-CA0034 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:5453.3			31-MAR-2004 5453.3 3928			
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02										
+ 05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE	MOS HRS/MSC ENC	6000	+100			22-FEB-2005 5750.3 4120	(11750.3) 11980.1	11850.3	4255.9

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
+ 05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION	MOS					22-FEB-2005			
	REF:	HRS/MSC	3000	+100			5750.3	(8750.3) 8980.1	8850.3	1255.9
		ENC					4120			
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS	MOS					13-FEB-2008			
	REF:	HRS/MSC	1200				7198.7	(8398.7) 8628.5		904.3
		ENC					5107			
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR	MOS					30-DEC-2008			
	REF:	HRS/MSC	600				7490.8	(8090.8) 8320.6		596.4
		ENC					5332			
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID	MOS					30-DEC-2008			
	REF: EMM 75-30-02	HRS/MSC	1500	+300/-300			7490.8	(8990.8) 9220.6		1496.4
		ENC					5332			
05-P&W-710020	NO. 1 ENGINE - VISUALLY CHECK AND/OR REPLACE N1 SPEED SENSORS	MOS					22-FEB-2005			
	REF:	HRS/MSC	3000				5750.3	(8750.3) 8980.1		1255.9
		ENC					4120			
710000	NO. 1 ENGINE - COMPRESSOR WASH	DAYS					06-MAY-1998			
	REF:	HRS/MSC	A/R				755			
		ENC					521			
710050	NO. 1 ENGINE - RUN ENGINES	DAYS	7				02-NOV-2009	09-NOV-2009		3 d
	REF:	HRS/MSC					7494.4			
		ENC					5337			
715020	HARNESS:NO. 1 ENGINE - ENGINE WIRE HARNESS	MOS			TSN:0		22-NOV-1996			
	PN	HRS/MSC	O/C		TSN:0		0			
	SN-UNKNOWN	ENC			TSN:0		0			
	REF: EMM 73-20-03						0			
715025	ALTERNATOR:NO. 1 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR	MOS			TSN:0		22-NOV-1996			
	PN	HRS/MSC	O/C		TSN:0		0			
	SN-UNKNOWN	ENC			TSN:0		0			
	REF: EMM 72-60-01						0			
M7120068	NO. 1 ENGINE - INSPECT NO. 1 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS	MOS					16-APR-2005			
	REF:	HRS/MSC	A/R				5750.3			
		ENC					4120			

ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
+ 05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE	MOS					18-AUG-2005			
	REF:	HRS/MSC ENC	6000 +100				5981.1 4288	(11981.1)	12238.5 12081.1	4514.3
+ 05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION	MOS					18-AUG-2005			
	REF:	HRS/MSC ENC	3000 +100				5981.1 4288	(8981.1)	9238.5 9081.1	1514.3
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS	MOS					13-FEB-2008			
	REF:	HRS/MSC ENC	1200				7171.1 5076	(8371.1)	8628.5	904.3
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR	MOS					30-DEC-2008			
	REF:	HRS/MSC ENC	600				7436.2 5301	(8036.2)	8293.6	569.4
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID	MOS					30-DEC-2008			
	REF: EMM 75-30-02	HRS/MSC ENC	1500 +300/-300				7436.2 5301	(8936.2)	9193.6	1469.4
05-P&W-710020	NO. 2 ENGINE - VISUALLY CHECK AND/OR REPLACE N1 SPEED SENSORS	MOS					18-AUG-2005			
	REF:	HRS/MSC ENC	3000				5981.1 4288	(8981.1)	9238.5	1514.3
710000	NO. 2 ENGINE - COMPRESSOR WASH	DAYS					01-NOV-2001			
	REF:	HRS/MSC ENC	A/R				4217.5 2985			
710050	NO. 2 ENGINE - RUN ENGINES	DAYS	7				02-NOV-2009	09-NOV-2009		3 d
	REF:	HRS/MSC ENC					7466.8 5306			
715020	HARNESS:NO. 2 ENGINE - ENGINE WIRE HARNESS	MOS					22-NOV-1996			
	PN	HRS/MSC	O/C		TSN:0		0			
	SN-UNKNOWN	ENC			TSN:0		0			
	REF: EMM 73-20-03				TSN:0		0			
715025	ALTERNATOR:NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR	MOS					22-NOV-1996			
	PN	HRS/MSC	O/C		TSN:0		0			
	SN-UNKNOWN	ENC			TSN:0		0			
	REF: EMM 72-60-01				TSN:0		0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
M7120068	NO. 2 ENGINE - INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS	MOS					16-SEP-2005			
	REF:	HRS/MSC A/R					5981.1			
		ENC					4288			
CHAPTER 72 ENGINE										
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02										
720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION	MOS	168				22-NOV-1996		VENDOR RECOMMENDATION	381 d
	REF:	HRS/MSC -					0			
		ENC					0			
723001	HUB:NO. 1 ENGINE - FAN HUB 30B2256	MOS		TSN:0			22-NOV-1996			LIFE LIMIT
	34B475	HRS/MSC		TSN:0			0			
	REF: EMM 72-30-01	ENC	12000	TSN:0			0		12000	6663
723002	CASE ASSEMBLY:NO. 1 ENGINE - FAN CASE ASSEMBLY PN	MOS		TSN:0			22-NOV-1996			
	SN-UNKNOWN	HRS/MSC O/C		TSN:0			0			
	REF: EMM 72-30-01	ENC		TSN:0			0			
723003	IMPELLER:NO. 1 ENGINE - CENTRIFUGAL IMPELLER 30B2486	MOS		TSN:0			22-NOV-1996			LIFE LIMIT
	6F664	HRS/MSC		TSN:0			0			
	REF: EMM 72-30-01	ENC	12000	TSN:0			0		12000	6663
723004	NO. 1 ENGINE - PRESSURE CHECK IMPELLER SHROUD	MOS					22-NOV-1996			
	REF:	HRS/MSC N/A					0			
		ENC					0			
723005	ROTOR:NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B2799-01	MOS		TSN:0			22-FEB-2005			LIFE LIMIT
	TXA1A3917	HRS/MSC		TSN:0			5750.3			
	REF: EMM 72-30-01	ENC	12000	TSN:0			4120		16120	10783
723005A	ROTOR:NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR	MOS					31-OCT-2008			
	REF: EMM 72-00-00	HRS/MSC 300	+25				7490.8		(7790.8) 8020.6	296.4
		ENC					5332			
723008	ROTOR:NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B4745-01	MOS		TSN:0			22-FEB-2005			LIFE LIMIT
	55B946	HRS/MSC		TSN:0			5750.3			
	REF:	ENC	8500	TSN:0			4120		12620	7283
+ 723008A	ROTOR:NO. 1 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM	MOS					07-AUG-2004			
	REF:	HRS/MSC O/C					5585.9			
		ENC					4017			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
724010	NO. 1 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)	MOS					22-NOV-1996			
	REF:	HRS/MSC ENC	N/A				0 0			
725001	VANE-RING:NO. 1 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING	MOS		TSN:0			22-NOV-1996			
	PN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 72-50-01	ENC		TSN:0			0			
725003	CASE ASSEMBLY:NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY	MOS		TSN:0			22-NOV-1996			
	PN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 72-50-03	ENC		TSN:0			0			
725101	DISC:NO. 1 ENGINE - STAGE 1 TURBINE DISC	MOS		TSN:0			22-FEB-2005			LIFE LIMIT
	30B2981-01	HRS/MSC		TSN:0			5750.3			
	A001M72A	ENC	3100	TSN:0			4120	7220		1883
725102	DISC:NO. 1 ENGINE - STAGE 2 TURBINE DISC	MOS		TSN:0			22-FEB-2005			LIFE LIMIT
	30B2912-01	HRS/MSC		TSN:0			5750.3			
	A001MHFM	ENC	3300	TSN:0			4120	7420		2083
725103	DISC:NO. 1 ENGINE - STAGE 3 TURBINE DISC	MOS		TSN:0			22-NOV-1996			LIFE LIMIT
	30A1102	HRS/MSC		TSN:0			0			
	11B316	ENC	7500	TSN:0			0	7500		2163
725104	DISC:NO. 1 ENGINE - STAGE 4 TURBINE DISC	MOS		TSN:0			22-NOV-1996			LIFE LIMIT
	30A1565	HRS/MSC		TSN:0			0			
	50A157	ENC	7500	TSN:0			0	7500		2163
725105	DISC:NO. 1 ENGINE - STAGE 5 TURBINE DISC	MOS		TSN:0			22-NOV-1996			LIFE LIMIT
	30A1104	HRS/MSC		TSN:0			0			
	11B094	ENC	7500	TSN:0			0	7500		2163
725107	COVER:NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER	MOS		TSN:0			24-OCT-2001			LIFE LIMIT
	30B2748-01	HRS/MSC		TSN:0			4217.2			
	A000YFC4	ENC	4800	TSN:0			2985	7785		2448
725109	COVER:NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER	MOS		TSN:0			24-OCT-2001			LIFE LIMIT
	30B2747-01	HRS/MSC		TSN:0			4217.2			
	A000YCF2	ENC	4400	TSN:0			2985	7385		2048

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
725111	SEAL:NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 WG001138 REF: EMM 72-50-01	MOS HRS/MSC ENC	4000	TSN:0 TSN:0 TSN:0		24-OCT-2001 4217.2 2985		6985	LIFE LIMIT 1648
726001	HOUSING:NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING 31B5065-01 9H279 REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0		22-NOV-1996 0 0			
727001	LINER:NO. 1 ENGINE - COMBUSTION CHAMBER LINER PN SN-UNKNOWN REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0		22-NOV-1996 0 0			
727001A	LINER:NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER LINER MOS HRS/MSC ENC REF: EMM 72-40-01	MOS HRS/MSC ENC	3000			22-FEB-2005 5750.3 4120	(8750.3)	8980.1	1255.9
727002	LINER ASSEMBLY:NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY 30B4561-01 A001LNOH REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0		22-FEB-2005 5750.3 4120			
727003	LINER ASSEMBLY:NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY 30B4562-01 A001LTRE REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0		22-FEB-2005 5750.3 4120			
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02									
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION	MOS HRS/MSC ENC	168 -			22-NOV-1996 0 0	VENDOR RECOMMENDATION 22-NOV-2010		381 d
723001	HUB:NO. 2 ENGINE - FAN HUB 30B2256 34B477 REF: EMM 72-30-01	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0		22-NOV-1996 0 0		12000	LIFE LIMIT 6694
723002	CASE ASSEMBLY:NO. 2 ENGINE - FAN CASE ASSEMBLY PN SN-UNKNOWN REF: EMM 72-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0		22-NOV-1996 0 0			
723003	IMPELLER:NO. 2 ENGINE - CENTRIFUGAL IMPELLER 30B2486 6F662 REF: EMM 72-30-01	MOS HRS/MSC ENC	12000	TSN:0 TSN:0 TSN:0		22-NOV-1996 0 0		12000	LIFE LIMIT 6694

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
723004	NO. 2 ENGINE - PRESSURE CHECK IMPELLER SHROUD	MOS					22-NOV-1996			
	REF:	HRS/MSC ENC	N/A				0 0			
723005	ROTOR:NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR	MOS					22-NOV-1996			LIFE LIMIT
	30B2260	HRS/MSC		TSN:0			0			
	35B349	ENC	12000	TSN:0			0	12000		6694
723005A	ROTOR:NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR	MOS					31-OCT-2008			
	REF: EMM 72-30-01	HRS/MSC ENC	300	+25			7436.2 5301	(7736.2)	7993.6	269.4
723008	ROTOR:NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR	MOS					18-AUG-2005			LIFE LIMIT
	30B4745-01	HRS/MSC		TSN:0			5981.1			
	55B955	ENC	8500	TSN:0			4288	12788		7482
+ 723008A	ROTOR:NO. 2 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM	MOS					18-AUG-2005			
	REF:	HRS/MSC ENC	O/C				5981.1 4288			
724010	NO. 2 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM)	MOS					22-NOV-1996			
	REF:	HRS/MSC ENC	N/A				0 0			
725001	VANE-RING:NO. 2 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING	MOS					22-NOV-1996			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	ENC		TSN:0			0			
	REF: EMM 72-50-01			TSN:0						
725003	CASE ASSEMBLY:NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY	MOS					22-NOV-1996			
	PN	HRS/MSC	O/C	TSN:0			0			
	SN-UNKNOWN	ENC		TSN:0			0			
	REF: EMM 72-50-03			TSN:0						
725101	DISC:NO. 2 ENGINE - STAGE 1 TURBINE DISC	MOS					18-AUG-2005			LIFE LIMIT
	30B2981-01	HRS/MSC		TSN:0			5981.1			
	A001R3R6	ENC	3100	TSN:0			4288	7388		2082
	REF: EMM 72-50-01			TSN:0						
725102	DISC:NO. 2 ENGINE - STAGE 2 TURBINE DISC	MOS					18-AUG-2005			LIFE LIMIT
	30B2912-01	HRS/MSC		TSN:0			5981.1			
	A001R0P9	ENC	3300	TSN:0			4288	7588		2282
	REF: EMM 72-50-01			TSN:0						

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
725103	DISC:NO. 2 ENGINE - STAGE 3 TURBINE DISC 30A1102 11B318 REF: EMM 72-50-01	MOS HRS/MSC ENC	7500	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0	7500		LIFE LIMIT 2194
725104	DISC:NO. 2 ENGINE - STAGE 4 TURBINE DISC 30A1565 50A155 REF: EMM 72-50-01	MOS HRS/MSC ENC	7500	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0	7500		LIFE LIMIT 2194
725105	DISC:NO. 2 ENGINE - STAGE 5 TURBINE DISC 30A1104 11B101 REF: EMM 72-50-01	MOS HRS/MSC ENC	7500	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0	7500		LIFE LIMIT 2194
725107	COVER:NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A000YCFE REF: EMM 72-50-01	MOS HRS/MSC ENC	4800	TSN:0 TSN:0 TSN:0			24-OCT-2001 4217.2 2985	7785		LIFE LIMIT 2479
725109	COVER:NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B2747-01 A000YCEW REF: EMM 72-50-01	MOS HRS/MSC ENC	4400	TSN:0 TSN:0 TSN:0			24-OCT-2001 4217.2 2985	7385		LIFE LIMIT 2079
725111	SEAL:NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 WG001139 REF: EMM 72-50-01	MOS HRS/MSC ENC	4000	TSN:0 TSN:0 TSN:0			24-OCT-2001 4217.2 2985	6985		LIFE LIMIT 1679
726001	HOUSING:NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING 31B5065-01 9H575 REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
727001	LINER:NO. 2 ENGINE - COMBUSTION CHAMBER LINER PN SN-UNKNOWN REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288			
727001A	LINER:NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER LINER MOS HRS/MSC REF: EMM 72-40-01	MOS HRS/MSC ENC	3000				18-AUG-2005 5981.1 4288	(8981.1) 9238.5		1514.3
727002	LINER ASSEMBLY:NO. 2 ENGINE - INNER COMBUSTION LINER ASSEMBLY 30B4561-01 A001PNFR REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
727003	LINER ASSEMBLY:NO. 2 ENGINE - OUTER COMBUSTION LINER ASSEMBLY 30B6146-01 A001PT60 REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288		
CHAPTER 73 ENGINE FUEL AND CONTROL									
731055	CABLE:NO. 1 ENGINE EMERGENCY FUEL SHUTOFF CABLE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
731056	CABLE:NO. 2 ENGINE EMERGENCY FUEL SHUTOFF CABLE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
733101	TRANSMITTER:LEFT ENGINE FUEL FLOW TRANSMITTER 5/8-1-81-503 SN-UNKNOWN REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
733102	TRANSMITTER:RIGHT ENGINE FUEL FLOW TRANSMITTER 5/8-1-81-503 SN-UNKNOWN REF: AMM 73-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
733103	INDICATOR:LEFT ENGINE FUEL FLOW INDICATOR 62000-002 148 REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493		
733104	INDICATOR:RIGHT ENGINE FUEL FLOW INDICATOR 62000-002 3585 REF: AMM 73-31-02	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			06-OCT-2009 7721.6 5493		
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02									
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT MOS HRS/MSC REF:	12 1200 ENC					30-DEC-2008 7490.8 5332	30-DEC-2009 (8690.8) 8920.6	54 d 1196.4
731001	PUMP:NO. 1 ENGINE - FUEL PUMP 30B1910A SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
731002	VALVE:NO. 1 ENGINE - MOTIVE FLOW VALVE PN SN-UNKNOWN REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
731003	SWITCH:NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH PN SN-UNKNOWN REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
731004	FUEL NOZZLE:NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE PN SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
731005	FUEL NOZZLE:NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE PN SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
731010	VALVE ASSEMBLY:NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY 30B1727 SN-UNKNOWN REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
731026	EJECTOR:NO. 1 ENGINE - FUEL WASTE EJECTOR 26100-8 0325 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			14-OCT-2004		
731051	VALVE:NO. 1 ENGINE - FUEL START & DUMP VALVE 26240-5 0373 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			14-OCT-2004		
732001	FUEL CONTROL:NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL 31B4469-04 1891384 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
732003	HARNES:NO. 1 ENGINE - ELECTRICAL FRONT HARNES PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
732004	HARNES:NO. 1 ENGINE - ELECTRICAL REAR HARNES PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
732101	FADEC:NO. 1 ENGINE - ENGINE FADEC PN-UNKNOWN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C				24-JUN-2004		

ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION	NEXT DUE		TIME REMAINING
							COMPLIANCE (ENH)	ACTUAL	MAX LIMIT	
05-P&W-730001	NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT	MOS	12				30-DEC-2008	30-DEC-2009		54 d
	REF:	HRS/MSC	1200				7463.2	(8663.2) 8920.6		1196.4
	ENC	ENC					5301			
731001	PUMP:NO. 2 ENGINE - FUEL PUMP PF4-038-11C	MOS					22-NOV-2000			
	MX-519131A	HRS/MSC	O/C				3373			
	REF: EMM 73-10-02	ENC					2386			
731002	VALVE:NO. 2 ENGINE - MOTIVE FLOW VALVE PN	MOS		TSN:0			22-NOV-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 73-20-01	ENC		TSN:0			0			
731003	SWITCH:NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH PN	MOS		TSN:0			22-NOV-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 73-10-03	ENC		TSN:0			0			
731004	FUEL NOZZLE:NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE PN	MOS		TSN:0			22-NOV-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 73-10-04	ENC		TSN:0			0			
731005	FUEL NOZZLE:NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE PN	MOS		TSN:0			22-NOV-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 73-10-04	ENC		TSN:0			0			
731010	VALVE ASSEMBLY:NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY 30B1727	MOS		TSN:0			22-NOV-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: EMM 73-10-05	ENC		TSN:0			0			
731026	EJECTOR:NO. 2 ENGINE - FUEL WASTE EJECTOR 26100-8	MOS		TSO:0			18-AUG-2005			
	056	HRS/MSC	O/C	TSO:0			5981.1			
	REF: EMM 73-10-03	ENC		TSO:0			4288			
731051	VALVE:NO. 2 ENGINE - FUEL START & DUMP VALVE 26240-5	MOS		TSO:0			18-AUG-2005			
	0639	HRS/MSC	O/C	TSO:0			5981.1			
	REF: EMM 73-10-05	ENC		TSO:0			4288			
732001	FUEL CONTROL:NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL 1891-11	MOS		TSO:0			22-NOV-2000			
	1891422	HRS/MSC	O/C	TSO:0			3373			
	REF: EMM 73-20-01	ENC		TSO:0			2386			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
732003	HARNES: NO. 2 ENGINE - ELECTRICAL FRONT HARNES PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
732004	HARNES: NO. 2 ENGINE - ELECTRICAL REAR HARNES PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
732101	FADEC: NO. 2 ENGINE - ENGINE FADEC PN-UNKNOWN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C				24-JUN-2004		
CHAPTER 74 IGNITION									
743003	BOX: ENGINE WARNING LIGHT BOX 6018314-3 SN-UNKNOWN REF: AMM 74-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02									
741001	EXCITER: NO. 1 ENGINE - NO. 1 IGNITION EXCITER 31B4636-02 NN96280202 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
741002	EXCITER: NO. 1 ENGINE - NO. 2 IGNITION EXCITER 31B4636-02 NN96373655 REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
742025	PLUG: NO. 1 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2008 7198.7 5107		
742026	PLUG: NO. 1 ENGINE - NO. 2 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2008 7198.7 5107		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02									
741001	EXCITER: NO. 2 ENGINE - NO. 1 IGNITION EXCITER 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				25-FEB-2002 4529.1 3195		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
741002	EXCITER:NO. 2 ENGINE - NO. 2 IGNITION EXCITER 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C				29-JUN-2000 2978 2098		
742025	PLUG:NO. 2 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2008 7171.1 5076		
742026	PLUG:NO. 2 ENGINE - NO. 2 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-FEB-2008 7171.1 5076		

CHAPTER 75

AIR

ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02

05-P&W-750001	NO. 1 ENGINE - INSPECT AND CLEAN P2.5 & P2.8 BLEED VALVES MOS HRS/MSC ENC REF:	3000					22-FEB-2005 5750.3 4120	(8750.3) 8980.1	1255.9
751001	VALVE:NO. 1 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-02 AL2 REF: EMM 75-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
753004	ACTUATOR:NO. 1 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
753005	ACTUATOR:NO. 1 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR 30B1782 SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
753081	SOLENOID:NO. 1 ENGINE - COMPRESSOR BLEED VALVE SOLENOID 31B4197-04 1598 REF: EMM 75-30-02	MOS HRS/MSC ENC	3000	TSO:0 TSO:0 TSO:0			31-OCT-2008 7490.8 5332	(10490.8) 10720.6	2996.4
753101	VALVE:NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 22A980 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-FEB-2005 5750.3 4120		
753102	VALVE:NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 14A523 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-FEB-2005 5750.3 4120		

?-Insufficient Information
(EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
753105	VALVE:NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 22A019 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-FEB-2005 5750.3 4120		
754001	TRANSDUCER:NO. 1 ENGINE - PRESSURE P3 TRANSDUCER PN SN-UNKNOWN REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02									
05-P&W-750001	NO. 2 ENGINE - INSPECT AND CLEAN P2.5 & P2.8 BLEED VALVES MOS HRS/MSC 3000 REF:						18-AUG-2005 5981.1 4288	(8981.1) 9238.5	1514.3
751001	VALVE:NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-01 7Y106 REF: EMM 75-10-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			21-JUN-1998		
753004	ACTUATOR:NO. 2 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR PN SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
753005	ACTUATOR:NO. 2 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR 31B5255-01 2600091 REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
753081	SOLENOID:NO. 2 ENGINE - COMPRESSOR BLEED VALVE SOLENOID 31B4197-04 991 REF: EMM 75-30-02	MOS HRS/MSC ENC	3000	TSO:0 TSO:0 TSO:0			31-OCT-2008 7436.2 5301	(10436.2) 10693.6	2969.4
753101	VALVE:NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 20A703 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288		
753102	VALVE:NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 20A704 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288		
753105	VALVE:NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 37A422 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
754001	TRANSDUCER:NO. 2 ENGINE - PRESSURE P3 TRANSDUCER PN SN-UNKNOWN REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
CHAPTER 76 ENGINE CONTROLS										
761001	QUADRANT ASSEMBLY:THROTTLE/THRUST REVERSER QUADRANT ASSEMBLY 6015201-3 SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
761003	TRANSFORMER:LEFT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER 3A2-240B SN-UNKNOWN REF: AMM 76-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
761004	TRANSFORMER:RIGHT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER 3A2-240A SN-UNKNOWN REF: AMM 76-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02										
761101	HARNESS:NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
761103	HARNESS:NO. 1 ENGINE - FADEC, ENGINE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
761105	HARNESS:NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
761107	HARNESS:NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02										
761101	HARNESS:NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
761103	HARNES: NO. 2 ENGINE - FADEC, ENGINE HARNES PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
761105	HARNES: NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNES PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
761107	HARNES: NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNES PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
CHAPTER 77 ENGINE INDICATING										
771001	INDICATOR: LEFT ENGINE N1 INDICATOR 6608496-001 1637 REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C				07-MAY-1999 1862.5 1286			
771002	INDICATOR: RIGHT ENGINE N1 INDICATOR 64500-001 2018 REF: AMM 77-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
771003	INDICATOR: LEFT ENGINE N2 INDICATOR 64000-001 SN-UNKNOWN REF: AMM 77-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
771004	INDICATOR: RIGHT ENGINE N2 INDICATOR 64000-001 SN-UNKNOWN REF: AMM 77-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
772001	INDICATOR: LEFT ENGINE ITT INDICATOR 61500-001 SN-UNKNOWN REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
772002	INDICATOR: RIGHT ENGINE ITT INDICATOR 6608505-001 3757 REF: AMM 77-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-SEP-2000 3421.5 2279			
772011	BOX: NO. 1 ENGINE N1/T4.5 TERMINAL BOX 30B1385 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
772012	BOX:NO. 2 ENGINE N1/T4.5 TERMINAL BOX 30B1385 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
772013	HARNES: NO. 1 ENGINE LEFT T4.5 WIRING HARNESS 30B2749-02 EM4393044 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
772014	HARNES: NO. 2 ENGINE LEFT T4.5 WIRING HARNESS 30B2749-02 EM4393046 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
772015	HARNES: NO. 1 ENGINE RIGHT T4.5 WIRING HARNESS 30B2749-02 EM4393053 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
772016	HARNES: NO. 2 ENGINE RIGHT T4.5 WIRING HARNESS 30B2749-02 EM4393065 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
774001	DIAGNOSTIC UNIT:ENGINE DIAGNOSTIC UNIT 9-361-06 F135 REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			27-SEP-2007 7264		
774002	UNIT:CONTROL AND DISPLAY (CDU) UNIT PN SN-UNKNOWN REF: AMM 77-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
774003	UNIT:LEFT ENGINE ISOLATION INTERFACE UNIT 9-343-01 SN-UNKNOWN REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
774004	UNIT:RIGHT ENGINE ISOLATION INTERFACE UNIT 9-343-01 SN-UNKNOWN REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
774101	BOX:SIGNAL CONDITIONING BOX 6600504-3 SN-UNKNOWN REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
774103	ACCELEROMETER:LEFT ENGINE VIBRATION ACCELEROMETER 6600504-2 SN-UNKNOWN REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
774104	ACCELEROMETER:RIGHT ENGINE VIBRATION ACCELEROMETER 6600504-2 SN-UNKNOWN REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02									
771027	SENSOR:NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR 31B4916-01 B004 REF: EMM 77-10-01	MOS HRS/MSC ENC	A/R	TSN:0 TSN:0 TSN:0			22-JUN-2007 6888.3 4895		
771028	SENSOR:NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR 31B4915-01 31B4916-01 REF: EMM 77-10-01	MOS HRS/MSC ENC	A/R	TSN:0 TSN:0 TSN:0			22-FEB-2005 5750.3 4120		
771040	SENSOR:NO. 1 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449 CH1012 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-FEB-2005 5750.3 4120		
771041	SENSOR:NO. 1 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449 CH1017 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-FEB-2005 5750.3 4120		
772010	HARNES:NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNES PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
772014	SENSOR:NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
772015	SENSOR:NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02									
771027	SENSOR:NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR 31B4916-01 B004 REF: EMM 77-10-01	MOS HRS/MSC ENC	3000	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288	(8981.1) 9238.5	1514.3

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
771028	SENSOR:NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR 30B6152-04 SN-UNKNOWN REF: EMM 77-10-01	MOS HRS/MSC ENC	3000	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288	(8981.1)	9238.5	1514.3
771040	SENSOR:NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449 CH1016 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-AUG-2005 5981.1 4288			
771041	SENSOR:NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449 CH1019 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C				18-AUG-2005 5981.1 4288			
772010	HARNES: NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNES PN SN-UNKNOWN REF: EMM 77-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
772014	SENSOR:NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
772015	SENSOR:NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0			
CHAPTER 78 EXHAUST										
+ 05-10-29-D7830036L	VISUAL INSPECTION THRUST REVERSER GUIDE ROD BUSHINGS (REFER TO 78-30-00)	MOS HRS/MSC AFL	O/C				16-NOV-2001 4217.4 2985			
+ 05-10-29-D7830036R	VISUAL INSPECTION THRUST REVERSER GUIDE ROD BUSHINGS (REFER TO 78-30-00)	MOS HRS/MSC AFL	O/C				16-NOV-2001 4217.4 2985			
780001	THRUST REVERSER:LEFT THRUST REVERSER 282-0052-519 901030-052 REF:	MOS HRS/MSC AFL	O/C				19-OCT-2008 7715.2 5489			
780002	THRUST REVERSER:RIGHT THRUST REVERSER 282-0052-511 248 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-DEC-2008 7720.6 5492			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
783001	RELAY BOX:LEFT THRUST REVERSER RELAY BOX 6018425-017 1730602 REF: AMM 78-30-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-JUN-2004 5510.7 3968			
783002	RELAY BOX:RIGHT THRUST REVERSER RELAY BOX 6018425-017 A00433347-01(A) REF: AMM 78-30-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			03-APR-2007			
783005	CONTROL UNIT:LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT 71335-3 0427 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C				30-NOV-2007 7345.4 5204			
783006	CONTROL UNIT:RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-507 0139 REF: AMM 78-30-03	MOS HRS/MSC AFL	O/C				26-JAN-2005 5830.6			
783013	DOOR:LEFT ENGINE THRUST REVERSER UPPER DOOR 266-0003-503 SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783014	DOOR:RIGHT ENGINE THRUST REVERSER UPPER DOOR 266-0003-503 SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783015	DOOR:LEFT ENGINE THRUST REVERSER LOWER DOOR 266-0004-504 SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783016	DOOR:RIGHT ENGINE THRUST REVERSER LOWER DOOR 266-0004-504 SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783105	ACTUATOR:LEFT OUTBOARD THRUST REVERSER ACTUATOR 71334 0673R REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-SEP-2000 3215.1 2264			
783106	ACTUATOR:LEFT INBOARD THRUST REVERSER ACTUATOR 282T0006-501 SN-UNKNOWN REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
783107	ACTUATOR:RIGHT INBOARD THRUST REVERSER ACTUATOR 282T0006-501 SN-UNKNOWN REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783108	ACTUATOR:RIGHT OUTBOARD THRUST REVERSER ACTUATOR 282T0006-501 SN-UNKNOWN REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783115	ACTUATOR:LEFT UPPER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783116	ACTUATOR:RIGHT UPPER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783117	ACTUATOR:LEFT LOWER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
783118	ACTUATOR:RIGHT LOWER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0			
E7830010A (s)	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION PKG 1 REF:	MOS HRS/MSC AFL	E/C				PKG 16-APR-2005 5981.1 4288			ENGINE CHANGE
E7830010B (s)	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION PKG 2 REF:	MOS HRS/MSC AFL	E/C				PKG 16-SEP-2005 6249.4 4477			ENGINE CHANGE
E7830012A (s)	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE PKG 1 REF:	MOS HRS/MSC AFL	E/C				PKG 16-APR-2005 5981.1 4288			ENGINE CHANGE
E7830012B (s)	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE PKG 2 REF:	MOS HRS/MSC AFL	E/C				PKG 16-SEP-2005 6249.4 4477			ENGINE CHANGE

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
CHAPTER 79 OIL									
793001	INDICATOR:LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR 6608499-001 2055 REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C				22-DEC-1997 364.5 266		
793002	INDICATOR:RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR 6608499-001 112 REF: AMM 79-30-01	MOS HRS/MSC AFL	O/C				27-DEC-1999 2452.3 1714		
793003	TRANSDUCER:LEFT ENGINE OIL PRESSURE TRANSDUCER 7600019-1 SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
793004	TRANSDUCER:RIGHT ENGINE OIL PRESSURE TRANSDUCER 7600019-1 SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
793005	BULB:LEFT ENGINE OIL TEMPERATURE BULB MS28034-3 74362 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-JUN-1999 1938 1352		
793006	BULB:RIGHT ENGINE OIL TEMPERATURE BULB MS28034-3 SN-UNKNOWN REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-CA0033 Part # 31B4067-02									
05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT MOS HRS/MSC ENC REF:	12 1200					30-DEC-2008 7490.8 5332	30-DEC-2009 (8690.8) 8920.6	54 d 1196.4
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE MOS HRS/MSC ENC REF:	12 600	+50/-50				30-DEC-2008 7490.8 5332	30-DEC-2009 (8090.8) 8320.6	8140.8 54 d 596.4
792001	PUMP:NO. 1 ENGINE - OIL PUMP 30B4858-01 24A138 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			14-OCT-2004		
792002	HEAT EXCHANGER:NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
792005	SWITCH:NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH PN SN-UNKNOWN REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
792010	SWITCH:NO. 1 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH 695-6-24 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
792020	HOUSING:NO. 1 ENGINE - OIL PUMP HOUSING PN SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
793005	DETECTOR:NO. 1 ENGINE - CHIP DETECTOR PN SN-UNKNOWN REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-CA0034 Part # 31B4067-02									
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT MOS HRS/MSC REF:	12 1200 ENC					17-MAR-2009 7209.7 5105	17-MAR-2010 (8409.7) 8667.1	131 d 942.9
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE MOS HRS/MSC REF:	12 600 ENC	+50/-50				30-DEC-2008 7436.2 5301	30-DEC-2009 (8036.2) 8293.6	8086.2 54 d 569.4
792001	PUMP:NO. 2 ENGINE - OIL PUMP 31B6168-01 24A139 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
792002	HEAT EXCHANGER:NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
792005	SWITCH:NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH PN SN-UNKNOWN REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
792010	SWITCH:NO. 2 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH 695-6-24 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 098 A/C Reg. #: N797PA

Aircraft HRS: 7724.2

Landings: 5497

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
792020	HOUSING:NO. 2 ENGINE - OIL PUMP HOUSING PN SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
793005	DETECTOR:NO. 2 ENGINE - CHIP DETECTOR PN SN-UNKNOWN REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			22-NOV-1996 0 0		
CHAPTER 80									
STARTING									
801001	RELAY BOX:CROSS START RELAY BOX 6018421-1 SN-UNKNOWN REF: AMM 80-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		
801002	RELAY BOX:AIR START RELAY BOX 6018358-2 SN-UNKNOWN REF: AMM 80-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JAN-1997 0 0		