

OWNER: AIR RESOURCE GROUP
ADDRESS: BOX 3874
 LITTLE ROCK AR 72203
PHONE: 501-219-4690
FAX:

OPERATOR: AIR RESOURCE GROUP
ADDRESS: BOX 3874
 LITTLE ROCK AR 72203
PHONE: 501-219-4690
FAX:

ANALYST: JONATHAN RAMON
EMAIL: JRAMON@CAMPSYSTEMS.COM

1-866-581-2267 (OFFICE)
 316-462-2442 (FAX)
 WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
 631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

AIRCRAFT SERIAL/REGNO: 60 076/N494PA **MODEL:** LEARJET 60 (CIMMS) **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	01-FEB-1996	8012.3 A/C HRS	as of 04-NOV-2009	A/C HRS	as of ___/___/___
		5606 AFL	as of 04-NOV-2009	AFL	as of ___/___/___
		2832.8 ACH	as of 14-SEP-2009	ACH	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: PCE-305272/31B4067-02 **MODEL:** PW 305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 19-FEB-1996		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	7842.6 ENG. HRS	as of 04-NOV-2009	ENG. HRS	as of ___/___/___
0 ENC		5450 ENC	as of 04-NOV-2009	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: PCE-305273/31B4067-02 **MODEL:** PW 305A **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 01-FEB-1996		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	7842.6 ENG. HRS	as of 04-NOV-2009	ENG. HRS	as of ___/___/___
0 ENC		5450 ENC	as of 04-NOV-2009	ENC	as of ___/___/___

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Work Packages

Aircraft HRS: 8012.3 Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	COMPLIANCE	DISPOSITION	TIME
WORKCARD	PKG #			ADJ WARR EXP	NEXT DUE	REMAINING
					ACTUAL MAXLIMIT	
CHAPTER 70 STANDARD PRACTICES - ENGINES						
700010	LEFT ENGINE CHANGE INSPECTION-AIRFRAME ITEMS PKG 1	MOS HRS/MSC E/C			11-AUG-2004 6276.7	ENGINE CHANGE
	REF:	AFL			4299	
700020	RIGHT ENGINE CHANGE INSPECTION-AIRFRAME ITEMS PKG 2	MOS HRS/MSC E/C			11-AUG-2004 6276.7	ENGINE CHANGE
	REF:	AFL			4299	

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
CHAPTER 05									
TIME LIMITS/MAINTENANCE CHECKS									
+ 05-10-01-A1	PERFORM PHASE A1-300 HOUR	MOS	12	+14d/-14d	-69	07-APR-2009	28-JAN-2010	11-FEB-2010	83 d
	REF: AMM 5-10-01	HRS/MSC	300	+25/-25		7943.3	8243.3	8268.3	231
		AFL				5534			
+ 05-10-02-A2	PERFORM PHASE A2-300 HOUR	MOS	12	+14d/-14d	-69	07-APR-2009	28-JAN-2010	11-FEB-2010	83 d
	REF: AMM 5-10-02	HRS/MSC	300	+25/-25		7943.3	8243.3	8268.3	231
		AFL				5534			
+ 05-10-03-A3	PERFORM PHASE A3-300 HOUR	MOS	12	+14d/-14d	-69	07-APR-2009	28-JAN-2010	11-FEB-2010	83 d
	REF: AMM 5-10-03	HRS/MSC	300	+25/-25		7943.3	8243.3	8268.3	231
		AFL				5534			
+ 05-10-04-A4	PERFORM PHASE A4-300 HOUR	MOS	12	+14d/-14d	-69	07-APR-2009	28-JAN-2010	11-FEB-2010	83 d
	REF: AMM 5-10-04	HRS/MSC	300	+25/-25		7943.3	8243.3	8268.3	231
		AFL				5534			
+ 05-10-05-A5	PERFORM PHASE A5-300 HOUR	MOS	12	+14d/-14d	-69	07-APR-2009	28-JAN-2010	11-FEB-2010	83 d
	REF: AMM 5-10-05	HRS/MSC	300	+25/-25		7943.3	8243.3	8268.3	231
		AFL				5534			
+ 05-10-06-A6	PERFORM PHASE A6-300 HOUR	MOS	12	+14d/-14d	-69	07-APR-2009	28-JAN-2010	11-FEB-2010	83 d
	REF: AMM 5-10-06	HRS/MSC	300	+25/-25		7943.3	8243.3	8268.3	231
		AFL				5534			
+ 05-10-07-B1	PERFORM PHASE B1-600 HOUR	MOS	24	+14d/-14d		07-APR-2009	07-APR-2011	21-APR-2011	517 d
	REF: AMM 5-10-07	HRS/MSC	600	+25/-25		7943.3	8543.3	8568.3	531
		AFL				5534			
+ 05-10-08-B2	PERFORM PHASE B2-600 HOUR	MOS	24	+14d/-14d		07-APR-2009	07-APR-2011	21-APR-2011	517 d
	REF: AMM 5-10-08	HRS/MSC	600	+25/-25		7943.3	8543.3	8568.3	531
		AFL				5534			
+ 05-10-09-B3	PERFORM PHASE B3-600 HOUR	MOS	24	+14d/-14d		07-APR-2009	07-APR-2011	21-APR-2011	517 d
	REF: AMM 5-10-09	HRS/MSC	600	+25/-25		7943.3	8543.3	8568.3	531
		AFL				5534			
+ 05-10-10-B4	PERFORM PHASE B4-600 HOUR	MOS	24	+14d/-14d		07-APR-2009	07-APR-2011	21-APR-2011	517 d
	REF: AMM 5-10-10	HRS/MSC	600	+25/-25		7943.3	8543.3	8568.3	531
		AFL				5534			
+ 05-10-11-B5	PERFORM PHASE B5-600 HOUR	MOS	24	+14d/-14d		07-APR-2009	07-APR-2011	21-APR-2011	517 d
	REF: AMM 5-10-11	HRS/MSC	600	+25/-25		7943.3	8543.3	8568.3	531
		AFL				5534			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
+ 05-10-12-B6	PERFORM PHASE B6-600 HOUR	MOS HRS/MSC AFL	24 600	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2011 8543.3 8568.3	21-APR-2011 517 d 531
	REF: AMM 5-10-12								
+ 05-10-13-C1	PERFORM PHASE C1-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2013 9147.5 9172.5	21-APR-2013 1248 d 1135.2
	REF: AMM 5-10-13				4.2				
+ 05-10-14-C2	PERFORM PHASE C2-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2013 9147.5 9172.5	21-APR-2013 1248 d 1135.2
	REF: AMM 5-10-14				4.2				
+ 05-10-15-C3	PERFORM PHASE C3-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2013 9147.5 9172.5	21-APR-2013 1248 d 1135.2
	REF: AMM 5-10-15				4.2				
+ 05-10-16-C4	PERFORM PHASE C4-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2013 9147.5 9172.5	21-APR-2013 1248 d 1135.2
	REF: AMM 5-10-16				4.2				
+ 05-10-17-C5	PERFORM PHASE C5-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2013 9147.5 9172.5	21-APR-2013 1248 d 1135.2
	REF: AMM 5-10-17				4.2				
+ 05-10-18-C6	PERFORM PHASE C6-1200 HOUR	MOS HRS/MSC AFL	48 1200	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2013 9147.5 9172.5	21-APR-2013 1248 d 1135.2
	REF: AMM 5-10-18				4.2				
+ 05-10-19-D1	PERFORM PHASE D1-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2017 10353.5 10378.5	21-APR-2017 2709 d 2341.2
	REF: AMM 5-10-19				10.2				
+ 05-10-20-D2	PERFORM PHASE D2-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2017 10353.5 10378.5	21-APR-2017 2709 d 2341.2
	REF: AMM 5-10-20				10.2				
+ 05-10-21-D3	PERFORM PHASE D3-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2017 10353.5 10378.5	21-APR-2017 2709 d 2341.2
	REF: AMM 5-10-21				10.2				
+ 05-10-22-D4	PERFORM PHASE D4-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2017 10353.5 10378.5	21-APR-2017 2709 d 2341.2
	REF: AMM 5-10-22				10.2				
+ 05-10-23-D5	PERFORM PHASE D5-2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2017 10353.5 10378.5	21-APR-2017 2709 d 2341.2
	REF: AMM 5-10-23				10.2				

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
+ 05-10-24-D6	PERFORM PHASE D6 2400 HOUR	MOS HRS/MSC AFL	96 2400	+14d/-14d +25/-25			07-APR-2009 7943.3 5534	07-APR-2017 10353.5	21-APR-2017 10378.5	2709 d 2341.2
	REF: AMM 5-10-24				10.2					
+ 05-10-25-3000 LDG	INSPECT 3000 LANDING	MOS HRS/MSC AFL					31-JAN-2001 4386.8 2931		5931 5956	325
	REF: AMM 5-10-25		3000	+25/-25						
+ 05-10-26-6000 LDG	INSPECT MAJOR LANDING GEAR	MOS HRS/MSC AFL							6000 6025	394
	REF: AMM 5-10-26		6000	+25/-25		0				
+ 05-10-27-12 YR	INSPECT 12 YEAR AIRFRAME	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			20-MAY-2008 7822.4 5441	20-MAY-2020 11441	03-JUN-2020 11466	3848 d 5835
	REF: AMM 5-10-27									
+ 05-10-28-12000 HR	INSPECT 12000 HOUR AIRFRAME	MOS HRS/MSC AFL	12000	+25/-25			01-FEB-1996 0 0	12000	12025	3987.7
	REF: AMM 5-10-28									
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02										
05-P&W-730005	NO. 1 ENGINE - CLEAN PRIMARY FUEL NOZZLES	MOS HRS/MSC ENC	1800				13-JUL-2004 6090.3 4124	(7890.3) 8060		47.7
	REF:									
052000	NO. 1 ENGINE - MINOR INSPECTION ITEMS	MOS HRS/MSC ENC	300				07-APR-2009 7773.6 5378	(8073.6) 8243.3		231
	REF:									
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02										
05-P&W-730005	NO. 2 ENGINE - CLEAN PRIMARY FUEL NOZZLES	MOS HRS/MSC ENC	1800				19-JUL-2004 6090.3 4124	(7890.3) 8060		47.7
	REF:									
052000	NO. 2 ENGINE - MINOR INSPECTION ITEMS	MOS HRS/MSC ENC	300				07-APR-2009 7773.6 5378	(8073.6) 8243.3		231
	REF:									
CHAPTER 08 LEVELING AND WEIGHING										
082000	FAR 135.185 WEIGHT AND BALLANCE	MOS HRS/MSC AFL	36				28-JAN-2008 7706.7 5364	28-JAN-2011		448 d
	REF: See Workcard									
CHAPTER 12 SERVICING										

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
122140	LUBRICATE THRUST REVERSERS	MOS					16-DEC-2004		
		HRS/MSC -					6386.4		
	REF: AMM 12-21-04	AFL					4385		
CHAPTER 20									
STANDARD PRACTICES - AIRFRAME									
206100	PERFORM PRECIPITATION STATIC (P-STATIC) TEST	MOS					01-FEB-1996		
		HRS/MSC O/C					0		
	REF: AMM 20-61-00	AFL					0		
CHAPTER 21									
AIR CONDITIONING									
+ 05-10-29-H2130007	PERFORM CABIN LEAK RATE CHECK	MOS					07-APR-2009		
		HRS/MSC 1200	+25/-25				7943.3	9143.3	9168.3
	REF: See Workcard	AFL					5534		1131
212001	CHECK VALVE:COCKPIT AIR CHECK VALVE	MOS					01-FEB-1996		
	6600423-7	HRS/MSC O/C		TSN:0			0		
	REF: AMM 21-20-01	AFL		TSN:0			0		
212003	CHECK VALVE:LEFT CABIN AIR CHECK VALVE	MOS					01-FEB-1996		
	3202188-1	HRS/MSC O/C		TSN:0			0		
	REF: AMM 21-20-02	AFL		TSN:0			0		
212004	CHECK VALVE:RIGHT CABIN AIR CHECK VALVE	MOS					31-JAN-2001		
	6600210-4	HRS/MSC O/C		TSN:0			4386.8		
	6448AC	AFL		TSN:0			2931		
	REF: AMM 21-20-02								
212101	BLOWER:CABIN EVAPORATOR BLOWER	MOS					10-AUG-1997		
	EM607-2	HRS/MSC O/C		TSO:0			1132.7		
	208A	AFL		TSO:0			672		
	REF: AMM 21-21-01								
212104	BLOWER:COCKPIT EVAPORATOR BLOWER	MOS					19-NOV-2007		
	EM607-2	HRS/MSC O/C		TSR:0			7609.9		
	491A	AFL		TSR:0			5285		
	REF: AMM 21-21-04								
212105	BOX ASSEMBLY:COCKPIT BLOWER CONTROL BOX ASSEMBLY	MOS					01-FEB-1996		
	6018203-2	HRS/MSC O/C		TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 21-21-05								
212202	COOLING FAN:RIGHT WINDSHIELD DEFOG/EQUIPMENT COOLING FAN	MOS					01-FEB-1996		
	030579	HRS/MSC O/C		TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 21-22-01								
213001	VALVE:PRIMARY OUTFLOW VALVE	MOS					24-SEP-1999		
	6600812-10	HRS/MSC O/C		TSN:0			3226.8		
	17-B0128	AFL		TSN:0			2094		
	REF: AMM 21-30-01								

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
213002	VALVE:SECONDARY OUTFLOW VALVE 6600812-10 63-B0023 REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-JUN-1997 1013.5 590		
213003	SELECTOR:CABIN AIR PRESSURE SELECTOR 2119828-1 SN-UNKNOWN REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213004	CONTROLLER:CABIN PRESSURE CONTROLLER 6600812-014 47-F0115 REF: AMM 21-30-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			13-MAR-2008 7771.4 5405		
213005	CONTROLLER:MANUAL PRESSURE CONTROLLER 6600812-1 SN-UNKNOWN REF: AMM 21-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213006	FILTER:AIR FILTER 6600812-7 SN-UNKNOWN REF: AMM 21-30-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213008	SWITCH:PRESSURIZATION MODE SWITCH 95-6A-15 SN-UNKNOWN REF: AMM 21-30-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-FEB-1999 2656.6		
213009	SWITCH:EMERGENCY DEPRESSURIZATION SWITCH 95-6A-14-H6-58284 SN-UNKNOWN REF: AMM 21-30-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213010	INDICATOR:CABIN PRESSURE INDICATOR 6608506-004 150 REF: AMM 21-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2004 6386.4 4385		
213011	REGULATOR:VACUUM REGULATOR 131402-2 SN-UNKNOWN REF: AMM 21-30-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213012	PUMP:VACUUM PUMP 6019410-10 SN-UNKNOWN REF: AMM 21-30-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213101	VALVE:LEFT EMERGENCY PRESSURIZATION VALVE 6600252-3 SN-UNKNOWN REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213102	VALVE:RIGHT EMERGENCY PRESSURIZATION VALVE 6600252-3 552 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-OCT-1998 2320.1 1460		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
213103	SWITCH:LEFT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 SN-UNKNOWN REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213104	SWITCH:RIGHT EMERGENCY PRESSURIZATION ANEROID SWITCH 2E37C-30 SN-UNKNOWN REF: AMM 21-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213105	CHECK VALVE:LEFT CONDITIONED AIR CHECK VALVE PN SN-UNKNOWN REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
213106	CHECK VALVE:RIGHT CONDITIONED AIR CHECK VALVE 6600210-5 7028AC REF: AMM 21-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-JAN-2001 4386.8 2931		
213107	CHECK VALVE:POSITIVE VENTILATION CHECK VALVE 9519-1-1 SN-UNKNOWN REF: AMM 21-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
214001	VALVE:FLOW CONTROL VALVE 320335-3 306 REF: AMM 21-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			28-JAN-2008 7706.7 5364		
214002	HEAT EXCHANGER:HEAT EXCHANGER 6608060-5 SN-UNKNOWN REF: AMM 21-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
214025	SOLENOID:COCKPIT DIVERTER DOOR SOLENOID 196000-001 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
214031	RESISTOR:COCKPIT DIVERTER DOOR RESISTOR 850F5R0 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
214101	HEATER:COCKPIT HEATER 7600804-2 SN-UNKNOWN REF: AMM 21-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
214102	SOLENOID:COCKPIT DIVERTER DOOR SOLENOID H2902-024 SN-UNKNOWN REF: AMM 21-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
214103	RESISTOR:COCKPIT DIVERTER DOOR RESISTOR 6018462-1 SN-UNKNOWN REF: AMM 21-41-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
214104	THERMOSTAT:COCKPIT DIVERTER DOOR THERMOSTAT 4344-145-97 SN-UNKNOWN REF: AMM 21-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
214201	HEATER:LEFT AUXILIARY CABIN HEATER 7026-1 SN-UNKNOWN REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
214202	HEATER:RIGHT AUXILIARY CABIN HEATER 7026-2 SN-UNKNOWN REF: AMM 21-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
214203	BOX:AUXILIARY HEAT OVERTEMPERATURE MONITOR BOX 6018166-002 186040Z REF: AMM 21-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-1997 616 370			
215001	COMPRESSOR:AIR CONDITIONING COMPRESSOR 83903 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-AUG-2005 6478 4469			
215003	CONDENSER:CONDENSER 7608061-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782			
215004	RECEIVER/DRYER:RECEIVER/DRYER 1523258-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			26-MAR-2004 6044.5			
215005	SWITCH:FREON PRESSURE SWITCH 20PS112-5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			17-AUG-1999 3123.7 2021			
215006	EVAPORATOR:COCKPIT EVAPORATOR 6600427-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
215007	MOTOR:FREON COMPRESSOR DRIVE (R134) MOTOR ES61134-3 SN-UNKNOWN REF: AMM 21-51-02	MOS HRS/MSC AFL ACH		TSO:0 TSO:0 TSO:0 2000			05-MAR-2008 7757.4 5395 2667.1		OVERHAUL	
215007A	MOTOR:INSPECT/REPLACE FREON COMPRESSOR DRIVE (R134) MOTOR BRUSHES - REF:	MOS HRS/MSC AFL ACH		05-10-29-K2150036 1200			05-MAR-2008 7757.4 5395 2667.1	4667.1	4692.1	1834.3

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
215008	PRESSURE REGULATOR VALVE:COCKPIT EVAPORATOR PRESSURE REGULATOR VALVE ORIT-6-0/50-5/8-SAE SN-UNKNOWN REF: AMM 21-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
215009	EVAPORATOR:CABIN EVAPORATOR 7600827-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782		
215010	VALVE:CABIN EXPANSION VALVE BFJ-B-C SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782		
215012	BOX:FREON MOTOR CONTROL BOX 5418598-6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
215013	CONTACTOR:K61 FREON MOTOR CONTACTOR 6018460-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
215016	CURRENT SENSOR:FREON MOTOR DIFFERENTIAL CURRENT SENSOR 268-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
215049	VALVE:COCKPIT EXPANSION VALVE GF-1/2-C SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-JUL-1999 3055.3 1972		
215067	VALVE:CABIN EVAPORATOR PRESSURE/REGULATOR VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216001	SETTING BOX:REMOTE CABIN TEMPERATURE SETTING BOX MS1826-1K 0111 REF: AMM 21-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16		
216003	SELECTOR:CABIN TEMPERATURE SELECTOR 6600423-12 SN-UNKNOWN REF: AMM 21-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216004	INDICATOR:TEMPERATURE CONTROL INDICATOR 6608472-1 SN-UNKNOWN REF: AMM 21-60-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216005	CONTROLLER:COCKPIT TEMPERATURE CONTROLLER 6600423-2 SN-UNKNOWN REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
216006	CONTROLLER:CABIN TEMPERATURE CONTROLLER 625734-2 123C-360 REF: AMM 21-60-04	MOS HRS/MSC AFL	O/C				27-OCT-2000 4227.1 2808		
216008	SENSOR:CABIN TEMPERATURE SENSOR 6600423-3 SN-UNKNOWN REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216010	BLOWER:CABIN TEMPERATURE SENSOR BLOWER 6600231-1 4641 REF: AMM 21-60-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-DEC-1998 2490.4 1576		
216011	SENSOR:COCKPIT SKIN TEMPERATURE SENSOR 6600423-5 SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216012	SENSOR:CABIN SKIN TEMPERATURE SENSOR 6600423-5 SN-UNKNOWN REF: AMM 21-60-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216013	VALVE:COCKPIT TEMPERATURE CONTROL VALVE 5581065-5 375C REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-JAN-2000 3475 2275		
216014	VALVE:CABIN TEMPERATURE CONTROL VALVE 6600423-16 262 REF: AMM 21-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-OCT-2000 4167.5 2764		
216015	MOTOR:COCKPIT TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216016	MOTOR:CABIN TEMPERATURE CONTROL VALVE TORQUE MOTOR 6600423-8 SN-UNKNOWN REF: AMM 21-60-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216017	REGULATOR:SERVO AIR PRESSURE REGULATOR 6600245-3 SN-UNKNOWN REF: AMM 21-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216019	CHECK VALVE:CABIN AIR DISTRIBUTION CHECK VALVE 6600423-7 SN-UNKNOWN REF: AMM 21-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
216020	SENSOR:COCKPIT DUCT TEMPERATURE SENSOR 6600423-4 016C8512 REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16		

?-Insufficient Information
(EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
216021	SENSOR:CABIN DUCT TEMPERATURE SENSOR 6600423-4 SN-UNKNOWN REF: AMM 21-60-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
216022	THERMOSTAT:COCKPIT DUCT OVERHEAT THERMOSTAT 3000-141-18 SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
216023	THERMOSTAT:CABIN DUCT OVERHEAT THERMOSTAT 3000-141-18 SN-UNKNOWN REF: AMM 21-60-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
216024	BOX:CLIMATE CONTROL BOX 6018448-011 239810Z REF: AMM 21-60-13	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-APR-1999 2825.3 1795			
216025	BOX:PILOT ELECTRICAL EQUIPMENT BOX 6018266-2 SN-UNKNOWN REF: AMM 21-60-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
216101	INDICATOR:CABIN TEMPERATURE INDICATOR 6608486-1 093 REF: AMM 21-61-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-NOV-1998 2459.5 1557			
216102	SENSOR:CABIN TEMPERATURE INDICATOR SENSOR FG106P SN-UNKNOWN REF: AMM 21-61-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
CHAPTER 22 AUTO FLIGHT										
221001	CONTROLLER:AUTOPILOT CONTROLLER 501-1679-02 1155 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-JUN-2007 7371.4 5105			
221002	BOX:AUTOPILOT ELECTRICAL BOX 6018309V2-001 680146 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-APR-2005 6402.8 4394			
221003	ACTUATOR:PITCH SERVO ACTUATOR 622-5027-102 4340 REF: AMM 22-10-03	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			27-MAY-2000 3902.7 2546			
221004	MOUNT:PITCH SERVO MOUNT 622-5029-101 SN-UNKNOWN REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
221005	BOX ASSY:PITCH TRIM AMPLIFIER BOX ASSY 5418419-009 06322K(B) REF: AMM 22-10-05	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-APR-2005 6402.8 4394		
221006	ACTUATOR:ROLL SERVO ACTUATOR 622-5027-002 SN-UNKNOWN REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
221007	RELAY BOX:ROLL DISCONNECT RELAY BOX 6018342-1 SN-UNKNOWN REF: AMM 22-10-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
221008	RELAY BOX:YAW DISCONNECT RELAY BOX 6018342-2 731131 REF: AMM 22-10-08	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			27-JUL-2001 4774.6 3187		
221009	ACTUATOR:YAW SERVO ACTUATOR 622-5027-002 SN-UNKNOWN REF: AMM 22-10-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
221010	MOUNT:YAW SERVO MOUNT 622-5029-101 SN-UNKNOWN REF: AMM 22-10-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
221011	MOUNT:ROLL SERVO MOUNT 622-5029-101 SN-UNKNOWN REF: AMM 22-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
222001	COMPUTER:MACH TRIM COMPUTER 501-1132-04 1001M REF: AMM 22-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-JUN-1997 1056.6 670		
222002	ADAPTER:MACH TRIM ADAPTER 902-1-1 SN-UNKNOWN REF: AMM 22-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
222003	SENSOR:MACH TRIM POSITION (FOLLOW UP) SENSOR 6608436-2 SN-UNKNOWN REF: AMM 22-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
225001	INTERFACE BOX:YAW FORCE INTERFACE BOX 6018102-004 197201 REF: AMM 22-50-01	MOS HRS/MSC AFL	O/C				09-JUN-2009 7960.5 5552		
225002	SENSOR:PILOT FORCE SENSOR 6608498-3 SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
225003	SENSOR:COPILOT FORCE SENSOR 6608498-3 SN-UNKNOWN REF: AMM 22-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
CHAPTER 23 COMMUNICATIONS									
231092	SPEAKER:PASSENGER SPEAKER #704 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231101	TRANSCEIVER:NO. 1 VHF TRANSCEIVER 822-1115-001 1880 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C				12-APR-2005 6402.8 4394		
231102	TRANSCEIVER:NO. 2 VHF TRANSCEIVER 822-1115-001 2305 REF: AMM 23-11-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-APR-2005 6402.8 4394		
231103	ANTENNA:NO. 1 VHF ANTENNA VF10-347 4218 REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-APR-2000 3746.5 2442		
231104	ANTENNA:NO. 2 VHF ANTENNA VF10-347 SN-UNKNOWN REF: AMM 23-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231192	INSULATOR:HF ANTENNA LEADTHRU INSULATOR 17340 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231201	RECEIVER/EXCITER:NO. 1 HF RECEIVER/EXCITER 064-1015-1 SN-UNKNOWN REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231202	RECEIVER/EXCITER:NO. 2 HF RECEIVER/EXCITER 064-1015-1 SN-UNKNOWN REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231203	COUPLER:PRIMARY POWER AMPLIFIER/ANTENNA COUPLER 064-1017-01 SN-UNKNOWN REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231204	COUPLER:STANDBY POWER AMPLIFIER/ANTENNA COUPLER 064-1017-01 SN-UNKNOWN REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
231205	ANTENNA:HF ANTENNA 5489123-2 SN-UNKNOWN REF: AMM 23-12-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231207	CONTROL UNIT:NO. 1 HF CONTROL UNIT 064-1016-03 6006 REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C				10-JUN-2008 7823.3 5442		
231208	CONTROL UNIT:NO. 2 HF CONTROL UNIT 064-1016-03 SN-UNKNOWN REF: AMM 23-12-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231209	ADAPTER:HF AUDIO ADAPTER 2688178-1 SN-UNKNOWN REF: AMM 23-12-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231210	BOX ASSEMBLY:HF COMMUNICATION FUSE BOX ASSEMBLY 071-0022-00 SN-UNKNOWN REF: AMM 23-12-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231211	BREAKER:(CBR8) HF REMOTE BREAKER 10RC1C-25 SN-UNKNOWN REF: AMM 23-12-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231301	TRANSCEIVER:FLITEFONE TRANSCEIVER 724855-801 MSA0622 REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			29-AUG-2000 4040.7 2679		
231302	ANTENNA:FLITEFONE ANTENNA 121-014378-01 SN-UNKNOWN REF: AMM 23-13-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231303	CONTROL UNIT:COCKPIT FLITEFONE BASE - CONTROL UNIT 300-2291-013 SN-UNKNOWN REF: AMM 23-13-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231401	CONTROL PANEL:SELCAL CONTROL PANEL 5489328-8 SN-UNKNOWN REF: AMM 23-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231402	DECODER:SELCAL DECODER 2800-0012-105 SN-UNKNOWN REF: AMM 23-14-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231403	SONALERT:SELCAL SONALERT SC628P SN-UNKNOWN REF: AMM 23-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
231501	CONTROL PANEL:PASSENGER BRIEFER CONTROL PANEL 6608478-2 SN-UNKNOWN REF: AMM 23-15-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
231502	COMPUTER:PASSENGER BRIEFER COMPUTER HUCAB-1-SF-LR60 SN-UNKNOWN REF: AMM 23-15-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
233005	AMPLIFIER:PASSENGER SPEAKER AMPLIFIER 909-3081-001 9512004 REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-OCT-1999 3299.9 2157		
235001	CONTROL PANEL:PILOT AUDIO CONTROL PANEL PN-UNKNOWN SN-UNKNOWN REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C				13-APR-2007 7272.3		
235002	CONTROL PANEL:COPILOT AUDIO CONTROL PANEL PN-UNKNOWN SN-UNKNOWN REF: AMM 23-50-01	MOS HRS/MSC AFL	O/C				13-APR-2007 7272.3		
235007	AMPLIFIER:NO. 1 AUDIO AMPLIFIER 700-002 252 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-AUG-1999 3095.5 2003		
235008	AMPLIFIER:NO. 2 AUDIO AMPLIFIER 700-002 428 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-APR-2007 7277 5046		
235011	SPEAKER:COCKPIT SPEAKER 5B3079 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
237001	RECORDER:COCKPIT VOICE (CVR) RECORDER 1601-01-03 SN-UNKNOWN REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
237002	AMPLIFIER:CVR REMOTE MICROPHONE AMPLIFIER 1615-01 SN-UNKNOWN REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
237003	MICROPHONE:CVR REMOTE AREA MICROPHONE 16101-02 SN-UNKNOWN REF: AMM 23-70-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
237004	SWITCH:CVR INERTIA SWITCH 3L0-453/8 SN-UNKNOWN REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
237014	SWITCH:COCKPIT VOICE RECORDER CONTROL SWITCH PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
237021	BEACON:CVR UNDERWATER LOCATOR (ULB) BEACON DK100 SC28582 REF: AMM 25-63-00	MOS HRS/MSC AFL	216 C/C	TSN:0 TSN:0 TSN:0			22-SEP-2008 7910.6 5512	22-SEP-2026	REPLACE 6164 d
237021A	BEACON:CLEAN/FUNCTIONAL TEST CVR UNDERWATER LOCATOR (ULB) BEACON SWITCH, BEACON AND BATTERY - 05-10-29-F2565000	MOS HRS/MSC AFL	24 +14d/-14d				22-SEP-2008 7910.6 5512	22-SEP-2010	06-OCT-2010 320 d
237021B	BEACON:REPLACE CVR UNDERWATER LOCATOR (ULB) BEACON BATTERY - 05-11-00-F2566000 REF: CMM SECTION VI	MOS HRS/MSC AFL	DUE				22-SEP-2008 7910.6 5512	31-OCT-2014 M	1820 d
237021C	BEACON:RECERTIFY CVR UNDERWATER LOCATOR (ULB) BEACON REF:	MOS HRS/MSC AFL	O/C				22-SEP-2008 7910.6 5512		
237021D	BEACON:PERFORM CVR UNDERWATER LOCATOR (ULB) BEACON INSPECTION OF THE UNDERWATER LOCATING BEACON (DK100, DK120, DK130, DK140, DUKANE CORPORATION) PERFORM ACOUSTICS CHARACTERISTICS CHECK (REFER TO 25-63-00)	MOS HRS/MSC AFL	216 +14d/-14d				22-SEP-2008 7910.6 5512	22-SEP-2026	06-OCT-2026 6164 d
+ 237022	UNDERWATER LOCATOR BEACON:CLEAN/TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON SWITCH REF:	MOS HRS/MSC AFL	24 +14d/-14d				22-SEP-2008 7910.6 5512	22-SEP-2010	06-OCT-2010 320 d
238001	UNIT:NO. 1 RADIO TUNING (RTU) UNIT 822-1123-102 1629 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			13-MAR-2008 7771.4 5405		
238002	UNIT:NO. 2 RADIO TUNING (RTU) UNIT 822-1123-102 1903 REF: AMM 23-80-01	MOS HRS/MSC AFL	O/C				12-APR-2005 6402.8 4394		
CHAPTER 24 ELECTRICAL POWER									
+ 05-10-29-B2432010	INSPECT MAIN AIRCRAFT BATTERY INSTALLATION REF: AMM 5-10-29	MOS HRS/MSC AFL	6 +14d/-14d		9		30-JUN-2009 7973.8 5564	09-JAN-2010	23-JAN-2010 64 d
+ 05-10-29-H2431017	PERFORM BATTERY CABLES & RECEPTACLES - BATTERY CONNECTOR INSPECTION REF: AMM 24-31-01	MOS HRS/MSC AFL	300 +25/-25				30-JUN-2009 7973.8 5564	8273.8	8298.8 261.5

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
242001	INVERTER:PRIMARY AC POWER INVERTER 501-1666-01 SN-UNKNOWN REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
242002	INVERTER:SECONDARY AC POWER INVERTER 6608483-1 1621 REF: AMM 24-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			17-JUN-2008 7830.3 5448		
242003	INDICATOR:POWER MONITOR INDICATOR 11003-003 86974 REF: AMM 24-20-03	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			24-OCT-2001 4976.1		
242013	RELAY:LEFT INVERTER RELAY KC-J2A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
242014	RELAY:RIGHT INVERTER RELAY KC-J2A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
242016	PANEL:GENERATOR CONTROL PANEL 6018408-802 43481 REF: AMM 24-30-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			09-JUN-1998 2019.6 1241		
243001	STARTER/GENERATOR:NO. 1 STARTER/GENERATOR 6608512-002 1568XL REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	TSO:0 TSO:0 TSO:0			27-NOV-2007 7617.3 5293	8617.3	605
243001A	STARTER/GENERATOR:OVERHAUL/REPLACE NO. 1 STARTER/GENERATOR BRUSHES - 05-10-29-D2431025 REF:	MOS HRS/MSC AFL	1000				27-NOV-2007 7617.3 5293	8617.3	605
243002	STARTER/GENERATOR:NO. 2 STARTER/GENERATOR 400SG138Q 1808XL REF: AMM 24-30-01	MOS HRS/MSC AFL	1000	TSO:0 TSO:0 TSO:0			09-JUL-2007 7401.5	8401.5	389.2
243002A	STARTER/GENERATOR:OVERHAUL/REPLACE NO. 2 STARTER/GENERATOR BRUSHES - 05-10-29-D2431025 REF:	MOS HRS/MSC AFL	1000				09-JUL-2007 7401.5	8401.5	389.2
243005	GENERATOR CONTROL UNIT:LEFT (GCU) GENERATOR CONTROL UNIT 6608513-3 1236B REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C				09-FEB-2000 3553.3 2326		
243006	GENERATOR CONTROL UNIT:RIGHT (GCU) GENERATOR CONTROL UNIT GC08513-3 1121B REF: AMM 24-30-03	MOS HRS/MSC AFL	O/C	TSN:0			11-AUG-2004		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
243007	TRANSFORMER:A11 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
243008	TRANSFORMER:2A11 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
243009	TRANSFORMER:A12 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
243010	TRANSFORMER:2A12 GENERATOR CURRENT TRANSFORMER CTS700 SN-UNKNOWN REF: AMM 24-30-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
243011	CURRENT SENSOR:LEFT DC AMMETER CURRENT SENSOR 256-1 SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
243012	CURRENT SENSOR:RIGHT DC AMMETER CURRENT SENSOR 256-1 SN-UNKNOWN REF: AMM 24-30-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
243049	BATTERY:UPPER LEAD-ACID (CAPTIVE) BATTERY RG-380E/60L 40286635 REF: AMM 24-31-01	MOS HRS/MSC AFL	36 1800	TSN:0 TSN:0 TSN:0			07-APR-2009 7943.3 5534	07-APR-2012 9743.3	LIFE LIMIT 883 d 1731
+ 243049B	BATTERY:CAPACITY CHECK UPPER LEAD-ACID (CAPTIVE) BATTERY MOS HRS/MSC REF: AMM 12-22-00-G1222002A	12 600 AFL	+14d/-14d +25/-25	05-10-29-G1222002		7943.3	07-APR-2009 7943.3 5534	07-APR-2010 8543.3	21-APR-2010 8568.3 152 d 531
243050	BATTERY:LOWER LEAD-ACID (CAPTIVE) BATTERY RG-380E/60L 40264924 REF: AMM 24-31-01	MOS HRS/MSC AFL	36 1800	TSN:0 TSN:0 TSN:0			07-APR-2009 7943.3 5534	07-APR-2012 9743.3	LIFE LIMIT 883 d 1731
+ 243050B	BATTERY:CAPACITY CHECK LOWER LEAD-ACID (CAPTIVE) BATTERY MOS HRS/MSC REF: AMM 12-22-00-G1222002A	12 600 AFL	+14d/-14d +25/-25	05-10-29-G1222002		7943.3	07-APR-2009 7943.3 5534	07-APR-2010 8543.3	21-APR-2010 8568.3 152 d 531
243062	BATTERY:NO. 1 EMERGENCY POWER BATTERY 501-1712-02 2620 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			28-JAN-2008 7706.7 5364		
+ 243062A	BATTERY:OPERATIONAL CHECK NO. 1 EMERGENCY POWER BATTERY - EMERGENCY BATTERY - MOS HRS/MSC REF: AMM 24-32-01-F1223010	6 HRS/MSC AFL	+14d/-14d	05-10-29-F1223010		-12	19-OCT-2009 8009 5596	07-APR-2010	21-APR-2010 152 d

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
+ 243062B	BATTERY:DISCHARGE CHECK NO. 1 EMERGENCY POWER BATTERY	MOS	12	+14d/-14d	-69	07-APR-2009	28-JAN-2010	11-FEB-2010	83 d
	EMERGENCY BATTERY - 05-10-29-D1223015	HRS/MSC				7943.3			
	REF: AFL	AFL				5534			
243103	INDICATOR:BATTERY TEMPERATURE INDICATOR	MOS				01-FEB-1996			
	51-4226-A3	HRS/MSC	O/C	TSN:0		0			
	SN-UNKNOWN	AFL		TSN:0		0			
	REF: AMM 24-31-03	AFL		TSN:0		0			
244002	MONITOR:GROUND POWER MONITOR	MOS				09-JUN-1998			
	3118487-2	HRS/MSC	O/C	TSN:0		2019.6			
	474076	AFL		TSN:0		1241			
	REF: AMM 24-40-02	AFL		TSN:0					
CHAPTER 25 EQUIPMENT/FURNISHINGS									
256001	EMERGENCY LOCATOR TRANSMITTER:ARTEX 406 (ELT)	MOS				01-FEB-1996			
	453-5000-(999)	HRS/MSC	O/C	TSN:0		0			
	SN-UNKNOWN	AFL		TSN:0		0			
	REF: AMM 25-62-01	AFL		TSN:0		0			
+ 256001A	EMERGENCY LOCATOR TRANSMITTER:BATTERY AND ELT SYSTEM - 05-10-29-J2563001 [FAR 91.207(D)]	MOS	12	+14d/-14d		07-APR-2009	07-APR-2010	21-APR-2010	152 d
		HRS/MSC				7943.3			
	REF: AMM 25-62-00	AFL				5534			
256001B	EMERGENCY LOCATOR TRANSMITTER:REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERY -	MOS	60			22-SEP-2008	22-SEP-2013		1416 d
	05-11-00-L2564000	HRS/MSC				7910.6			
	REF: AFL	AFL				5512			
256001C	EMERGENCY LOCATOR TRANSMITTER:REPLACE (ELT) EMERGENCY LOCATOR TRANSMITTER REMOTE SWITCH	MOS				01-FEB-1996			
	BATTERY (IF INSTALLED)	HRS/MSC	N/A			0			
	REF: AFL	AFL				0			
256001D	EMERGENCY LOCATOR TRANSMITTER:REGISTRATION RENEWAL (ELT) EMERGENCY LOCATOR TRANSMITTER	MOS	24			26-AUG-2009	26-AUG-2011		658 d
		HRS/MSC				7998.5			
	REF: CMM NOAA/SARSAT	AFL				5587			
256001E	EMERGENCY LOCATOR TRANSMITTER:MONTHLY SELF TEST IAW ARTEX 406 ICA	MOS	1			02-NOV-2009	02-DEC-2009		26 d
		HRS/MSC				8009			
	REF: AFL	AFL				5596			
256001F	EMERGENCY LOCATOR TRANSMITTER:NDT (ELT) EMERGENCY LOCATOR TRANSMITTER ARTEX 406 ANTANNA &	MOS	144			17-SEP-2003	17-SEP-2015		2141 d
	EQUIPMENT STRUCTURAL INSPECTION	HRS/MSC	12000			5897.9	17897.9		9885.6
	REF: AFL	AFL				3984			
256001G	EMERGENCY LOCATOR TRANSMITTER:GENERAL VISUAL INSPECTION (ELT) EMERGENCY LOCATOR TRANSMITTER	MOS				07-APR-2009			
	ARTEX 406 ANTANNA & EQUIPMENT	HRS/MSC	1200			7943.3	9143.3		1131
	REF: AFL	AFL				5534			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
256001H	EMERGENCY LOCATOR TRANSMITTER:INSPECTION (ELT) EMERGENCY LOCATOR TRANSMITTER ARTEX 406 12 MONTH INSPECTION & CHECK FOR NEW ADS	MOS HRS/MSC AFL	12				07-APR-2009 7943.3 5534	07-APR-2010	152 d
256010	INTERFACE:ELT/NAV INTERFACE PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
256060	INSPECT ALL CREW & PAX LIFE VEST REF:	MOS HRS/MSC AFL	12				30-JUN-2009 7973.8 5564	30-JUN-2010	INSPECT 236 d
256061	VEST:#1 LEFT PAX LIFE VEST P0723E105P 923462 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C				15-NOV-2007 7600.7 5279		
+ 256061A	VEST:INSPECT NO. 1 LIFE VEST REF: See Workcard	MOS HRS/MSC AFL	60	PER MANUFACTURER'S INSTRUCTIONS			30-JUN-2006	30-JUN-2011	RECERTIFY 601 d
256062	VEST:#2 LIFE VEST FWD DIVAN P0723E105P 923703 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C				15-NOV-2007 7600.7 5279		
+ 256062A	VEST:INSPECT NO. 2 LIFE VEST REF: See Workcard	MOS HRS/MSC AFL	60	PER MANUFACTURER'S INSTRUCTIONS			30-JUN-2006	30-JUN-2011	RECERTIFY 601 d
256063	VEST:#3 LIFE VEST AFT DIVAN P0723E105P 923494 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C				15-NOV-2007 7600.7 5279		
256063A	VEST:INSPECT NO. 3 LIFE VEST REF: See Workcard	MOS HRS/MSC AFL	60	PER MANUFACTURER'S INSTRUCTIONS			30-JUN-2006	30-JUN-2011	601 d
256064	VEST:#4 LEFT PAX LIFE VEST 63600-101 L291606 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C				30-MAY-2003 5782.1 3894		
256064A	VEST:INSPECT NO. 4 LIFE VEST REF: See Workcard	MOS HRS/MSC AFL	60	PER MANUFACTURER'S INSTRUCTIONS			31-MAR-2005	31-MAR-2010	145 d
256065	VEST:#5 RIGHT PAX LIFE VEST P0723E105P 923977 REF: AMM 25-61-00	MOS HRS/MSC AFL	O/C				15-NOV-2007 7600.7 5279		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
256065A	VEST:INSPECT NO. 5 LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS							
		MOS	60				30-JUN-2006	30-JUN-2011	601 d
	REF: See Workcard	HRS/MSC AFL							
256066	VEST:#6 LEFT PAX LIFE VEST								
	63600-101	MOS		TSR:23			12-APR-2005		
	L291600	HRS/MSC	O/C	TSR:620.7			6402.8		
	REF: AMM 25-61-00	AFL		TSR:500			4394		
256066A	VEST:INSPECT NO. 6 LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS							
		MOS	60				31-MAR-2005	31-MAR-2010	145 d
	REF: See Workcard	HRS/MSC AFL							
256067	VEST:#7 RIGHT PAX LIFE VEST								
	P0723E105P	MOS					15-NOV-2007		
	085470	HRS/MSC	O/C				7600.7		
	REF: AMM 25-61-00	AFL					5279		
+ 256067A	VEST:INSPECT NO. 7 LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS							
		MOS	60				30-JUN-2007	30-JUN-2012	967 d
	REF: See Workcard	HRS/MSC AFL							
256070	VEST:LAVATORY LIFE VEST								
	P01074-201	MOS		TSN:0			24-JUL-2008		
	199383	HRS/MSC	O/C	TSN:0			7869.3		
	REF:	AFL		TSN:0			5484		
256070A	VEST:INSPECT LAVATORY LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS							
		MOS	120				31-MAR-2008	31-MAR-2018	3067 d
	REF: See Workcard	HRS/MSC AFL							
256071	VEST:PILOT LIFE VEST								
	63600-101	MOS		TSN:0			30-MAY-2003		
	L291607	HRS/MSC	O/C	TSN:0			5782.1		
	REF: AMM 25-61-00	AFL		TSN:0			3894		
+ 256071A	VEST:INSPECT PILOT LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS							
		MOS	60				31-MAY-2005	31-MAY-2010	206 d
	REF: See Workcard	HRS/MSC AFL							
256072	VEST:COPILOT LIFE VEST								
	63600-101	MOS		TSN:23			12-APR-2005		
	L291609	HRS/MSC	O/C	TSN:620.7			6402.8		
	REF: AMM 25-61-00	AFL		TSN:500			4394		
+ 256072A	VEST:INSPECT COPILOT LIFE VEST	PER MANUFACTURER'S INSTRUCTIONS							
		MOS	60				31-MAR-2005	31-MAR-2010	145 d
	REF: See Workcard	HRS/MSC AFL							
256076	KIT:FIRST AID KIT								
	AFAK	MOS					19-OCT-2009		
	00040541B	HRS/MSC	O/C				8009		
	REF:	AFL					5596		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
256076A	KIT:CONDITION CHECK FIRST AID KIT INVENTORY & EXPIRATION DATES	MOS HRS/MSC AFL	12			19-OCT-2009 8009 5596	19-OCT-2010		347 d
256076B	KIT:FIRST AID KIT EXPIRES	MOS HRS/MSC AFL	DUE			19-OCT-2009 8009 5596	31-OCT-2010 M		359 d
256116	SWITCH PANEL:ELT REMOTE SWITCH PANEL 345-6196-04 UN-KNOWN	MOS HRS/MSC AFL	O/C			17-OCT-2003 5897.9 3984			
+ 256120	TRANSMITTER:INSPECT (ELT) EMERGENCY LOCATOR TRANSMITTER BATTERIES	MOS HRS/MSC AFL	N/A			22-SEP-2008 7910.6 5512			
256202	ANTENNA:ELT ANTENNA 110-337 UN-KNOWN	MOS HRS/MSC AFL	O/C			17-OCT-2003 5897.9 3984			
257007	DIVERTER:NOSE COMPARTMENT CONDENSATION DIVERTER 5418151-16 SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		01-FEB-1996 0 0			
257101	BLOWER:NOSE AVIONICS EXHAUST BLOWER 718ZH SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		01-FEB-1996 0 0			
258010	DIGITAL INTERFACE UNIT:AIRSHOW DIGITAL INTERFACE UNIT 920040 635	MOS HRS/MSC AFL	O/C			29-MAR-2009 7954.6 5546			
258011	UNIT:COCKPIT CONTROL - AIRSHOW UNIT PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		01-FEB-1996 0 0			
258012	CONTROLLER:AIRSHOW FLIGHT DECK CONTROLLER PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		01-FEB-1996 0 0			
CHAPTER 26 FIRE PROTECTION									
261001	UNIT:NO. 1 FIRE DETECTION CONTROL UNIT 377-02833 SN-UNKNOWN	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
261002	UNIT:NO. 2 FIRE DETECTION CONTROL UNIT 377-02833 SN-UNKNOWN REF: AMM 26-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261013	ELEMENT:NO. 1 ENGINE NO 1 FIRE DETECTION SENSOR ELEMENT 244-03915 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261014	ELEMENT:NO. 2 ENGINE NO 1 FIRE DETECTION SENSOR ELEMENT 244-03915 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261025	ELEMENT:NO. 1 ENGINE NO 2 FIRE DETECTION SENSOR ELEMENT 244-09135 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261026	ELEMENT:NO. 2 ENGINE NO 2 FIRE DETECTION SENSOR ELEMENT 244-09135 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261037	ELEMENT:NO. 1 ENGINE NO 3 FIRE DETECTION SENSOR ELEMENT 244-03915 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261038	ELEMENT:NO. 2 ENGINE NO 3 FIRE DETECTION SENSOR ELEMENT 244-03915 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261051	VALVE:NO. 1 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261052	VALVE:NO. 2 TEE DOUBLE CHECK VALVE PN SN-UNKNOWN REF: AMM 26-21-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
261207	SENSOR ASSEMBLY:BAGGAGE COMPARTMENT SMOKE DETECTOR SENSOR ASSEMBLY FR2222 352 REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16		
262013	BOTTLE:FORWARD FIRE EXTINGUISHER BOTTLE 344T 312677 REF: AMM 26-21-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-FEB-2003 5676.7 3821		
+ 262013A	BOTTLE:INSPECTION FORWARD FIRE EXTINGUISHER BOTTLE CHECK ENGINE FIRE EXTINGUISHER CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 26-21-00) REF: AMM 26-21-00-P2620042	MOS HRS/MSC AFL	6 +14d/-14d		-12		19-OCT-2009 8009 5596	07-APR-2010 21-APR-2010	152 d

?-Insufficient Information
(EFF)-Effective C/W
06-NOV-2009

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
+ 262013C	BOTTLE:HYDROSTATIC TEST FORWARD FIRE EXTINGUISHER BOTTLE	MOS	60	+14d/-14d			01-JUN-2006	01-JUN-2011	15-JUN-2011	572 d
	REF:	HRS/MSC AFL								
262014	BOTTLE:AFT FIRE EXTINGUISHER BOTTLE 344T 312686	MOS		TSN:0			14-FEB-2003			
	REF: AMM 26-21-03	HRS/MSC AFL	O/C	TSN:0			5676.7 3821			
+ 262014A	BOTTLE:INSPECTION AFT FIRE EXTINGUISHER BOTTLE CHECK ENGINE FIRE EXTINGUISHER CONTAINER PRESSURE GAUGE FOR PROPER PRESSURE, AND PLUMBING FOR CONDITION AND SECURITY. (REF TO 26-21-00)	MOS	6	+14d/-14d	-12		19-OCT-2009	07-APR-2010	21-APR-2010	152 d
	REF: AMM 26-21-00-P2620042	HRS/MSC AFL					8009 5596			
+ 262014C	BOTTLE:HYDROSTATIC TEST AFT FIRE EXTINGUISHER BOTTLE	MOS	60	+14d/-14d			01-JUN-2006	01-JUN-2011	15-JUN-2011	572 d
	REF:	HRS/MSC AFL								
262036	SQUIB:FORWARD ENGINE FIRE EXTINGUISHER FORWARD SQUIB 30903823 00250	MOS	72	TSN:0			12-APR-2005	01-MAR-2011		LIFE LIMIT 480 d
	REF: AMM 26-21-04	HRS/MSC AFL		TSN:0			6402.8 4394			
	Manufacture Date: 01-MAR-2005									
262037	SQUIB:AFT ENGINE FIRE EXTINGUISHER FORWARD SQUIB 30903823 00240	MOS	72	TSN:0			25-MAY-2006	01-FEB-2011		LIFE LIMIT 452 d
	REF: AMM 26-21-04	HRS/MSC AFL		TSN:0			6926.7 4782			
	Manufacture Date: 01-FEB-2005									
262038	SQUIB:FORWARD ENGINE FIRE EXTINGUISHER AFT SQUIB AE30903823 SN-UNKNOWN	MOS	72	TSN:0			12-APR-2005	01-MAR-2011		LIFE LIMIT 480 d
	REF: AMM 26-21-04	HRS/MSC AFL		TSN:0						
	Manufacture Date: 01-MAR-2005									
262039	SQUIB:AFT ENGINE FIRE EXTINGUISHER AFT SQUIB AE30903823 SN-UNKNOWN	MOS	72	TSN:0			25-MAY-2006	01-AUG-2010		LIFE LIMIT 268 d
	REF: AMM 26-21-04	HRS/MSC AFL		TSN:0			6926.7 4782			
	Manufacture Date: 01-AUG-2004									
262041	FIRE EXTINGUISHER:PILOT PORTABLE FIRE EXTINGUISHER 344T SN-UNKNOWN	MOS		TSN:0			12-JAN-1999			
	REF: AMM 26-20-00	HRS/MSC AFL	O/C	TSN:0			2592.2 1635			
+ 262041B	FIRE EXTINGUISHER:HYDROSTATIC TEST PILOT PORTABLE FIRE EXTINGUISHER 5-10-29-R2620030	MOS	144				21-MAR-2006	21-MAR-2018		3057 d
	REF:	HRS/MSC AFL					6830.3 4720			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
+ 262042B	FIRE EXTINGUISHER:HYDROSTATIC TEST COPILOT PORTABLE FIRE EXTINGUISHER	MOS	144				21-MAR-2006	21-MAR-2018	3057 d
		HRS/MSC					6830.3		
	REF:	AFL					4720		
262045	SWITCH:NO. 1 ENGINE FIRE - PULL SWITCH	MOS		TSN:0			01-FEB-1996		
	865201-3	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 26-21-01								
262046	SWITCH:NO. 2 ENGINE FIRE - PULL SWITCH	MOS		TSN:0			01-FEB-1996		
	865201-3	HRS/MSC	O/C	TSN:0			0		
	SN-UNKNOWN	AFL		TSN:0			0		
	REF: AMM 26-21-01								
262051	EXTINGUISHER:CABIN PORTABLE FIRE EXTINGUISHER	MOS		TSN:0			14-FEB-2003		
	352T	HRS/MSC	O/C	TSN:0			5676.7		
	50709	AFL		TSN:0			3821		
	REF: AMM 26-20-00								
+ 262051B	EXTINGUISHER:HYDROSTATIC TEST CABIN PORTABLE FIRE EXTINGUISHER	MOS	144				18-AUG-2006	18-AUG-2018	3207 d
		HRS/MSC					7006.9		
	REF:	AFL					4840		
E2610020A (s)	INSPECT NO. 1 ENGINE TAILCONE FIRE DETECTION ELEMENT	MOS					PKG		ENGINE CHANGE
	PKG 1	HRS/MSC	E/C				11-AUG-2004		
	REF: AMM 5-10-29	AFL					6276.7		
							4299		
E2610020B (s)	INSPECT NO. 2 ENGINE TAILCONE FIRE DETECTION ELEMENT	MOS					PKG		ENGINE CHANGE
	PKG 2	HRS/MSC	E/C				11-AUG-2004		
	REF: AMM 5-10-29	AFL					6276.7		
							4299		
CHAPTER 27 FLIGHT CONTROLS									
+ 05-10-29-H2750044L	INSPECT LEFT FLAP CAM FOLLOWER BEARING - DETAILED	MOS					28-JAN-2008		
		HRS/MSC	1200	+25/-25			7706.7	8906.7	8931.7
	REF: AMM 5-10-00	AFL					5364		894.4
+ 05-10-29-H2750044R	INSPECT RIGHT FLAP CAM FOLLOWER BEARING - DETAILED	MOS					28-JAN-2008		
		HRS/MSC	1200	+25/-25			7706.7	8906.7	8931.7
	REF: AMM 5-10-00	AFL					5364		894.4
05-11-00-E2710010L	REPLACE LEFT AILERON DRIVE YOKE BOLT (NAS1104-38D)	MOS					03-MAR-2006		LIFE LIMIT
		HRS/MSC	3600				6794	10394	2381.7
	REF:	AFL					4695		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2710010R	REPLACE RIGHT AILERON DRIVE YOKE BOLT (NAS1104-38D)	MOS					03-MAR-2006		LIFE LIMIT	
	REF:	HRS/MSC AFL	3600				6794 4695	10394		2381.7
05-11-00-E2710013L	REPLACE LEFT AILERON CENTER HINGE BOLT (AN4H12A)	MOS					03-MAR-2006		LIFE LIMIT	
	REF:	HRS/MSC AFL	3600				6794 4695	10394		2381.7
05-11-00-E2710013R	REPLACE RIGHT AILERON CENTER HINGE BOLT (AN4H12A)	MOS					03-MAR-2006		LIFE LIMIT	
	REF:	HRS/MSC AFL	3600				6794 4695	10394		2381.7
05-11-00-E2710020L	REPLACE LEFT AILERON CLEVIS BOLT (NAS464P4)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-E2710020R	REPLACE RIGHT AILERON CLEVIS BOLT (NAS464P4)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-E2710022L	REPLACE LEFT AILERON SECTOR (5425105)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2710022R	REPLACE RIGHT AILERON SECTOR (5425105)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2710024L	REPLACE LEFT AILERON CLEVIS (2324517)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2710024R	REPLACE RIGHT AILERON CLEVIS (2324517)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2710026L	REPLACE LEFT AILERON YOKE ASSY (2324511)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2710026R	REPLACE RIGHT AILERON YOKE ASSY (2324511)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2710028L	REPLACE LEFT AILERON BEARING SUPPORT ASSY (5425016)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-E2710028R	REPLACE RIGHT AILERON BEARING SUPPORT ASSY (5425016)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-E2710031L	REPLACE LEFT AILERON HINGE BRACKET ASSY (2322530)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2710031R	REPLACE RIGHT AILERON HINGE BRACKET ASSY (2322530)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2720020	REPLACE RUDDER HINGE BOLTS (NAS6205 & NAS464P5)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-E2720022	REPLACE RUDDER SECTOR BEARING ASSY (5435052)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2720026	REPLACE RUDDER HINGE BRACKETS (5431005 & 5431056)	MOS					20-JUL-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6423.5 4416	26423.5		18411.2
05-11-00-E2730021L	REPLACE LEFT ELEVATOR BELLCRANKS (2331511)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2730021R	REPLACE RIGHT ELEVATOR BELLCRANKS (2331511)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2730022L	REPLACE LEFT ELEVATOR UPPER PUSH-PULL TUBES (5435013)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2730022R	REPLACE RIGHT ELEVATOR UPPER PUSH-PULL TUBES (5435013)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2730024L	REPLACE LEFT ELEVATOR HINGE BOLTS (AN4H11A)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-E2730024R	REPLACE RIGHT ELEVATOR HINGE BOLTS (AN4H11A)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-E2740010	REPLACE HORZ STAB HINGE PIN (2331028)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7
05-11-00-E2750002L	REPLACE LEFT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	MOS					07-APR-2009			
	REF:	HRS/MSC AFL	1200	+25/-25			7943.3 5534	9143.3	9168.3	1131
05-11-00-E2750002R	REPLACE RIGHT FLAP NOSE ROLLER BUSHINGS (NAS76A4)	MOS					07-APR-2009			
	REF:	HRS/MSC AFL	1200	+25/-25			7943.3 5534	9143.3	9168.3	1131
05-11-00-E2750035L	REPLACE LEFT FLAP SECTOR (2625031)	MOS					01-FEB-1996			
	REF:	HRS/MSC AFL	6000	+25/-25			0 0	6000	6025	394
05-11-00-E2750035R	REPLACE RIGHT FLAP SECTOR (2625031)	MOS					01-FEB-1996			
	REF:	HRS/MSC AFL	6000	+25/-25			0 0	6000	6025	394
05-11-00-E2760059L	REPLACE LEFT SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4386.8 2931	8886.8		874.5

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2760059R	REPLACE RIGHT SPOILER ATTACH BOLTS, 5/16 (NAS464-P5A14)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4386.8 2931	8886.8		874.5
05-11-00-E2760061L	REPLACE LEFT SPOILER ACTUATOR ARM (2422511)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4386.8 2931	8886.8		874.5
05-11-00-E2760061R	REPLACE RIGHT SPOILER ACTUATOR ARM (2422511)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4386.8 2931	8886.8		874.5
05-11-00-E2760062L	REPLACE LEFT SPOILER ACTUATOR BOLT (NAS464P4)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4386.8 2931	8886.8		874.5
05-11-00-E2760062R	REPLACE RIGHT SPOILER ACTUATOR BOLT (NAS464P4)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				4386.8 2931	8886.8		874.5
05-11-00-E2760063L	REPLACE LEFT SPOILER CENTER PIVOT BOLT (NAS464P5)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				6402.8 4394	10902.8		2890.5
05-11-00-E2760063R	REPLACE RIGHT SPOILER CENTER PIVOT BOLT (NAS464P5)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				6402.8 4394	10902.8		2890.5
05-11-00-E2760064LI	REPLACE LEFT INBOARD SPOILER HINGE BOLT (AN4-13)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				6402.8 4394	10902.8		2890.5
05-11-00-E2760064LO	REPLACE LEFT OUTBOARD SPOILER HINGE BOLT (AN4-13)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				6402.8 4394	10902.8		2890.5
05-11-00-E2760064RI	REPLACE RIGHT INBOARD SPOILER HINGE BOLT (AN4-13)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				6402.8 4394	10902.8		2890.5

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E2760064RO	REPLACE RIGHT OUTBOARD SPOILER HINGE BOLT (AN4-13)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	4500				6402.8 4394	10902.8		2890.5
05-11-00-F2710036	REPLACE PRIMARY AILERON CONTROL CABLES	MOS					30-JAN-2006		LIFE LIMIT	
	REF:	HRS/MSC AFL	2400				6747.5 4666	9147.5		1135.2
05-11-00-F2720029	REPLACE PRIMARY RUDDER CONTROL CABLES	MOS					30-JAN-2006			
	REF:	HRS/MSC AFL	2400	+25/-25			6747.5 4666	9147.5	9172.5	1135.2
05-11-00-F2730030	REPLACE PRIMARY ELEVATOR CONTROL SYSTEM CABLES	MOS					30-JAN-2006		LIFE LIMIT	
	REF:	HRS/MSC AFL	2400				6747.5 4666	9147.5		1135.2
05-11-00-G2740011	REPLACE HORIZONTAL STABILIZER ACTUATOR ATTACH BOLTS (NAS464P6)	MOS	144				12-APR-2008	12-APR-2020	LIFE LIMIT	3810 d
	REF:	HRS/MSC AFL	6000				7820.2 5440	11440		5834
05-11-00-G2750034L	REPLACE LEFT WING FLAP SECTOR MOUNTING BOLT	MOS	144	+14d/-14d			20-MAY-2008	20-MAY-2020	03-JUN-2020	3848 d
	REF:	HRS/MSC AFL	6000	+25/-25			7822.4 5441	11441	11466	5835
05-11-00-G2750034R	REPLACE RIGHT WING FLAP SECTOR MOUNTING BOLT	MOS	144	+14d/-14d			20-MAY-2008	20-MAY-2020	03-JUN-2020	3848 d
	REF:	HRS/MSC AFL	6000	+25/-25			7822.4 5441	11441	11466	5835
05-11-00-L2750027LI	REPLACE LEFT INBOARD FLAP TRACK ASSY (6022515)	MOS					20-MAY-2008		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				7822.4 5441	25441		19835
05-11-00-L2750027LO	REPLACE LEFT OUTBOARD FLAP TRACK ASSY (6022515)	MOS					20-MAY-2008		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				7822.4 5441	25441		19835
05-11-00-L2750027RI	REPLACE RIGHT INBOARD FLAP TRACK ASSY (6022515)	MOS					03-JUN-2002		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				5553.5 3720	23720		18114

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-L2750027RO	REPLACE RIGHT OUTBOARD FLAP TRACK ASSY (6022515)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		14394
05-11-00-L2750028	REPLACE INBOARD NOSE ROLLER TRACK (2322511)	MOS					20-MAY-2008		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				7822.4 5441	25441		19835
05-11-00-L2750029	REPLACE OUTBOARD NOSE ROLLER TRACK (2322512)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		14394
05-11-00-L2750033L	REPLACE LEFT LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	10000				0 0	10000		4394
05-11-00-L2750033R	REPLACE RIGHT LOWER FLAP SECTOR BRACKET ASSEMBLY (2322516)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	10000				0 0	10000		4394
05-11-00-M2710021LI	REPLACE LEFT INBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-M2710021LO	REPLACE LEFT OUTBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-M2710021RI	REPLACE RIGHT INBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-M2710021RO	REPLACE RIGHT OUTBOARD AILERON HINGE BOLTS (AN4H12A)	MOS					12-APR-2005		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				6402.8 4394	26402.8		18390.5
05-11-00-M2730031	REPLACE HINGE ASSEMBLIES (2332013 OUTBOARD, 2332018, 2393009-801, 3532003 CENTER, AND 2332019 INBOARD)(LOCATED ON HORIZONTAL STABILIZER ASSEMBLY)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		11987.7

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-M2750049LI	REPLACE LEFT INBOARD FLAP SUPPORT FITTING	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4386.8 2931	22931		17325
05-11-00-M2750049LO	REPLACE LEFT OUTBOARD FLAP SUPPORT FITTING	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4386.8 2931	22931		17325
05-11-00-M2750049RI	REPLACE RIGHT INBOARD FLAP SUPPORT FITTING	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4386.8 2931	22931		17325
05-11-00-M2750049RO	REPLACE RIGHT OUTBOARD FLAP SUPPORT FITTING	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4386.8 2931	22931		17325
05-11-00-N2750025	REPLACE INBOARD FLAP TRACK HINGE FITTING (ON FLAP) (2625023)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				0 0	6000		394
05-11-00-N2750026	REPLACE OUTBOARD FLAP TRACK HINGE FITTING (ON FLAP) (2625024)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				0 0	6000		394
05-11-00-N2750031	REPLACE INBOARD AND OUTBOARD FLAP SUPPORT FITTING (6022521-1 THRU-8)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	O/C				0 0			
05-11-00-N2750032	REPLACE UPPER FLAP SECTOR BRACKET ASSEMBLY (6022511-1, -2, -801, AND -802)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	O/C				0 0			
05-11-00-N2750051	REPLACE INBOARD FLAP HINGE FITTING (6025022)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		14394
05-11-00-N2750052	REPLACE OUTBOARD FLAP HINGE FITTING (6025021)	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				0 0	20000		14394

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-R2750050L	REPLACE LEFT UPPER FLAP SECTOR BRACKET	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4386.8 2931	22931		17325
05-11-00-R2750050R	REPLACE RIGHT UPPER FLAP SECTOR BRACKET	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	20000				4386.8 2931	22931		17325
05-11-00-R2760079L	REPLACE LEFT SPOILER ACTUATOR ATTACH FITTING AND BOLT	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	10000				0 0	10000		1987.7
05-11-00-R2760079R	REPLACE RIGHT SPOILER ACTUATOR ATTACH FITTING AND BOLT	MOS					01-FEB-1996		LIFE LIMIT	
	REF:	HRS/MSC AFL	10000				0 0	10000		1987.7
270505	PANEL ASSY:TRIM SWITCH PANEL ASSY 6018201-007 253987Z	MOS		TSN:0			21-AUG-2000			
	REF: AMM 27-00-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			4045.5 2665			
271013	TAB ASSEMBLY:AILERON TRIM TAB ASSEMBLY 2324028-116	MOS		TSN:0			01-FEB-1996			
	REF: AMM 27-10-04	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271015	TAB ASSEMBLY:LEFT AILERON BALANCE TAB ASSEMBLY 2324028-83	MOS		TSN:0			01-FEB-1996			
	REF: AMM 27-10-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271016	TAB ASSEMBLY:RIGHT AILERON BALANCE TAB ASSEMBLY 2324028-84	MOS		TSN:0			01-FEB-1996			
	REF: AMM 27-10-03	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			
271019	ACTUATOR:AILERON TRIM ACTUATOR 6600156-031	MOS		TSR:0			24-JUL-2002			
	REF: AMM 27-10-11	HRS/MSC AFL	O/C	TSR:0 TSR:0			5554.2 3722			
271025	WHEEL:PILOT CONTROL WHEEL 2415151-13	MOS		TSN:0			01-FEB-1996			
	REF: AMM 27-10-01	HRS/MSC AFL	O/C	TSN:0 TSN:0			0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
271026	WHEEL:COPILOT CONTROL WHEEL 2415151-14 SN-UNKNOWN REF: AMM 27-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
271031	POTENTIOMETER:AILERON TRIM TAB ACTUATOR POTENTIOMETER CMU1021 SN-UNKNOWN REF: AMM 27-10-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-FEB-1997 616 370			
271126	INDICATOR:AILERON TRIM POSITION INDICATOR 6608217-21 SN-UNKNOWN REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
271132	SENSOR:RIGHT AILERON POSITION SENSOR 501-1123-02 SN-UNKNOWN REF: AMM 27-10-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
271701	AILERON:LEFT AILERON 2424000-243 SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0	20000		LIFE LIMIT 11987.7
271702	AILERON:RIGHT AILERON 2424000-242 SN-UNKNOWN REF: AMM 27-10-02	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0	20000		LIFE LIMIT 11987.7
272001	RUDDER:RUDDER 5433000-16 SN-UNKNOWN REF: AMM 27-20-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0	20000		LIFE LIMIT 11987.7
272005	SECTOR:AFT RUDDER SECTOR 5435051-13 SN-UNKNOWN REF: AMM 27-20-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
272007	TAB:RUDDER TRIM TAB 5433300-29 SN-UNKNOWN REF: AMM 27-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
272013	ACTUATOR:RUDDER TRIM TAB ACTUATOR 6600156-14 5145 REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
272020	POTENTIOMETER:RUDDER TRIM TAB POTENTIOMETER CMU1021 079 REF: AMM 27-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-FEB-1997 616 370		
272026	INDICATOR:RUDDER TRIM INDICATOR 6608217-20 SN-UNKNOWN REF: AMM 27-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
273001	ELEVATOR:LEFT ELEVATOR 2434000-151 SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0	LIFE LIMIT 20000	11987.7
273002	ELEVATOR:RIGHT ELEVATOR 2434000-152 SN-UNKNOWN REF: AMM 27-30-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0	LIFE LIMIT 20000	11987.7
273013	COMPUTER:STALL WARNING COMPUTER 6608263-18 GST02528 REF: AMM 27-31-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			25-APR-2005 6405.7 4397		
273017	SHAKER:PILOT STICK SHAKER 6608289-3 SN-UNKNOWN REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
273018	SHAKER:COPILOT STICK SHAKER 6608289-3 SN-UNKNOWN REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
273101	TRANSDUCER:PILOT STALL WARNING TRANSDUCER 25147A-12 1066 REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			03-JUN-2002 5553.5 3720		
273102	TRANSDUCER:COPILOT STALL WARNING TRANSDUCER 6608263-15 SN-UNKNOWN REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
273105	INDICATOR:PILOT ANGLE-OF-ATTACK (AOA) INDICATOR 6608515-2 SN-UNKNOWN REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
273106	INDICATOR:COPILOT ANGLE-OF-ATTACK (AOA) INDICATOR 6608515-2 134 REF: AMM 27-31-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-FEB-1997 616 370		
273110	VANE:ANGLE-OF-ATTACK (AOA) VANE 3065227 SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
274001	HORIZONTAL STABILIZER:HORIZONTAL STABILIZER 2332000-61 SN-UNKNOWN REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
274003	CONTROLLER:HORIZONTAL STABILIZER ACTUATOR CONTROLLER 6608444-2 1135A REF: AMM 27-40-03	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			26-SEP-2001 4899.8 3283		
274010	DETECTOR:TRIM-IN-MOTION DETECTOR 6608446-2 SN-UNKNOWN REF: AMM 27-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
274013	ACTUATOR:HORIZONTAL STABILIZER ACTUATOR 5435005-028 157 REF: AMM 27-40-02	MOS HRS/MSC AFL	600	TSO:0 TSO:0			07-APR-2009 7943.3 5534	OVERHAUL 8543.3	531
274020	REPLACE HORIZONTAL STABILIZER ACTUATOR LOWER ATTACH BOLT REF:	MOS HRS/MSC AFL	144 6000				12-APR-2008 7820.2 5440	LIFE LIMIT 12-APR-2020 11440	3810 d 5834
274062	INDICATOR:PITCH TRIM INDICATOR 6608514-1 SN-UNKNOWN REF: AMM 27-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
274068	CONTROL:HORIZONTAL STABILIZER ACTUATOR CONTROL 6018454-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
275001	FLAP ASSEMBLY:LEFT FLAP ASSEMBLY 6025010 SN-UNKNOWN REF: AMM 27-50-01	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0	LIFE LIMIT 10000	4394

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
275002	FLAP ASSEMBLY:RIGHT FLAP ASSEMBLY 6025010-024 W171 REF: AMM 27-50-01	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			06-OCT-2000 4167.5 2764	12764	LIFE LIMIT	7158
275010	BOX ASSY:FLAP & ENGINE SYNCHRONIZER RELAY BOX ASSY 6018336-1 SN-UNKNOWN REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
275012	POTENTIOMETER:FLAP POSITION POTENTIOMETER RV4SAYSD102A SN-UNKNOWN REF: AMM 27-50-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2004 6386.4 4385			
275019	SWITCH:LEFT LIMIT, INBOARD FLAP/STABILIZER SWITCH 2625045-31 SN-UNKNOWN REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
275020	SWITCH:RIGHT LIMIT, INBOARD FLAP/STABILIZER SWITCH 2625045-32 SN-UNKNOWN REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
275021	SWITCH:LEFT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
275022	SWITCH:RIGHT POSITION, OUTBOARD FLAP/STABILIZER SWITCH CS402-3 SN-UNKNOWN REF: AMM 27-50-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
275031	VALVE:FLAP CONTROL (FLAP/SPOILER) VALVE 6600362-1 SN-UNKNOWN REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
275037	ACTUATOR:LEFT FLAP ACTUATOR 6600493-1 SN-UNKNOWN REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
275038	ACTUATOR:RIGHT FLAP ACTUATOR 6600493-1 SN-UNKNOWN REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
275200	INDICATOR:FLAP POSITION INDICATOR 6608475-004 159 REF: AMM 27-50-10	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-APR-2005 6402.8 4394		
275217	CHECK VALVE:FLAP ACTUATION CHECK VALVE AN6207-4 SN-UNKNOWN REF: AMM 27-50-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
276001	SPOILER:LEFT ASSEMBLY SPOILER 2492001-5 W1483S REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			31-JAN-2001 4386.8 2931	8886.8	LIFE LIMIT 874.5
276002	SPOILER:RIGHT ASSEMBLY SPOILER 2492001-6 W1406S REF: AMM 27-60-01	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			31-JAN-2001 4386.8 2931	8886.8	LIFE LIMIT 874.5
276010	COMPUTER:SPOILER COMPUTER 6608454-3 1370 REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-AUG-2004 6247.4 4270		
276013	ACTUATOR:LEFT SPOILER ACTUATOR 2417015-5 277 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			12-APR-2005 6402.8 4394	16402.8	LIFE LIMIT 8390.5
276014	ACTUATOR:RIGHT SPOILER ACTUATOR 2417015-5 778 REF: AMM 27-60-04	MOS HRS/MSC AFL	10000	TSN:0 TSN:0 TSN:0			16-DEC-2004 6386.4 4385	16386.4	LIFE LIMIT 8374.1
276019	ARM:LEFT SPOILER ACTUATOR ARM 2422511 SN-UNKNOWN REF:	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			31-JAN-2001 4386.8 2931	8886.8	LIFE LIMIT 874.5
276020	ARM:RIGHT SPOILER ACTUATOR ARM 2422511 SN-UNKNOWN REF:	MOS HRS/MSC AFL	4500	TSN:0 TSN:0 TSN:0			31-JAN-2001 4386.8 2931	8886.8	LIFE LIMIT 874.5
276025	SWITCH:LEFT SPOILER DOWN AND LOCKED SWITCH CS402-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
276026	SWITCH:RIGHT SPOILER DOWN AND LOCKED SWITCH CS402-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
276031	SWITCH:LEFT SPOILER UPLIMIT SWITCH 622EN513-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-OCT-1998 2298.1 1443		
276032	SWITCH:RIGHT SPOILER UPLIMIT SWITCH CS402-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
276037	SENSOR:LEFT SPOILER POSITION SENSOR 501-1123-02 SN-UNKNOWN REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
276038	SENSOR:RIGHT SPOILER POSITION SENSOR 501-1123-02 SN-UNKNOWN REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
276043	POTENTIOMETER:SPOILER POTENTIOMETER CMU1021 SN-UNKNOWN REF: AMM 27-60-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-FEB-1997 616 370		
276049	INDICATOR:SPOILER POSITION INDICATOR 6608476-3 169 REF: AMM 27-60-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2004 6386.4 4385		
276119	REPLACE LEFT SPOILER ACTUATOR ATTACH BOLT MOS HRS/MSC REF:		10000				01-FEB-1996 0 0	LIFE LIMIT 10000	1987.7
276120	REPLACE RIGHT SPOILER ACTUATOR ATTACH BOLT MOS HRS/MSC REF:		10000				01-FEB-1996 0 0	LIFE LIMIT 10000	1987.7
276181	REPLACE RIGHT FLAP SECTOR MOUNTING BOLTS MOS HRS/MSC REF:		144 6000				13-APR-2006 6852.5 4737	13-APR-2018 10737	SCRAP 3080 d 5131

CHAPTER 28 FUEL

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
05-10-29-F2820012	CLEAN/CHECK LOW PRESSURE FUEL FILTERS	MOS					01-FEB-1996		
	REF:	HRS/MSC AFL	-				0 0		
+ 05-10-29-L2812002L	INSPECT LEFT INNER WING STRUCTURE OUTBOARD OF WS 213.602	MOS	24	+14d/-14d			07-APR-2009	07-APR-2011	21-APR-2011 517 d
	REF:	HRS/MSC AFL					7943.3 5534		
+ 05-10-29-L2812002R	INSPECT RIGHT INNER WING STRUCTURE OUTBOARD OF WS 213.602	MOS	24	+14d/-14d			07-APR-2009	07-APR-2011	21-APR-2011 517 d
	REF:	HRS/MSC AFL					7943.3 5534		
+ 05-10-29-L2812010L	INSPECT LEFT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA	MOS	24	+14d/-14d			07-APR-2009	07-APR-2011	21-APR-2011 517 d
	REF:	HRS/MSC AFL					7943.3 5534		
+ 05-10-29-L2812010R	INSPECT RIGHT INNER WING BETWEEN WS 53.0 & 92.0 FOR CORROSION & BACTERIA	MOS	24	+14d/-14d			07-APR-2009	07-APR-2011	21-APR-2011 517 d
	REF:	HRS/MSC AFL					7943.3 5534		
+ 05-10-29-L2812020L	INSPECT LEFT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION	MOS	24	+14d/-14d			07-APR-2009	07-APR-2011	21-APR-2011 517 d
	REF:	HRS/MSC AFL					7943.3 5534		
+ 05-10-29-L2812020R	INSPECT RIGHT INNER WING, INBOARD OF WS 72 FOR CORROSION/CONDITION	MOS	24	+14d/-14d			07-APR-2009	07-APR-2011	21-APR-2011 517 d
	REF:	HRS/MSC AFL					7943.3 5534		
05-11-00-G2820003	REPLACE ALL FUEL HOSE ASSEMBLIES (EXCLUDING ALL HOSES IN ENGINE NACELLE AREA) IN AICRAFT (PRESSURE)	MOS	144	+14d/-14d			20-MAY-2008	20-MAY-2020	03-JUN-2020 3848 d
	REF:	HRS/MSC AFL	6000	+25/-25			7822.4 5441	11441	11466 5835
281007	VALVE:INTERCONNECT VALVE	MOS					01-FEB-1996		
	PN	MOS					01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF:	AFL			TSN:0		0		
281013	SUMP ASSEMBLY:FUSELAGE SUMP ASSEMBLY	MOS					01-FEB-1996		
	PN	MOS					01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:0		0		
	REF:	AFL			TSN:0		0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
281019	SUMP ASSEMBLY:LEFT WING SUMP ASSEMBLY 2826023-41 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281020	SUMP ASSEMBLY:RIGHT WING SUMP ASSEMBLY 2826023-42 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281027	CELL:FORWARD FUEL CELL 6600500-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281028	CELL:AFT FUEL CELL 6600501-3 109820 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-JUN-2008 7823.3 5442		
281061	VALVE:LEFT FUEL VENT FLOAT VALVE 6600346-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281062	VALVE:RIGHT FUEL VENT FLOAT VALVE 6600346-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281087	PUMP:LEFT INBOARD SCAVENGE JET PUMP 2326023-33 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281088	PUMP:RIGHT INBOARD SCAVENGE JET PUMP 2326023-33 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281089	PUMP:LEFT CENTER SCAVENGE JET PUMP 2326023-32 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281090	PUMP:RIGHT CENTER SCAVENGE JET PUMP 2326023-32 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
281091	PUMP:LEFT OUTBOARD SCAVENGE JET PUMP 2326023-33 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281092	PUMP:RIGHT OUTBOARD SCAVENGE JET PUMP 2326023-33 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281114	SWITCH:FUSELAGE TANK FLOAT SWITCH L14F-74 461 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-JAN-2000 3475 2275		
281401	PUMP:LEFT FUSELAGE CELL TRANSFER PUMP 2380060-43 SN-UNKNOWN REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281402	PUMP:RIGHT FUSELAGE CELL TRANSFER PUMP 2380060-43 SN-UNKNOWN REF: AMM 28-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281409	PUMP:LEFT SCAVENGE PUMP 2380060-42 SN-UNKNOWN REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281410	PUMP:RIGHT SCAVENGE PUMP 2380060-42 SN-UNKNOWN REF: AMM 28-14-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281411	VALVE:LEFT FUEL TRANSFER VALVE 6600355-2 SN-UNKNOWN REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281412	VALVE:RIGHT FUEL TRANSFER VALVE 6600355-2 SN-UNKNOWN REF: AMM 28-14-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
281413	VALVE:CROSSFLOW VALVE 6600355-2 SN-UNKNOWN REF: AMM 28-14-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
281414	FLOAT SWITCH:FUSELAGE HIGH-LEVEL FLOAT SWITCH L14F-47 SN-UNKNOWN REF: AMM 28-14-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
281421	BOX:FUEL FILL AND TRANSFER BOX 6018255-3 SN-UNKNOWN REF: AMM 28-14-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282001	FILTER ASSEMBLY:LEFT FUEL FILTER ASSEMBLY 6600488-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282002	FILTER ASSEMBLY:RIGHT FUEL FILTER ASSEMBLY 6600488-4 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282003	PUMP:LEFT STANDBY PUMP 2380060-48 SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282004	PUMP:RIGHT STANDBY PUMP 2380060-48 SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282007	PUMP:LEFT INBOARD JET PUMP 2326023-31 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282008	PUMP:RIGHT INBOARD JET PUMP 2326023-31 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282009	SHUTOFF VALVE:LEFT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE 3244870-1 C37063 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSO:0			13-JUL-2004			
282010	SHUTOFF VALVE:RIGHT WING AND FUSELAGE MOTIVE FLOW SHUTOFF VALVE 3244870-1 C37080 REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	TSO:0			19-JUL-2004			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
282019	VALVE:FUSELAGE PILOT VALVE 2780610-102 SN-UNKNOWN REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282020	VENT VALVE:FUSELAGE VENT VALVE 2780610-102 SN-UNKNOWN REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282021	CHECK VALVE:REFUELING CHECK VALVE 2780623-101 SN-UNKNOWN REF: AMM 28-20-13	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282023	VALVE:FUEL SOLENOID VALVE 2780613-101 SN-UNKNOWN REF: AMM 28-20-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282025	VALVE:LEFT FUEL SUPPLY SHUTOFF VALVE 6600355-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282026	VALVE:RIGHT FUEL SUPPLY SHUTOFF VALVE 6600355-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282061	VALVE:LEFT RELIEF VALVE 7600005-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282062	VALVE:RIGHT RELIEF VALVE 7600005-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
282065	VALVE:LEFT WING PILOT VALVE 2780610-102 1205 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16			
282066	VALVE:RIGHT WING PILOT VALVE 2780610-102 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
282067	VALVE:LEFT WING REFUEL SHUTOFF VALVE 2780614-102 765 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16		
282068	VALVE:RIGHT WING REFUEL SHUTOFF VALVE 2780614-102 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
282072	VALVE:REFUELING SHUTOFF VALVE 2780624-102 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
282075	VALVE:FORWARD PRECHECK VALVE 2780615-102 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
282076	VALVE:AFT PRECHECK VALVE 2780615-102 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
282530	BOX:FUEL CONTROL RELAY BOX JC-J2A SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-OCT-2006 7088 4901		
284001	INDICATOR:FUEL QUANTITY INDICATOR 6608467-1 034 REF:	MOS HRS/MSC AFL	O/C				27-OCT-2000 4227.1 2808		
284001	FUEL PROBE:LEFT INBOARD WING (MT5) FUEL PROBE 2326014-016 99080801 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-APR-2005 6403.1 4395		
284002	FUEL PROBE:RIGHT INBOARD WING (MT6) FUEL PROBE 2326014-12 SN-UNKNOWN REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
284009	FUEL PROBE:FUSELAGE (MT18) FUEL PROBE 0118KTU01 987045 REF: AMM 28-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			11-JUN-1999 2977.2 1910		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
284058	SWITCH:LEFT WING LOW LEVEL FLOAT SWITCH L15H-8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284059	SWITCH:RIGHT WING LOW LEVEL FLOAT SWITCH L15H-8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284061	SWITCH:LEFT WING HIGH LEVEL FLOAT SWITCH L15H-8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284062	SWITCH:RIGHT WING HIGH LEVEL FLOAT SWITCH L15H-8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284067	SWITCH:LEFT LOW FUEL PRESSURE SWITCH 7600002-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284068	SWITCH:RIGHT LOW FUEL PRESSURE SWITCH 7600002-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284077	PROBE:LEFT WING OUTBOARD PROBE FG220A224 95111392 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-MAR-1999 2758.8 1747			
284078	PROBE:RIGHT WING OUTBOARD PROBE 2326014-9 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284079	PROBE:LEFT WING EXTENSION INBOARD PROBE 2826003-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284080	PROBE:RIGHT WING EXTENSION INBOARD PROBE 2826003-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE		
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT		
284081	PROBE:LEFT WING EXTENSION OUTBOARD PROBE 2626003-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
284082	PROBE:RIGHT WING EXTENSION OUTBOARD PROBE 2826003-3 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
CHAPTER 29 HYDRAULIC POWER										
05-11-00-G2900001	REPLACE HYDRAULIC HOSE ASSEMBLIES(EXCLUDING HOSES FOR THE LANDING GEAR AND THE HOSE ASSEMBLIES IN THE ENGINE NACELLE AREA)	MOS HRS/MSC AFL	144 6000	+14d/-14d +25/-25			20-MAY-2008 7822.4 5441	20-MAY-2020 11441	03-JUN-2020 11466	3848 d 5835
05-11-00-L2910020	REPLACE PRESSURE AND RETURN HYDRAULIC FILTER ELEMENTS	MOS HRS/MSC AFL	O/C				26-NOV-2003 5929.3 4010			
290002	PRESSURE REGULATOR:HYDRAULIC PRESSURE REGULATOR 2702-13 0309 REF: AMM 29-00-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1998 2320.1 1460			
290003	RESERVOIR:HYDRAULIC RESERVOIR 5417007-30 SN-UNKNOWN REF: AMM 29-00-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
290005	CHECK VALVE:PRESSURE REGULATOR CHECK VALVE 496-4D2-1/4 SN-UNKNOWN REF: AMM 29-00-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1998 2320.1 1460			
291005	FILTER ASSEMBLY:HYDRAULIC PRESSURE FILTER ASSEMBLY M8815/2A-10 SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
291006	FILTER ASSEMBLY:HYDRAULIC RETURN FILTER ASSEMBLY M8815/1A-10 SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
291007	ACCUMULATOR:HYDRAULIC SYSTEM ACCUMULATOR 2617049-1 SN-UNKNOWN REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
291013	SHUTOFF VALVE:NO. 1 ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE P40-791 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
291014	SHUTOFF VALVE:NO. 2 ENGINE HYDRAULIC SUPPLY SHUTOFF VALVE 6600355-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			25-MAY-2006 6926.7 4782			
291018	PRESSURE SWITCH:NO. 1 ENGINE HYDRAULIC PRESSURE SWITCH 730635 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
291020	PRESSURE SWITCH:NO. 2 ENGINE HYDRAULIC PRESSURE SWITCH 730635 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
291037	PUMP:NO. 1 ENGINE HYDRAULIC PUMP 6607066-1 K0056AB REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-DEC-2003 5945.2			
291038	PUMP:NO. 2 ENGINE HYDRAULIC PUMP 66137 K0080BA REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			30-JUL-2007 7923 5140			
291079	FILTER:HYDRAULIC PRESSURE REGULATOR FILTER 4301-2 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-OCT-1998 2320.1 1460			
292001	PUMP:AUXILIARY HYDRAULIC PUMP 6600248-1 1504 REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			12-JAN-1999 2592.2 1635			
293001	TRANSDUCER:HYDRAULIC PRESSURE MT15 TRANSDUCER 123091-1 SN-UNKNOWN REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
293002	PRESSURE SWITCH:AUXILIARY HYDRAULIC PUMP PRESSURE SWITCH 730635 SN-UNKNOWN REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
293003	INDICATOR:HYDRAULIC PRESSURE INDICATOR 6608401-13 SN-UNKNOWN REF: AMM 29-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
CHAPTER 30 ICE AND RAIN PROTECTION									
300001	BOX:COPILOT ELECTRICAL EQUIPMENT BOX 6018294-003 092038 REF: AMM 30-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16		
301001	VALVE:WING ANTI-ICE SHUTOFF AND PRESSURE REGULATING VALVE 15E51-4 120 REF: AMM 30-10-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			31-JAN-2001 4386.8 2931		
301005	THERMOSWITCH:WING OVERHEAT WARNING THERMOSWITCH 6600141-1 SN-UNKNOWN REF: AMM 30-10-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
301007	INDICATOR:WING TEMPERATURE INDICATOR 6608210-28 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
301009	SENSOR:WING ANTI-ICE TEMPERATURE SENSOR FG101P SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
301101	CONTROLLER:HORIZONTAL STABILIZER ANTI-ICE CONTROLLER 6608485-1 126 REF: AMM 30-11-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			15-SEP-1998 2232.2 1391		
301103	BLANKET:LEFT HORIZONTAL STABILIZER HEAT BLANKET 4065-3481 SN-UNKNOWN REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSN:0			18-NOV-2002 5604.6		
301104	BLANKET:RIGHT HORIZONTAL STABILIZER HEAT BLANKET 4065-3481 00-06580 REF: AMM 30-11-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-JUN-2005 6412.8 4404		
302001	SHUTOFF VALVE:LEFT NACELLE ANTI-ICE SHUTOFF VALVE 27441482-13 7AH36 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-FEB-1998 1597.3 961		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
302002	SHUTOFF VALVE:RIGHT NACELLE ANTI-ICE SHUTOFF VALVE 27441482 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
302013	PRESSURE SWITCH:LEFT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 1922TW REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-NOV-1996 329.5 199		
302014	PRESSURE SWITCH:RIGHT NACELLE ANTI-ICE PRESSURE SWITCH 7600020-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
303001	MONITOR:LEFT PITOT HEAT MONITOR 6608317-7 2395 REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			14-OCT-1998 2307.8 1450		
303002	MONITOR:RIGHT PITOT HEAT MONITOR 6608317-7 SN-UNKNOWN REF: AMM 30-30-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
304001	SHUTOFF VALVE:WINDSHIELD ANTI-ICE SHUTOFF VALVE 6600201-1 1044 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			30-JAN-2006 6747.5 4666		
304003	VALVE:WINDSHIELD ANTI-ICE RAM AIR MODULATING VALVE 6600203-1 SN-UNKNOWN REF: AMM 30-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
304004	HEAT EXCHANGER:WINDSHIELD ANTI-ICE HEAT EXCHANGER 6600351-2 SN-UNKNOWN REF: AMM 30-40-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
304007	THERMOSWITCH:LEFT WINDSHIELD ANTI-ICE LOW-LIMIT (S83) THERMOSWITCH 6600141-3 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
304007	VALVE:WINDSHIELD ANTI-ICE MODULATING VALVE 27241287-07 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
304008	THERMOSWITCH:RIGHT WINDSHIELD ANTI-ICE LOW-LIMIT (S82) THERMOSWITCH 6600141-3 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
304009	THERMOSWITCH:LEFT WINDSHIELD ANTI-ICE HIGH-LIMIT (S85) THERMOSWITCH 6600141-13 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
304010	THERMOSWITCH:RIGHT WINDSHIELD ANTI-ICE HIGH-LIMIT (S84) THERMOSWITCH 6600141-13 SN-UNKNOWN REF: AMM 30-40-07	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
304101	TANK ASSY:ALCOHOL SUPPLY TANK ASSY 5419751-11 SN-UNKNOWN REF: AMM 30-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
304102	FLOAT SWITCH:ALCOHOL ANTI-ICE FLOAT SWITCH L14F-74 SN-UNKNOWN REF: AMM 30-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
304104	RELIEF VALVE:ALCOHOL PRESSURE RELIEF VALVE 6608260-3 SN-UNKNOWN REF: AMM 30-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
304105	SHUTOFF VALVE:ANTI-ICE THREE-WAY SHUTOFF VALVE 6608258-2 SN-UNKNOWN REF: AMM 30-41-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
304106	PRESSURE REGULATOR VALVE:ALCOHOL ANTI-ICE SHUTOFF AND PRESSURE REGULATOR VALVE 6608257-1 456A REF: AMM 30-41-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-JAN-2004 5969.6			
304203	RELAY BOX:WINDSHIELD DEFOG RELAY BOX 3118318-3 SN-UNKNOWN REF: AMM 30-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
305025	FILTER:ALCOHOL FILTER 213-851 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
308001	LAMP:LEFT ICE DETECT LAMP ML6839 SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			05-JUN-1999 2960.1 1901		
308002	LAMP:RIGHT ICE DETECT LAMP 6839 SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			22-MAY-2000 3887.6 2537		
E3020001A (s)	INSPECT NO. 1 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 1 REF:	MOS HRS/MSC AFL	E/C				11-AUG-2004 6276.7 4299	ENGINE CHANGE	
E3020001B (s)	INSPECT NO. 2 ENGINE NACELLE INLET BULKHEAD, PLUMBING, AND SHUTOFF VALVE FOR SECURITY, CRACKS, OR OTHER DEFORMATION PKG 2 REF:	MOS HRS/MSC AFL	E/C				11-AUG-2004 6276.7 4299	ENGINE CHANGE	
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
312001	CLOCK:PILOT CREW CLOCK M877 SN-UNKNOWN REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
312001A	CLOCK:REPLACE PILOT CREW CLOCK BATTERY MOS 24 HRS/MSC REF: CMM STANDARD AND OPTIONAL FEATURES	MOS HRS/MSC AFL					02-NOV-2009 8009 5596	02-NOV-2011	726 d
312002	CLOCK:COPILOT CREW CLOCK M877 SN-UNKNOWN REF: AMM 31-21-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
312002A	CLOCK:REPLACE COPILOT CREW CLOCK BATTERY MOS 24 HRS/MSC REF: CMM STANDARD AND OPTIONAL FEATURES	MOS HRS/MSC AFL					02-NOV-2009 8009 5596	02-NOV-2011	726 d
315007	SYSTEM:TAKE-OFF CONFIGURATION MONITOR SYSTEM PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
315101	CONTROL UNIT:AURAL WARNING CONTROL UNIT 6608108-2 SN-UNKNOWN REF: AMM 31-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
315102	GENERATOR:TONE GENERATOR 6608445-3 0272 REF: AMM 31-51-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-AUG-2003 5821.4		
315103	MIXER:AURAL WARNING MIXER 1882-1 SN-UNKNOWN REF: AMM 31-51-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
316001	DISPLAY:PILOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-026 1225 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-SEP-2002 5554.2 3722		
316002	DISPLAY:COPILLOT EFD-871 ELECTRONIC FLIGHT DISPLAY 622-9345-026 2528 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16		
316003	DISPLAY:MULTIFUNCTION DISPLAY 622-9434-026 1664 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-SEP-1998 2223.5 1382		
316004	DISPLAY:MULTIFUNCTION DISPLAY 622-9434-012 SN-UNKNOWN REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
CHAPTER 32 LANDING GEAR									
05-11-00-E3211066	REPLACE NOSE LANDING GEAR ACTUATOR BOLT (6042007-4) -	MOS HRS/MSC AFL					20-MAY-2008 7822.4 5441	11441 11466	5835
05-11-00-E3211084L	REPLACE LEFT MLG ACTUATOR ATTACH PIN (5441101)	MOS HRS/MSC AFL					01-FEB-1996 0 0		LIFE LIMIT 14394
05-11-00-E3211084R	REPLACE RIGHT MLG ACTUATOR ATTACH PIN (5441101)	MOS HRS/MSC AFL					01-FEB-1996 0 0		LIFE LIMIT 14394
05-11-00-E3211092L	REPLACE LEFT MLG UPPER BEARING (7600839)	MOS HRS/MSC AFL					31-JAN-2001 4386.8 2931		LIFE LIMIT 3325

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
05-11-00-E3211092R	REPLACE RIGHT MLG UPPER BEARING (7600839)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				4386.8 2931	8931		3325
05-11-00-E3211093L	REPLACE LEFT MLG LOWER BEARING (6041105)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				4368.8 2931	8931		3325
05-11-00-E3211093R	REPLACE RIGHT MLG LOWER BEARING (6041105)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				4368.8 2931	8931		3325
05-11-00-G3210003	REPLACE HYDRAULIC HOSE ASSEMBLIES ATTACHED TO THE MAIN AND NOSE GEAR ACTUATORS, MAIN GEAR DOOR ACTUATORS, AND THE MAIN AND NOSE GEAR UPLATCH ACTUATOR	MOS					12-APR-2005			
	REF:	HRS/MSC AFL	O/C				6402.8 4394			
05-11-00-G3233007	REPLACE EMERGENCY AIR HOSE ASSEMBLIES FOR LANDING GEAR EMERGENCY FREEFALL EXTENSION, LANDING GEAR EMERGENCY BLOWDOWN, AND EMERGENCY BRAKING SYSTEMS.	MOS	144	+14d/-14d			20-MAY-2008	20-MAY-2020	03-JUN-2020	3848 d
	REF:	HRS/MSC AFL	6000	+25/-25			7822.4 5441	11441	11466	5835
05-11-00-G3243040	REPLACE HYDRAULIC BRAKE HOSE ASSEMBLIES LOCATED ON THE STRUT AND IN WHEEL WELL AREA	MOS					31-OCT-2005			
	REF:	HRS/MSC AFL	O/C				6600.3 4469			
05-11-00-M3211091L	REPLACE LEFT MLG UPPER BEARING RETENTION PIN (6041110-002, -003, AND -004)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				4386.8 2931	8931		3325
05-11-00-M3211091R	REPLACE RIGHT MLG UPPER BEARING RETENTION PIN (6041110-002, -003, AND -004)	MOS					31-JAN-2001		LIFE LIMIT	
	REF:	HRS/MSC AFL	6000				4386.8 2931	8931		3325
321001	STRUT:ASSEMBLY, LEFT MAIN LANDING GEAR STRUT 6081021-811	MOS					12-JAN-1999		LIFE LIMIT	
	026	HRS/MSC					2592.2			
	REF: AMM 32-11-00	AFL	16500				1635	18135		12529
321002	STRUT:ASSEMBLY, RIGHT MAIN LANDING GEAR STRUT 6081021-812	MOS					12-JAN-1999		LIFE LIMIT	
	024	HRS/MSC					2592.2			
	REF: AMM 32-11-00	AFL	16500				1635	18135		12529

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
321003	ARM:LEFT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM 2341119-5 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
321004	ARM:RIGHT MAIN GEAR SHOCK STRUT UPPER TORQUE ARM 2341119-5 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
321005	ARM:LEFT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM 2384034-2 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-FEB-1999 2656.6			
321006	ARM:RIGHT MAIN GEAR SHOCK STRUT LOWER TORQUE ARM 2384034-2 SN-UNKNOWN REF: AMM 32-11-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			09-FEB-1999 2656.6			
321015	SWITCH:DOOR DOWN SWITCH 1CH1-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
322001	STRUT:ASSEMBLY, NOSE GEAR STRUT 2342100-19 077 REF: AMM 32-21-00	MOS HRS/MSC AFL	10000				07-NOV-1999 3318.5 2172		LIFE LIMIT 11635 M	6029
323019	SWITCH:LEFT MAIN LANDING GEAR SQUAT SWITCH 426EN12-8 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-AUG-2006 7025.6 4854			
323020	SWITCH:RIGHT MAIN LANDING GEAR SQUAT SWITCH 426EN12-8 SN-UNKNOWN REF: AMM 32-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			29-AUG-2006 7025.6 4854			
323031	ACTUATOR:LEFT MAIN LANDING GEAR ACTUATOR 2327100-028 TF-0024 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			12-JAN-1999 2592.2 1635		LIFE LIMIT 21635	16029
323032	ACTUATOR:RIGHT MAIN LANDING GEAR ACTUATOR 2327100-028 TF0024 REF: AMM 32-31-01	MOS HRS/MSC AFL	20000	TSN:0 TSN:0 TSN:0			16-DEC-2004 6386.4 4385		LIFE LIMIT 24385	18779

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
323036	PIN:LEFT MAIN LANDING GEAR ACTUATOR ATTACH PIN 5441101-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
323037	PIN:RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PIN 5441101-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
323043	ACTUATOR:LEFT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 6600085-2 SN-UNKNOWN REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
323044	ACTUATOR:RIGHT MAIN LANDING GEAR INBOARD GEAR DOOR ACTUATOR 6600085-8 0590 REF: AMM 32-31-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-JUL-1998 2118.2 1306		
323055	ACTUATOR:LEFT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 477 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-MAR-2000 3705.9 2416		
323056	ACTUATOR:RIGHT UPLOCK, MAIN LANDING GEAR INBOARD DOOR ACTUATOR 2417016-1 4221 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			16-DEC-2004 6386.4 4385		
323073	ACTUATOR:NOSE LANDING GEAR ACTUATOR 2317100-12 SN-UNKNOWN REF: AMM 32-32-01	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0		10000	12-JAN-1999 2592.2 1635	LIFE LIMIT	6029
323079	ACTUATOR:UPLOCK, NOSE LANDING GEAR ACTUATOR 2417016-1 1022 REF: AMM 32-32-02	MOS HRS/MSC AFL	O/C				07-APR-2009 7943.3 5534		
323099	VALVE:SELECT, LANDING GEAR VALVE 48C48641 1291 REF: AMM 32-30-05	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			07-JUL-2001 4752.4 3167		
323222	PILLAR:LEFT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR 2441123-17 SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0		20000	01-FEB-1996 0 0	LIFE LIMIT	14394

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
323223	PILLAR:RIGHT MAIN LANDING GEAR ACTUATOR ATTACH PILLAR 2341123-17 SN-UNKNOWN REF: AMM 32-31-05	MOS HRS/MSC AFL		TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		LIFE LIMIT 20000	14394
324001	TIRE:NOSE TIRE 184F10-2 71030553 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2008 7822.4 5441			
324007	WHEEL:ASSEMBLY, NOSE WHEEL 9544207-4 MAY08-10626 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-AUG-2008 7890 5496			
324013	TIRE:NO. 1 MAIN LANDING GEAR TIRE 178K43-1 71710882 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-SEP-2008 7913.1 5513			
324014	TIRE:NO. 2 MAIN LANDING GEAR TIRE 178K43-1 70480894 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-SEP-2008 7913.1 5513			
324015	TIRE:NO. 3 MAIN LANDING GEAR TIRE 178K43-1 71650899 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-SEP-2008 7913.1 5513			
324016	TIRE:NO. 4 MAIN LANDING GEAR TIRE 301-321-870 82520823 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0			04-JUN-2009 7954.6 5546			
324037	WHEEL:NO. 1 MAIN LANDING GEAR WHEEL 5011740 OCT03-1956 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				27-SEP-2008 7913.1 5513			
324037A	WHEEL:NDT INSPECT NO. 1 MAIN LANDING GEAR WHEEL REF:	MOS HRS/MSC AFL	O/C				27-SEP-2008 7913.1 5513			
324038	WHEEL:NO. 2 MAIN LANDING GEAR WHEEL 5011740 JUL94-332 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				27-SEP-2008 7913.1 5513			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
324038A	WHEEL:NDT INSPECT NO. 2 MAIN LANDING GEAR WHEEL	MOS					27-SEP-2008		
		HRS/MSC	O/C				7913.1		
	REF:	AFL					5513		
324039	WHEEL:NO. 3 MAIN LANDING GEAR WHEEL	MOS		TSO:0			27-SEP-2008		
	5011740	HRS/MSC	O/C	TSO:0			7913.1		
	MAR07-2460	AFL		TSO:0			5513		
	REF: AMM 32-40-02								
324039A	WHEEL:NDT INSPECT NO. 3 MAIN LANDING GEAR WHEEL	MOS					27-SEP-2008		
		HRS/MSC	O/C				7913.1		
	REF:	AFL					5513		
324040	WHEEL:NO. 4 MAIN LANDING GEAR WHEEL	MOS					04-JUN-2009		
	5011740	HRS/MSC	O/C	TSO:0			7954.6		
	FEB92-11/FEB01-1590	AFL		TSO:0			5546		
	REF: AMM 32-40-02								
324040A	WHEEL:NDT INSPECT NO. 4 MAIN LANDING GEAR WHEEL	MOS					04-JUN-2009		
		HRS/MSC	O/C				7954.6		
	REF:	AFL					5546		
324048	BRAKE:NO. 1 ASSEMBLY, MAIN LANDING GEAR BRAKE	MOS		TSO:0			08-AUG-2008		
	5003096-7	HRS/MSC	O/C	TSO:0			7890		
	JAN01-5721	AFL		TSO:0			5496		
	REF: AMM 32-41-01								
324049	BRAKE:NO. 2 ASSEMBLY, MAIN LANDING GEAR BRAKE	MOS		TSO:0			08-AUG-2008		
	5003096-7	HRS/MSC	O/C	TSO:0			7890		
	MAR97-4421	AFL		TSO:0			5496		
	REF: AMM 32-41-01								
324050	BRAKE:NO. 3 ASSEMBLY, MAIN LANDING GEAR BRAKE	MOS		TSO:0			08-AUG-2008		
	5003096-7	HRS/MSC	O/C	TSO:0			7890		
	JULY85-407	AFL		TSO:0			5496		
	REF: AMM 32-41-01								
324051	BRAKE:NO. 4 ASSEMBLY, MAIN LANDING GEAR BRAKE	MOS		TSO:0			08-AUG-2008		
	5003096-7	HRS/MSC	O/C	TSO:0			7890		
	DEC97-4622	AFL		TSO:0			5496		
	REF: AMM 32-41-01								
324061	VALVE:NO. 1 POWER BRAKE, PILOTS VALVE	MOS		TSN:0			10-JUL-2000		
	3321200-2	HRS/MSC	O/C	TSN:0			4006.8		
	1409	AFL		TSN:0			2630		
	REF: See Workcard								

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
324062	VALVE:NO. 2 POWER BRAKE, PILOTS VALVE 3321200-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324063	VALVE:NO. 1 POWER BRAKE, COPILOTS VALVE 3321200-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324064	VALVE:NO. 2 POWER BRAKE, COPILOTS VALVE 3321200-1 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324085	FUSE:NO. 1 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324086	FUSE:NO. 2 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324109	FUSE:NO. 3 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324110	FUSE:NO. 4 HYDRAULIC, BRAKE FUSE 2380114-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324133	VALVE:AFT PARKING BRAKE VALVE 3329 SN-UNKNOWN REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324134	VALVE:FWD PARKING BRAKE VALVE 3329 SN-UNKNOWN REF: AMM 32-41-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324145	TRANSDUCER:NO. 1 WHEEL SPEED TRANSDUCER 40-911 SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
324146	TRANSDUCER:NO. 2 WHEEL SPEED TRANSDUCER 40-911 SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324147	TRANSDUCER:NO. 3 WHEEL SPEED TRANSDUCER 40-911 SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324148	TRANSDUCER:NO. 4 WHEEL SPEED TRANSDUCER 40-911 7183 REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JUL-2001 4774.6 3187		
324169	VALVE:LEFT ANTI-SKID VALVE 39-309-1 SN-UNKNOWN REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324170	VALVE:RIGHT ANTI-SKID VALVE 39-309-1 1798 REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			04-MAR-1997 654.6 392		
324175	CONTROL:ANTI-SKID CONTROL 42-379-1 SN-UNKNOWN REF: AMM 32-42-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324413	BOX ASSY:PARK BRAKE ANNUNCIATOR BOX ASSY 2618481-3 SN-UNKNOWN REF: AMM 32-42-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
324501	VALVE:EMERGENCY BRAKE CONTROL VALVE 63500-2 SN-UNKNOWN REF: AMM 32-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
325001	ACTUATOR:NOSE WHEEL STEERING ACTUATOR 501-1711-02 1087 REF: AMM 32-50-05	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-AUG-2008 7903.3 5504		
325005	COMPUTER:NOSE WHEEL STEERING COMPUTER 501-1708-02 1102 REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-AUG-2008 7890 5496		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
325019	GEARBOX:NOSE WHEEL STEERING ACTUATOR GEARBOX 3142025-1 SN-UNKNOWN REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
326001	SWITCH:LEFT MAIN GEAR DOWN-AND-LOCKED SWITCH 1EN1-8 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-MAR-1999 2730.2 1724			
326002	SWITCH:RIGHT MAIN GEAR DOWN-AND-LOCKED SWITCH 1CH1-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
326003	SWITCH:LEFT MAIN GEAR DOOR UPLATCH SWITCH 1CH1-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
326004	SWITCH:RIGHT MAIN GEAR DOOR UPLATCH SWITCH 1CH1-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
326013	SWITCH:NOSE GEAR DOWN-AND-LOCKED SWITCH 1CH1-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
326019	SWITCH:NOSE GEAR UPLATCH SWITCH 21CH9-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-DEC-2006 7130.4 4931			
CHAPTER 33	LIGHTS									
331201	POWER SUPPLY:LEFT GLARESHIELD FLOODLIGHT POWER SUPPLY 6608477-1 2464 REF: AMM 33-12-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-NOV-2001 5002.9 3358			
331202	POWER SUPPLY:RIGHT GLARESHIELD FLOODLIGHT POWER SUPPLY 6608477-1 2406 REF: AMM 33-12-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-NOV-2001 5002.9 3358			
331401	CONTROL BOX:PILOT DIMMING CONTROL BOX 6018145-1 SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
331402	CONTROL BOX:COPILOT DIMMING CONTROL BOX 6018145-1 SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
331403	CONTROL BOX:CENTER INSTRUMENT AND PEDESTAL DIMMING CONTROL BOX 2618289-14 SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
331404	CONTROL BOX:PEDESTAL DIMMING CONTROL BOX 2618289-14 SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
331405	CONTROL BOX:FUEL QUANTITY INDICATOR DIMMING CONTROL BOX 2618289-14 SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
331406	CONTROL BOX:CDU LAMP DIMMING CONTROL BOX 2618262-9 SN-UNKNOWN REF: AMM 33-14-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
332009	CONTROL:INDIRECT LIGHTING CONTROL MS1836 0083 REF: AMM 33-20-09	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16			
332010	MODULE:ALTERNATE/MOMENTARY SWITCHING MODULE MS1881 0042 REF: AMM 33-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			23-MAR-1999 2762.9 1750			
332014	CONTROL:ZONE BACK LIGHTING CONTROL MS1839 SN-UNKNOWN REF: AMM 33-20-14	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
334101	LIGHT ASSEMBLY:LEFT LANDING AND TAXI LIGHT ASSEMBLY GE4580 SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-AUG-2008 7908.8 5508			
334102	LIGHT ASSEMBLY:RIGHT LANDING AND TAXI LIGHT ASSEMBLY GE4580 SN-UNKNOWN REF: AMM 33-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-OCT-2006 7080.9 4896			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
334201	LIGHT ASSEMBLY:LEFT NAVIGATION LIGHT ASSEMBLY GE1683 SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			14-APR-2006 6853.5 4738			
334202	LIGHT ASSEMBLY:RIGHT NAVIGATION LIGHT ASSEMBLY GE1683 SN-UNKNOWN REF: AMM 33-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-NOV-2007 7600.7 5279			
334301	LIGHT:UPPER STROBE/BEACON LIGHT GE16386-4 179 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			06-SEP-2002 5554.2 3722			
334302	LIGHT:LOWER STROBE/BEACON LIGHT GE16386-9-1 AB0377 REF: AMM 33-43-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-APR-2002 5530 3705			
334401	LIGHT ASSEMBLY:WING ICE INSPECTION LIGHT ASSEMBLY GLJ-111 SN-UNKNOWN REF: AMM 33-44-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			02-MAY-2001 4625.6 3072			
334501	LIGHT:RECOGNITION LIGHT MS25241Q4681 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			31-DEC-2002 5648.8			
CHAPTER 34 NAVIGATION										
+ 05-10-30-RVSM-L3411015	PERFORM AIR DATA CERTIFICATION TESTING OF PRIMARY ALTITUDE SYSTEM (REFER TO 34-17-00)	MOS HRS/MSC AFL	12	+14d/-14d	-69		07-APR-2009 7943.3 5534	28-JAN-2010	11-FEB-2010	83 d
34-00-FAR-91.171	CHECK VOR FAR 91.171	DAYS HRS/MSC AFL					12-JUN-1996 25 16			
34-00-FAR-91.217	PERFORM ALTITUDE DATA TRANSMISSION TEST	MOS HRS/MSC AFL					01-FEB-1996 0 0			
34-00-FAR-91.411	RECERTIFY PITOT-STATIC SYSTEM	MOS HRS/MSC AFL	24				07-APR-2009 7943.3 5534	07-APR-2011		517 d

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
341001	PROCESSOR UNIT:TCAS PROCESSOR UNIT 622-8971-422 6198 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			08-MAR-2002 5372.2 3612			
341020	PROBE:LEFT PITOT/STATIC PROBE 856KR7 SN-UNKNOWN REF: AMM 34-11-02	MOS HRS/MSC AFL	15000	+25/-25 TSN:0 TSN:0			01-FEB-1996 0 0	15000	15025	LIFE LIMIT 6987.7
341020A	PROBE:VERIFY LEFT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (REFER TO 34-11-02) 5-10-30-N3411016 REF: AMM 34-11-02-N3411016	MOS HRS/MSC AFL	24	+14d/-14d			17-JUL-2008 7869.3 5484	17-JUL-2010	31-JUL-2010	253 d
+ 341020B	PROBE:DETAILED VISUAL INSPECTION LEFT PITOT/STATIC PROBE (REFER TO 34-11-02) 5-10-30-N3411064 REF: AMM 34-11-02-N3411064	MOS HRS/MSC AFL	24	+14d/-14d			07-APR-2009 7943.3 5534	07-APR-2011	21-APR-2011	517 d
341025	PROBE:RIGHT PITOT/STATIC PROBE 856KR8 SN-UNKNOWN REF: AMM 34-11-02	MOS HRS/MSC AFL	15000	+25/-25 TSN:0 TSN:0			01-FEB-1996 0 0	15000	15025	LIFE LIMIT 6987.7
341025A	PROBE:VERIFY RIGHT PITOT/STATIC PROBE PITCH AND YAW ALIGNMENT (REFER TO 34-11-02) 5-10-30-N3411016 REF: AMM 34-11-02-N3411016	MOS HRS/MSC AFL	24	+14d/-14d			17-JUL-2008 7869.3 5484	17-JUL-2010	31-JUL-2010	253 d
+ 341025B	PROBE:DETAILED VISUAL INSPECTION RIGHT PITOT/STATIC PROBE (REFER TO 34-11-02) 5-10-30-N3411064 REF: AMM 34-11-02-N3411064	MOS HRS/MSC AFL	24	+14d/-14d			07-APR-2009 7943.3 5534	07-APR-2011	21-APR-2011	517 d
341111	ALTIMETER:STANDBY ALTIMETER N884-9001 8188B REF: AMM 34-15-01	MOS HRS/MSC AFL	O/C				19-MAR-2009 7943.3 5534			
+ 341111A	ALTIMETER:RECERTIFY STANDBY ALTIMETER REF:	MOS HRS/MSC AFL	24				19-MAR-2009	19-MAR-2011		498 d
341133	COMPUTER:NO. 1 AIR DATA COMPUTER 822-0389-429 4542 REF: AMM 34-17-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			08-AUG-2008 7890 5496			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION	NEXT DUE		TIME REMAINING
							COMPLIANCE (ENH)	ACTUAL	MAX LIMIT	
+ 341133A	COMPUTER:RECERTIFY NO. 1 AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM NO. 1	MOS	12				07-APR-2009	07-APR-2010		152 d
	REF: AMM 34-17-00-L3411015	HRS/MSC AFL					7943.3 5534			
341134	COMPUTER:NO. 2 AIR DATA COMPUTER 822-0389-429	MOS					19-MAR-2009			
	3019	HRS/MSC AFL	O/C				7943.3 5534			
REF: AMM 34-17-01										
+ 341134A	COMPUTER:RECERTIFY NO. 2 AIR DATA COMPUTER PRIMARY AIR DATA SYSTEM NO. 2	MOS	24				19-MAR-2009	19-MAR-2011		498 d
	REF: AMM 34-17-00-L3411015	HRS/MSC AFL								
341801	INDICATOR:STANDBY MACH/AIRSPEED INDICATOR 39310-J2057	MOS		TSN:0			01-FEB-1996			
	SN-UNKNOWN	HRS/MSC AFL	O/C	TSN:0			0			
REF: AMM 34-18-01				TSN:0			0			
342015	SENSOR:DISPLAY UNIT SENSOR 622-9735-002	MOS		TSR:0			13-NOV-2004			
	4AFV	HRS/MSC AFL	O/C	TSR:0			6386.4			
REF:				TSR:0			4385			
342401	COMPASS:MAGNETIC COMPASS C2350L4M23	MOS		TSN:0			24-AUG-2008			
	C279	HRS/MSC AFL	O/C	TSN:0			7908.8			
REF: AMM 34-24-01				TSN:0			5508			
342410	COMPUTER:NO. 1 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400	MOS		TSO:0			04-DEC-1999			
	1582	HRS/MSC AFL	O/C	TSO:0			3378.6			
REF: AMM 34-26-01				TSO:0			2213			
342411	COMPUTER:NO. 2 ATTITUDE/HEADING (AHC-85E) COMPUTER 622-9336-400	MOS		TSN:0			31-JUL-1997			
	2187	HRS/MSC AFL	O/C	TSN:0			1097.7			
REF: AMM 34-26-01				TSN:0			649			
342501	INDICATOR:STANDBY ATTITUDE DIRECTIONAL (ADI) INDICATOR 501-1197-05	MOS		TSR:0			08-SEP-2007			
	2042	HRS/MSC AFL	O/C	TSR:0			7495.7			
REF: AMM 34-25-01				TSR:0			5200			
344111	ANTENNA:LOWER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001	MOS		TSN:0			20-MAY-2008			
	2WGY	HRS/MSC AFL	O/C	TSN:0			7822.4			
REF:				TSN:0			5441			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
344112	ANTENNA:UPPER TCAS DIRECTIONAL (TRE-920) ANTENNA 622-8973-001 21321 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-JUN-1996 25 16		
344205	RECEIVER/TRANSMITTER/ANTENNA:WEATHER RADAR (RTA-844) RECEIVER/TRANSMITTER/ANTENNA 622-9302-003 1UN4 REF: AMM 34-42-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-SEP-2003 5874 3961		
345001	RECEIVER:NO. 1 ADF (ADF-462) RECEIVER 622-7382-101 SN-UNKNOWN REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345002	RECEIVER:NO. 2 ADF (ADF-462) RECEIVER 622-7382-101 SN-UNKNOWN REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345005	COMPUTER:ENHANCED GROUND PROXIMITY WARNING SYSTEM COMPUTER 965-0976-040-212-212 20829 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			12-APR-2005 6402.8 4394		
345011	TRANSCEIVER:NO. 1 DME TRANSCEIVER 622-7309-101 SN-UNKNOWN REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345012	TRANSCEIVER:NO. 2 DME TRANSCEIVER 622-7309-101 SN-UNKNOWN REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345021	RECEIVER:NO. 1 VHF (VIR 432) RECEIVER 622-7194-101 SN-UNKNOWN REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345022	RECEIVER:NO. 2 VHF (VIR 432) RECEIVER 622-7194-101 2696 REF: AMM 34-51-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			10-OCT-2003 5897		
345031	COMPUTER:NO. 1 NAVIGATION COMPUTER 1190-01-1110 SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
345032	COMPUTER:NO. 2 NAVIGATION COMPUTER 1190-01-1110 SN-UNKNOWN REF: AMM 34-61-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345079	TRANSPONDER:PRIMARY ATC TRANSPONDER 622-9210-003 3085 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				09-MAR-2008		
+ 345079A	TRANSPONDER:RECERTIFY PRIMARY ATC TRANSPONDER 91.413 REF:	MOS HRS/MSC AFL	24				07-APR-2009 7943.3 5534	07-APR-2011	517 d
345080	TRANSPONDER:SECONDARY ATC TRANSPONDER 622-9210-003 4664 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C				09-MAR-2008		
+ 345080A	TRANSPONDER:RECERTIFY SECONDARY ATC TRANSPONDER 91.413 REF:	MOS HRS/MSC AFL	24				07-APR-2009 7943.3 5534	07-APR-2011	517 d
345085	CONTROL ADAPTER:NO. 1 ATC TRANSPONDER CONTROL ADAPTER PN SN-UNKNOWN REF: AMM 34-56-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345086	CONTROL ADAPTER:NO. 2 ATC TRANSPONDER CONTROL ADAPTER PN SN-UNKNOWN REF: AMM 34-56-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
345091	ANTENNA:NO. 1 TRANSPONDER/DME ANTENNA CI-100-2 245855 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2008 7822.4 5441		
345092	ANTENNA:NO. 2 TRANSPONDER/DME ANTENNA CI-100-2 245854 REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-MAY-2008 7822.4 5441		
346015	CDU:NO. 1 FLIGHT MANAGEMENT SYSTEM CDU PN-UNKNOWN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			20-MAY-2008 7822.4 5441		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
346017	CDU:NO. 3 FLIGHT MANAGEMENT SYSTEM CDU 622-9576-002 146 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		17-JUL-2004 6238.1			
CHAPTER 35 OXYGEN									
05-10-29-R3500019	HYDROSTATIC TEST/INSPECT	KEVLAR WRAPPED OXYGEN CYLINDER							
		MOS HRS/MSC AFL	36			07-APR-2009 7943.3 5534	07-APR-2012		883 d
350003	TRANSDUCER:NOSE OXYGEN SYSTEM PRESSURE TRANSDUCER 124058-5000 39605 REF: AMM 35-00-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		16-DEC-2004 6386.4 4385			
350005	REGULATOR ASSEMBLY:NOSE OXYGEN SHUTOFF VALVE AND REGULATOR ASSEMBLY 172270-04 SN-UNKNOWN REF: AMM 35-00-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		01-FEB-1996 0 0			
351001	MASK:PILOT OXYGEN MASK MC10-15-107 12177 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0		12-FEB-2007 7178 4961			
351001A	MASK:OVERHAUL PILOT OXYGEN MASK MOS HRS/MSC AFL	72				12-FEB-2007 7178 4961	12-FEB-2013		1194 d
351002	MASK:COPILOT OXYGEN MASK MC-10-15-107 72571 REF: AMM 35-10-01	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0		14-APR-2005 6403.1 4395			
351002A	MASK:OVERHAUL COPILOT OXYGEN MASK MOS HRS/MSC AFL	72				30-JAN-2006 6747.5 4666	30-JAN-2012		815 d
352006	CYLINDER:NOSE OXYGEN CYLINDER 176270-40 AE-34242 REF: AMM 35-00-01 Manufacture Date: 31-DEC-1995	MOS HRS/MSC AFL ACH	180	TSN:0 TSN:0 TSN:0		20-FEB-1996 0 0	31-DEC-2010	LIFE LIMIT	420 d
352027	VALVE:PASSENGER OXYGEN CONTROL VALVE P21004 SN-UNKNOWN REF: AMM 35-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0		01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION	NEXT DUE		TIME REMAINING
							COMPLIANCE (ENH)	ACTUAL	MAX LIMIT	
352040	EQUIPMENT:PROTECTIVE BREATHING EQUIPMENT 802300-14 SN-UNKNOWN REF:	MOS HRS/MSC AFL	120	+14d/-14d	TSN:0 TSN:0 TSN:0	18-OCT-2006 7080.9 4896	18-OCT-2016	01-NOV-2016	LIFE LIMIT 2538 d	
CHAPTER 36 PNEUMATIC										
05-11-00-M3610011	REPLACE ENGINE BLEED AIR CHECK VALVES MOS HRS/MSC REF:	2400	+25/-25			30-JUL-2007 7923 5140	10323	10348	2310.7	
360001	REPLACE LEFT ENGINE PYLON BLEED AIR SEALS MOS HRS/MSC REF: AMM 36-10-01	1200	+25/-25			28-JAN-2008 7706.7 5364	8906.7	8931.7	894.4	
360002	REPLACE RIGHT ENGINE PYLON BLEED AIR SEALS MOS HRS/MSC REF: AMM 36-10-01	1200	+25/-25			28-JAN-2008 7706.7 5364	8906.7	8931.7	894.4	
360003	REPLACE TAILCONE BLEED AIR SEALS (LOCATED BETWEEN THE FORWARD BLEED AIR MANIFOLD AND AFT BLEED AIR MANIFOLD) (REFER TO 36-10-01) MOS HRS/MSC REF: AMM 36-10-01	1200	+25/-25			13-NOV-2006 7109.1 4913	8309.1	8334.1	296.8	
361001	VALVE:NO. 1 BLEED AIR REGULATING/SHUTOFF VALVE 23E64-2 SN-UNKNOWN REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0	01-FEB-1996 0 0				
361002	VALVE:NO. 2 BLEED AIR REGULATING/SHUTOFF VALVE 23E64-2 SN-UNKNOWN REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0	01-FEB-1996 0 0				
361007	CONTROL BOX:LEFT MIXING VALVE CONTROL BOX 5418553-14 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0	01-FEB-1996 0 0				
361008	CONTROL BOX:RIGHT MIXING VALVE CONTROL BOX 1H106-7 5AM22 REF:	MOS HRS/MSC AFL	O/C		TSN:0 TSN:0 TSN:0	06-OCT-1996 245.7 146				
361011	VALVE:LEFT ENGINE BLEED AIR MIXTURE VALVE 1H106-9 6AU46 REF:	MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0	11-FEB-2004 5974.1				

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION	NEXT DUE		TIME REMAINING
							COMPLIANCE (ENH)	ACTUAL	MAX LIMIT	
361012	VALVE:RIGHT ENGINE BLEED AIR MIXTURE VALVE 1H106-9 1AM7 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			27-SEP-2008			
361013	CHECK VALVE:NO. 1 BLEED AIR CHECK VALVE 6608295-3 2786 REF: AMM 21-30-14	MOS HRS/MSC AFL	2400	+25/-25 TSN:0 TSN:0 TSN:0			30-JUL-2007 7923 5140	10323	10348	LIFE LIMIT 2310.7
361014	CHECK VALVE:NO. 2 BLEED AIR CHECK VALVE 6608295-3 2256 REF: AMM 21-30-14	MOS HRS/MSC AFL	2400	+25/-25 TSN:0 TSN:0 TSN:0			30-JUL-2007 7923 5140	10323	10348	LIFE LIMIT 2310.7
361037	BOTTLE:NO. 1 EMERGENCY AIR BOTTLE 23111425 294 REF: AMM 36-15-01 Manufacture Date: 31-MAR-1998	MOS HRS/MSC AFL ACH	180	TSN:0 TSN:0 TSN:0			30-NOV-2007 7619 5294	31-MAR-2013		SCRAP 1241 d
+ 361037A	BOTTLE:VISUAL INSPECTION NO. 1 EMERGENCY AIR BOTTLE AND HYDROSTATIC TEST MOS HRS/MSC REF:	MOS HRS/MSC AFL	36				20-APR-2007 7619 5294	20-APR-2010		165 d
+ 361037B	BOTTLE:X-RAY NO. 1 EMERGENCY AIR BOTTLE MOS HRS/MSC REF:	MOS HRS/MSC AFL	36				20-APR-2007 7619 5294	20-APR-2010		165 d
361038	BOTTLE:NO. 2 EMERGENCY AIR BOTTLE 23111425 410 REF: AMM 36-15-01 Manufacture Date: 30-SEP-1999	MOS HRS/MSC AFL	180				07-APR-2009 7943.3 5534	30-SEP-2014		SCRAP 1789 d
+ 361038A	BOTTLE:VISUAL INSPECTION NO. 2 EMERGENCY AIR BOTTLE AND HYDROSTATIC TEST MOS HRS/MSC REF:	MOS HRS/MSC AFL	36				10-SEP-2008	10-SEP-2011		673 d
+ 361038B	BOTTLE:X-RAY NO. 2 EMERGENCY AIR BOTTLE MOS HRS/MSC REF:	MOS HRS/MSC AFL	36				10-SEP-2008	10-SEP-2011		673 d
362001	INDICATOR:LANDING GEAR/BRAKE PRESSURE INDICATOR 6608401-12 117 REF: AMM 36-20-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			24-OCT-1996 300.7 182			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
362003	TRANSUCER:PRIMARY EMERGENCY AIR SYSTEM PRESSURE TRANSUCER 123091-5 SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
362004	TRANSUCER:SECONDARY EMERGENCY AIR SYSTEM PRESSURE TRANSUCER 123091-5 SN-UNKNOWN REF: AMM 36-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
362011	THERMOSTAT:NO. 1 ENGINE HI-LIMIT BLEED AIR THERMOSTAT 6600141-3 SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
362012	THERMOSTAT:NO. 2 ENGINE HI-LIMIT BLEED AIR THERMOSTAT 6600141-3 SN-UNKNOWN REF: AMM 36-20-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
362019	SWITCH:NO. 1 INBOARD OVERHEAT SWITCH PN SN-UNKNOWN REF: AMM 36-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
362020	SWITCH:NO. 2 INBOARD OVERHEAT SWITCH PN SN-UNKNOWN REF: AMM 36-20-04	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
CHAPTER 49 AIRBORNE AUXILIARY POWER										
49APU1	APU:APU PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	E/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
CHAPTER 52 DOORS										
+ 05-10-29-L5210025	VISUAL INSPECTION EXTERIOR LWR DOOR STRUCTURE/HINGE FOR CORROSION MOS HRS/MSC REF:	24 HRS/MSC AFL		+14d/-14d			07-APR-2009 7943.3 5534	07-APR-2011	21-APR-2011	517 d
521001	DOOR:UPPER PASSENGER/CREW DOOR 5410501-104 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
521002	DOOR:LOWER PASSENGER/CREW DOOR 5410536-26 SN-UNKNOWN REF: AMM 52-10-00	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
521012	DAMPER:LOWER PASSENGER/CREW DOOR DAMPER 6600425-2 580 REF: AMM 52-10-11	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			24-JAN-1998 1557.5 938			
521091	SEAL:PASSENGER/CREW DOOR SEAL PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
522002	HANDLE:EMERGENCY EXIT / BAGGAGE DOOR HANDLE 5411536-45 SN-UNKNOWN REF: AMM 52-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
522025	DAMPER:EMERGENCY EXIT/BAGGAGE DAMPER 12754-0012-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
522031	SEAL:EMERGENCY EXIT/BAGGAGE DOOR SEAL 1300314 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-JUN-2002 5553.5 3720			
522032	WINDOW:ASSEMBLY, EMERGENCY EXIT/BAGGAGE DOOR WINDOW 6600405-8 0777 REF: AMM 52-20-06	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			03-JUN-2002 5553.5 3720			
522032A	WINDOW:PRISM CHECK ASSEMBLY, EMERGENCY EXIT/BAGGAGE DOOR WINDOW REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C			05-10-29-M5600008	01-FEB-1996 0 0			
523101	DOOR:TAILCONE BAGGAGE DOOR 6011551-1 SN-UNKNOWN REF: AMM 52-31-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
524001	PERFORM AFT AVIONICS DOOR GAP AND MISMATCH INSPECTION (REFER TO 52-40-01) REF: AMM 52-40-01-N5240000	MOS HRS/MSC AFL	24	+14d/-14d			17-JUL-2008 7869.3 5484	17-JUL-2010	31-JUL-2010	253 d
527005	BOX ASSEMBLY:CREW DOOR WARNING BOX ASSEMBLY 5418316-8 SN-UNKNOWN REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
527006	BOX ASSEMBLY:EMERGENCY EXIT DOOR WARNING BOX ASSEMBLY 5418316-10 SN-UNKNOWN REF: AMM 52-70-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
528001	DOOR:LEFT INBOARD MAIN LANDING GEAR DOOR 5422162-23 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
528002	DOOR:RIGHT INBOARD MAIN LANDING GEAR DOOR 5422162-24 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			21-JUN-2005 6413.6 4406			
528003	DOOR:LEFT OUTBOARD MAIN LANDING GEAR DOOR 5422152-11 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
528004	DOOR:RIGHT OUTBOARD MAIN LANDING GEAR DOOR 6022151-008 SN-UNKNOWN REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			21-MAY-2009 7951.4 5542			
528101	DOOR:LEFT NOSE LANDING GEAR DOOR 5410450-19 SN-UNKNOWN REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
528102	DOOR:RIGHT NOSE LANDING GEAR DOOR 5410450-20 SN-UNKNOWN REF: AMM 52-81-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
CHAPTER 53	FUSELAGE									
05-10-30-RVSM-N5313000	PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK (REFER TO 53-11-01) MOS HRS/MSC REF: AMM 53-11-01-N5313000	MOS HRS/MSC AFL	24	+14d/-14d			17-JUL-2008 7869.3 5484	17-JUL-2010	31-JUL-2010	253 d
05-11-00-E5322000	REPLACE KEELBEAM ATTACHMENT BOLTS MOS HRS/MSC REF:	MOS HRS/MSC AFL	144	+14d/-14d			20-MAY-2008 7822.4 5441	20-MAY-2020	03-JUN-2020	3848 d
534001	ATTACH FITTING:NO. 1 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING 6011153 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
534002	ATTACH FITTING:NO. 2 ENGINE FORWARD ENGINE MOUNT ATTACH FITTING 6011153 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
534003	ATTACH FITTING:NO. 1 ENGINE AFT ENGINE MOUNT ATTACH FITTING 6011173 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
534004	ATTACH FITTING:NO. 2 ENGINE AFT ENGINE MOUNT ATTACH FITTING 6011173 SN-UNKNOWN REF: AMM 53-40-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
535001	RADOME:RADOME 5410420-26-526 0071 REF: AMM 53-50-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			02-NOV-2003 5907.2 3991		
+ 535102	INSPECT AFT PRESSURE BULKHEAD REF:	MOS HRS/MSC AFL	12000				01-FEB-1996 0 0	12000	3987.7
CHAPTER 56 WINDOWS									
+ 05-10-29-C5610022L	WINDSHIELD:INSPECT LEFT WINDSHIELD OPTICAL PRISM REF: NDT PART 4 / 56-10-01	MOS HRS/MSC AFL	C/C				07-APR-2009 7943.3 5534		
+ 05-10-29-C5610022R	WINDSHIELD:INSPECT RIGHT WINDSHIELD OPTICAL PRISM REF: NDT PART 4 / 56-10-01	MOS HRS/MSC AFL	C/C				07-APR-2009 7943.3 5534		
05-10-29-C5610023R	WINDSHIELD:INSPECT CO-PILOT (RH) SIDE WINDSHIELD OPTICAL PRISM REF:	MOS HRS/MSC AFL	N/A			7943.3 5534			NOT APPLICABLE
561001	WINDSHIELD:LEFT WINDSHIELD 6600394-002 1294-02-1 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-2008 7751.3 5391		
561002	WINDSHIELD:RIGHT WINDSHIELD 6600394-2 484 REF: AMM 56-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			30-JUN-1997 1013.5 590		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
561009	WINDOW:LEFT COCKPIT CREW WINDOW RF56-11-05 SN-UNKNOWN REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
561010	WINDOW:RIGHT COCKPIT CREW WINDOW 6600402-2 788 REF: AMM 56-10-02	MOS HRS/MSC AFL	O/C				30-MAR-2009 7943.3 5534		
561010A	WINDOW:PRISM CHECK RIGHT COCKPIT CREW WINDOW REF:	MOS HRS/MSC AFL	600		7943.3		30-MAR-2009 7943.3 5534	8543.3	531
562011	WINDOW:LEFT NO. 1 CABIN WINDOW LA6600405-20 1896 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-JAN-2008 7706.7 5364		
+ 562011A	WINDOW:PRISM CHECK LEFT NO. 1 CABIN WINDOW REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534		
562013	WINDOW:LEFT NO.2 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782		
562013A	WINDOW:PRISM CHECK LEFT NO.2 CABIN WINDOW REF:	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534		
562015	WINDOW:LEFT NO. 3 CABIN WINDOW LA6600405-20 1899 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-JAN-2008 7706.7 5364		
562015A	WINDOW:PRISM CHECK LEFT NO. 3 CABIN WINDOW REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534		
562017	WINDOW:LEFT NO. 4 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
562017A	WINDOW:PRISM CHECK LEFT NO. 4 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534			
562019	WINDOW:LEFT NO. 5 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782			
562019A	WINDOW:PRISM CHECK LEFT NO. 5 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534			
562022	WINDOW:RIGHT NO. 1 CABIN WINDOW LA6600405-18 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782			
562022A	WINDOW:PRISM CHECK RIGHT NO. 1 CABIN WINDOW LA6600405-20 1897 REF: AMM 56-20-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5364			
562024	WINDOW:RIGHT NO. 2 CABIN WINDOW LA6600405-20 1897 REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			28-JAN-2008 7706.7 5364			
562024A	WINDOW:PRISM CHECK RIGHT NO. 2 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534			
562026	WINDOW:RIGHT NO.3 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782			
562026A	WINDOW:PRISM CHECK RIGHT NO. 3 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534			
562028	WINDOW:RIGHT NO. 4 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
562028A	WINDOW:PRISM CHECK RIGHT NO. 4 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534			
562030	WINDOW:RIGHT NO. 5 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: AMM 56-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			25-MAY-2006 6926.7 4782			
562030A	WINDOW:PRISM CHECK RIGHT NO. 5 CABIN WINDOW LA6600405-20 SN-UNKNOWN REF: NDT PART 4 / 56-30-01	MOS HRS/MSC AFL	C/C	05-10-29-M5600008			07-APR-2009 7943.3 5534			
CHAPTER 57 WINGS										
+ 05-10-29-L5720012L	PERFORM LEFT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION REF: NDT PART 3 / 57-40-03	MOS HRS/MSC AFL		10000	+25/-25		01-FEB-1996 0 0	10000	10025	4394
+ 05-10-29-L5720012R	PERFORM RIGHT FLAP SUPPORT FITTING-TITANIUM EDDY CURRENT INSPECTION REF: NDT PART 3 / 57-40-03	MOS HRS/MSC AFL		10000	+25/-25		01-FEB-1996 0 0	10000	10025	4394
570001	WING:LEFT WING PN SN-UNKNOWN REF: AMM 57-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
570002	WING:RIGHT WING PN SN-UNKNOWN REF: AMM 57-00-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
572001	WINGLET ASSEMBLY:LEFT WINGLET ASSEMBLY 2822650-43 SN-UNKNOWN REF: AMM 57-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0			
572002	WINGLET ASSEMBLY:RIGHT WINGLET ASSEMBLY 2822650-44 SN-UNKNOWN REF: AMM 57-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0			
572003	LEADING EDGE:LEFT WING LEADING EDGE PN SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
572004	LEADING EDGE:RIGHT WING LEADING EDGE 12225-0059-152 SN-UNKNOWN REF: AMM 57-20-02	MOS HRS/MSC O/C AFL		TSR:0 TSR:0 TSR:0			28-JUL-1999 3066.1 1984		
CHAPTER 71 POWER PLANT									
05-11-00-E7120049L	REPLACE NO. 1 ENGINE AFT MOUNT ATTACH BOLTS	MOS HRS/MSC 20000 AFL					13-APR-2006 6852.5 4737	LIFE LIMIT 26852.5	18840.2
05-11-00-E7120049R	REPLACE NO. 2 ENGINE AFT MOUNT ATTACH BOLTS	MOS HRS/MSC 20000 AFL					13-APR-2006 6852.5 4737	LIFE LIMIT 26852.5	18840.2
05-11-00-G7110021L	REPLACE LEFT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS HRS/MSC O/C AFL					12-APR-2005 6402.8 4394		
05-11-00-G7110021R	REPLACE RIGHT FUEL HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA	MOS HRS/MSC O/C AFL					12-APR-2005 6402.8 4394		
05-11-00-G7110022L	REPLACE LEFT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)	MOS HRS/MSC O/C AFL					12-APR-2005 6402.8 4394		
05-11-00-G7110022R	REPLACE RIGHT HYDRAULIC HOSE ASSEMBLIES INSIDE ENGINE NACELLE AREA (INCLUDING HOSE ASSEMBLIES ATTACHED TO THE HYDRAULIC PUMP AND TERMINATING AT THE FIRE-WALL)	MOS HRS/MSC O/C AFL					12-APR-2005 6402.8 4394		
05-11-00-M7120048L	REPLACE NO. 1 ENGINE FWD MOUNT ATTACH BOLTS	MOS HRS/MSC 20000 AFL					13-APR-2006 6852.5 4737	LIFE LIMIT 26852.5	18840.2
05-11-00-M7120048R	REPLACE NO. 2 ENGINE FWD MOUNT ATTACH BOLTS	MOS HRS/MSC 20000 AFL					13-APR-2006 6852.5 4737	LIFE LIMIT 26852.5	18840.2
712001	FITTING:LEFT ENGINE FORWARD INTERMEDIATE FITTING 6011154 SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC O/C AFL		TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
712002	FITTING:RIGHT ENGINE FORWARD INTERMEDIATE FITTING 6011154 SN-UNKNOWN REF: AMM 71-20-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712005	ISOLATOR:LEFT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-505 SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712006	ISOLATOR:RIGHT ENGINE FORWARD UPPER VIBRATION ISOLATOR 266D0820-505 SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712007	ISOLATOR:LEFT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-501 SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712008	ISOLATOR:RIGHT ENGINE FORWARD LOWER VIBRATION ISOLATOR 266D0820-501 SN-UNKNOWN REF: AMM 71-20-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712009	BEAM:NO. 1 ENGINE FORWARD BEAM 6011153 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712010	BEAM:NO. 2 ENGINE FORWARD BEAM 6011153 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712011	BEAM:NO. 1 ENGINE AFT BEAM 6011170 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712012	BEAM:NO. 2 ENGINE AFT BEAM 6011170 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712015	LINK:LEFT ENGINE LOWER AFT MOUNT LINK 266-0807-505 0573BJ REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2006 6852.5 4737		

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
712015	STABILIZER:NO. 1 ENGINE FORWARD STABILIZER 6011160 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712016	STABILIZER:NO.2 ENGINE FORWARD STABILIZER 6011160 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712016	LINK:RIGHT ENGINE LOWER AFT MOUNT LINK 266-0807-505 0562BJ REF: AMM 71-20-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2006 6852.5 4737		
712035	YOKE:NO. 1 ENGINE FORWARD MOUNT YOKE 266-0803-501 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712036	YOKE:NO. 2 ENGINE FORWARD MOUNT YOKE 266-0803-501 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712039	LINK:NO. 1 ENGINE AFT UPPER MOUNT LINK 266-0807-505 0572BJ REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2006 6852.5 4737		
712040	LINK:NO. 2 ENGINE AFT UPPER MOUNT LINK 266-0807-505 0563BJ REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			13-APR-2006 6852.5 4737		
712043	MOUNT:NO. 1 ENGINE FORWARD MOUNT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712044	MOUNT:NO. 2 ENGINE FORWARD MOUNT PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
712045	MOUNT:NO. 1 ENGINE AFT MOUNT RF71-02-11 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
712046	MOUNT:NO. 2 ENGINE AFT MOUNT RF71-02-11 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
712291	ISOLATOR:NO. 1 ENGINE AFT ISOLATOR 266D0820-503 LK0335 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-SEP-1998 2223.5 1382			
712292	ISOLATOR:NO. 2 ENGINE AFT ISOLATOR 266D0820-503 LK0347 REF:	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-SEP-1998 2223.5 1382			
71EN1 71.EN1	ENGINE:NO. 1 ENGINE 31B4067-02 PCE-305272 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:0 TSN:6090.3			11-AUG-2004 6276.7 4299			
71EN2 71.EN2	ENGINE:NO. 2 ENGINE 31B4067-02 PCE-305273 REF: See Workcard	MOS HRS/MSC AFL	E/C	TSN:0 TSN:6090.3			11-AUG-2004 6276.7 4299			
T71T01	REMOVAL/INSTALLATION POWERPLANT MOS HRS/MSC REF:	MOS HRS/MSC AFL	O/C				01-FEB-1996 0 0			
T78T01	REMOVAL/INSTALLATION THRUST REVERSER ASSEMBLY MOS HRS/MSC REF:	MOS HRS/MSC AFL	O/C				01-FEB-1996 0 0			
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02										
+ 05-P&W-710001	NO. 1 ENGINE - PERFORM OVERHAUL ENGINE MOS HRS/MSC REF:	MOS HRS/MSC ENC	6000	+100			13-JUL-2004 6090.3 4124	(12090.3) 12260	12190.3	4247.7
+ 05-P&W-710006	NO. 1 ENGINE - PERFORM HOT SECTION INSPECTION MOS HRS/MSC REF:	MOS HRS/MSC ENC	3000	+100			13-JUL-2004 6090.3 4124	(9090.3) 9260	9190.3	1247.7
05-P&W-710015	NO. 1 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS MOS HRS/MSC REF:	MOS HRS/MSC ENC	1200				15-MAY-2006 6727.5 4610	(7927.5) 8097.2		84.9

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
05-P&W-710017	NO. 1 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR	MOS				15-NOV-2007				
	REF:	HRS/MSC ENC	600			7431 5123	(8031)	8200.7	188.4	
05-P&W-710019	NO. 1 ENGINE - REPLACE BLEED OFF VALVE SOLENOID	MOS				24-MAR-2009				
	REF: EMM 75-30-02	HRS/MSC ENC	1500	+300/-300		7773.6 5378	(9273.6)	9443.3	1431	
05-P&W-710020	NO. 1 ENGINE - VISUALLY CHECK AND/OR REPLACE N1 SPEED SENSORS	MOS				13-JUL-2004				
	REF:	HRS/MSC ENC	3000			6090.3 4124	(9090.3)	9260	1247.7	
710000	NO. 1 ENGINE - COMPRESSOR WASH	DAYS				10-JUL-2000				
	REF:	HRS/MSC ENC	A/R			4006.4 2630				
710050	NO. 1 ENGINE - RUN ENGINES	DAYS	7			04-NOV-2009		11-NOV-2009	5 d	
	REF:	HRS/MSC ENC				7842.6 5450				
715020	HARNES: NO. 1 ENGINE - ENGINE WIRE HARNES	MOS		TSN:0		15-DEC-1995				
	31B4553-01	HRS/MSC	O/C	TSN:0						
	MND00069	ENC		TSN:0						
	REF: EMM 73-20-03									
715025	ALTERNATOR: NO. 1 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR	MOS		TSN:0		01-DEC-1995				
	PN	HRS/MSC	O/C	TSN:0		0				
	SN-UNKNOWN	ENC		TSN:0		0				
	REF: EMM 72-60-01									
M7120068	NO. 1 ENGINE - INSPECT NO. 1 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS	MOS				13-JUL-2004				
	REF:	HRS/MSC ENC	A/R			6090.3 4124				
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02										
+ 05-P&W-710001	NO. 2 ENGINE - PERFORM OVERHAUL ENGINE	MOS	168	+12m		19-JUL-2004		19-JUL-2018	19-JUL-2019	3177 d
	REF:	HRS/MSC ENC	6000	+100		6090.3 4124	(12090.3)	12260	12190.3	4247.7
+ 05-P&W-710006	NO. 2 ENGINE - PERFORM HOT SECTION INSPECTION	MOS				19-JUL-2004				
	REF:	HRS/MSC ENC	3000	+100		6090.3 4124	(9090.3)	9260	9190.3	1247.7

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION	NEXT DUE		TIME REMAINING
							COMPLIANCE (ENH)	ACTUAL	MAX LIMIT	
05-P&W-710015	NO. 2 ENGINE - PERFORM CHECK AND CLEAN PMA HARNESS CONNECTORS	MOS					15-MAY-2006			
	REF:	HRS/MSC ENC	1200				6727.5 4610	(7927.5)	8097.2	84.9
05-P&W-710017	NO. 2 ENGINE - INSPECT AND CLEAN P1/T1 SENSOR CONNECTOR	MOS					15-NOV-2007			
	REF:	HRS/MSC ENC	600				7431 5123	(8031)	8200.7	188.4
05-P&W-710019	NO. 2 ENGINE - REPLACE BLEED OFF VALVE SOLENOID	MOS					24-MAR-2009			
	REF: EMM 75-30-02	HRS/MSC ENC	1500	+300/-300			7773.6 5378	(9273.6)	9443.3	1431
05-P&W-710020	NO. 2 ENGINE - VISUALLY CHECK AND/OR REPLACE N1 SPEED SENSORS	MOS					19-JUL-2004			
	REF:	HRS/MSC ENC	3000				6090.3 4124	(9090.3)	9260	1247.7
710000	NO. 2 ENGINE - COMPRESSOR WASH	DAYS					10-JUL-2000			
	REF:	HRS/MSC ENC	A/R				4006.4 2630			
710050	NO. 2 ENGINE - RUN ENGINES	DAYS	7				04-NOV-2009	11-NOV-2009		5 d
	REF:	HRS/MSC ENC					7842.6 5450			
715020	HARNESS:NO. 2 ENGINE - ENGINE WIRE HARNESS	MOS					18-DEC-1995			
	REF: EMM 73-20-03	HRS/MSC ENC	O/C				TSN:0 TSN:0 TSN:0			
715025	ALTERNATOR:NO. 2 ENGINE - PERMANENT MAGNET (PMA) ALTERNATOR	MOS					01-DEC-1995			
	REF: EMM 72-60-01	HRS/MSC ENC	O/C				0 0			
M7120068	NO. 2 ENGINE - INSPECT NO. 2 ENGINE FORWARD AND AFT MOUNT ISOLATORS AND ASSOCIATED PARTS	MOS					19-JUL-2004			
	REF:	HRS/MSC ENC	A/R				6090.3 4124			

CHAPTER 72 ENGINE

ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02

720000	NO. 1 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION	MOS	168				13-JUN-2004	13-JUN-2018		3141 d
	REF:	HRS/MSC ENC	-				6090.3 4124			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
723001	HUB:NO. 1 ENGINE - FAN HUB 30B2256 13B491 REF: EMM 72-30-01	MOS HRS/MSC ENC	12000	TSN:0 TSN:6090.3 TSN:4124			13-JUL-2004 6090.3 4124	12000	LIFE LIMIT	6550
723002	CASE ASSEMBLY:NO. 1 ENGINE - FAN CASE ASSEMBLY 31B5237-01 5K762 REF: EMM 72-30-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			13-JUL-2004 6090.3 4124			
723003	IMPELLER:NO. 1 ENGINE - CENTRIFUGAL IMPELLER 30B2486 3F476 REF: EMM 72-30-01	MOS HRS/MSC ENC	12000	TSN:0 TSN:6090.3 TSN:4124			13-JUL-2004 6090.3 4124	12000	LIFE LIMIT	6550
723004	NO. 1 ENGINE - PRESSURE CHECK IMPELLER SHROUD REF:	MOS HRS/MSC ENC	N/A				01-DEC-1995 0 0			
723005	ROTOR:NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B2260 12B283 REF: EMM 72-30-01	MOS HRS/MSC ENC	12000	TSN:0 TSN:6090.3 TSN:4124			13-JUL-2004 6090.3 4124	12000	LIFE LIMIT	6550
723005A	ROTOR:NO. 1 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR REF: EMM 72-00-00	MOS HRS/MSC ENC	300 +25				24-MAR-2009 7773.6 5378	(8073.6) 8243.3		231
723008	ROTOR:NO. 1 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 30B4745-01 55B903 REF:	MOS HRS/MSC ENC	8500	TSN:0 TSN:0 TSN:0			13-JUL-2004 6090.3 4124	12624	LIFE LIMIT	7174
+ 723008A	ROTOR:NO. 1 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM REF:	MOS HRS/MSC ENC	O/C				06-OCT-1996			
724010	NO. 1 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM) REF:	MOS HRS/MSC ENC	3000				13-JUL-2004 6090.3 4124	(9090.3) 9260		1247.7
+ 724030	NO. 1 ENGINE - BORESCOPE COMBUSTION LINER REF:	MOS HRS/MSC ENC	O/C				01-DEC-1995 0 0			

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
+ 725001	VANE-RING:NO. 1 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING 30B3012CL01 SN-UNKNOWN REF: EMM 72-50-01	MOS HRS/MSC ENC	O/C				13-JUL-2004 6090.3 4124			
725003	CASE ASSEMBLY:NO. 1 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 30A1426 1F702 REF: EMM 72-50-03	MOS HRS/MSC ENC	O/C				15-DEC-1995 TSN:0 TSN:0 TSN:0			
725101	DISC:NO. 1 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A000K0YL REF: EMM 72-50-01	MOS HRS/MSC ENC		3100			13-JUL-2004 6090.3 4124	6031		581
725102	DISC:NO. 1 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A000LMCH REF: EMM 72-50-01	MOS HRS/MSC ENC		3300			13-JUL-2004 6090.3 4124	6231		781
725103	DISC:NO. 1 ENGINE - STAGE 3 TURBINE DISC 30A1102 58A043 REF: EMM 72-50-01	MOS HRS/MSC ENC		7500			13-JUL-2004 6090.3 4124	7500		2050
725104	DISC:NO. 1 ENGINE - STAGE 4 TURBINE DISC 30A1565 49A986 REF: EMM 72-50-01	MOS HRS/MSC ENC		7500			13-JUL-2004 6090.3 4124	7500		2050
725105	DISC:NO. 1 ENGINE - STAGE 5 TURBINE DISC 30A1104 58A149 REF: EMM 72-50-01	MOS HRS/MSC ENC		7500			13-JUL-2004 6090.3 4124	7500		2050
725107	COVER:NO. 1 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A000H2H0 REF: EMM 72-50-01	MOS HRS/MSC ENC		4800			13-JUL-2004 6090.3 4124	7731		2281
725109	COVER:NO. 1 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B2747-01 A000L1F9 REF: EMM 72-50-01	MOS HRS/MSC ENC		4400			13-JUL-2004 6090.3 4124	7331		1881
725111	SEAL:NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 WG000445 REF: EMM 72-50-01	MOS HRS/MSC ENC		4000			13-JUL-2004 6090.3 4124	6931		1481

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
726001	HOUSING:NO. 1 ENGINE - ACCESSORY GEARBOX HOUSING 31B5065-01 6H489 REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-DEC-1995		
727001	LINER:NO. 1 ENGINE - COMBUSTION CHAMBER LINER 31B2705 1H194 REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C				09-SEP-1998 2223.5 1382		
+ 727001A	LINER:NO. 1 ENGINE - INSPECT COMBUSTION CHAMBER LINER REF: EMM 72-40-01	MOS HRS/MSC ENC	3000				13-JUL-2004 6090.3 4124	(9090.3) 9260	1247.7
727002	LINER ASSEMBLY:NO. 1 ENGINE - INNER COMBUSTION LINER ASSEMBLY 30B4561-01 A000YBBA REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			13-JUL-2004 6090.3 4124		
727003	LINER ASSEMBLY:NO. 1 ENGINE - OUTER COMBUSTION LINER ASSEMBLY 30B4562-01 A001FRE7 REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-JUL-2004 6090.3 4124		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02									
720000	NO. 2 ENGINE - IN SERVICE LOW UTILIZATION INSPECTION REF:	MOS HRS/MSC ENC	168 -				13-JUN-2004 6090.3 4124	VENDOR RECOMMENDATION 13-JUN-2018	3141 d
723001	HUB:NO. 2 ENGINE - FAN HUB 30B2256 13B487 REF: EMM 72-30-01	MOS HRS/MSC ENC		TSN:0 TSN:6090.3 TSN:4124			19-JUL-2004 6090.3 4124		LIFE LIMIT 6550
723002	CASE ASSEMBLY:NO. 2 ENGINE - FAN CASE ASSEMBLY 31B5237-01 1F562 REF: EMM 72-30-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			19-JUL-2004 6090.3 4124		
723003	IMPELLER:NO. 2 ENGINE - CENTRIFUGAL IMPELLER 30B2486 3F398 REF: EMM 72-30-01	MOS HRS/MSC ENC		TSN:0 TSN:6090.3 TSN:4124			19-JUL-2004 6090.3 4124		LIFE LIMIT 6550
723004	NO. 2 ENGINE - PRESSURE CHECK IMPELLER SHROUD REF:	MOS HRS/MSC ENC	N/A				01-DEC-1995 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
723005	ROTOR:NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR 30B2260 12B295 REF: EMM 72-30-01	MOS HRS/MSC ENC		TSN:0 TSN:6090.3 TSO:0 TSN:4124			19-JUL-2004 6090.3 4124	12000	LIFE LIMIT	6550
723005A	ROTOR:NO. 2 ENGINE - EDDY CURRENT INSPECT STAGE 1 COMPRESSOR ROTOR REF: EMM 72-00-00	MOS HRS/MSC ENC	300 +25				24-MAR-2009 7773.6 5378	(8073.6) 8243.3		231
723008	ROTOR:NO. 2 ENGINE - HPC (2ND-,3RD- AND 4TH STAGE) ROTOR 31B6325-01 57A203 REF:	MOS HRS/MSC ENC	8500	TSO:0 TSN:0 TSN:0			19-JUL-2004 6090.3 4124	12624	LIFE LIMIT	7174
+ 723008A	ROTOR:NO. 2 ENGINE - BORESCOPE HPC (2ND-,3RD- AND 4TH STAGE) ROTOR DRUM REF:	MOS HRS/MSC ENC	O/C				06-OCT-1996			
724010	NO. 2 ENGINE - BORESCOPE WORKSCOPE ENGINE CONDITION TREND MONITORING (ECTM) REF:	MOS HRS/MSC ENC	3000				19-JUL-2004 6090.3 4124	(9090.3) 9260		1247.7
+ 724030	NO. 2 ENGINE - BORESCOPE COMBUSTION LINER REF:	MOS HRS/MSC ENC	O/C				19-JUL-2004 6090.3 4124			
+ 725001	VANE-RING:NO. 2 ENGINE - STAGE 2 TURBINE ASSEMBLY VANE-RING PN SN-UNKNOWN REF: EMM 72-50-01	MOS HRS/MSC ENC	O/C				28-AUG-1998 2223.5 1382			
725003	CASE ASSEMBLY:NO. 2 ENGINE - TURBINE EXHAUST CASE ASSEMBLY 30A1426 IF706 REF: EMM 72-50-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-DEC-1995			
725101	DISC:NO. 2 ENGINE - STAGE 1 TURBINE DISC 30B2981-01 A000K10B REF: EMM 72-50-01	MOS HRS/MSC ENC	3100	TSN:0 TSN:1803.5 TSO:0 TSN:1193			19-JUL-2004 6090.3 4124	6031	LIFE LIMIT	581
725102	DISC:NO. 2 ENGINE - STAGE 2 TURBINE DISC 30B2912-01 A000LMCN REF: EMM 72-50-01	MOS HRS/MSC ENC	3300	TSN:0 TSN:1803.5 TSN:1193			19-JUL-2004 6090.3 4124	6231	LIFE LIMIT	781

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
725103	DISC:NO. 2 ENGINE - STAGE 3 TURBINE DISC 30A1102 11B268 REF: EMM 72-50-01	MOS HRS/MSC ENC	7500	TSN:0 TSO:0 TSN:6090.3 TSN:4124			19-JUL-2004 6090.3 4124	7500	LIFE LIMIT	2050
725104	DISC:NO. 2 ENGINE - STAGE 4 TURBINE DISC 30A1565 50A107 REF: EMM 72-50-01	MOS HRS/MSC ENC	7500	TSN:0 TSN:6090.3 TSO:0 TSN:4124			19-JUL-2004 6090.3 4124	7500	LIFE LIMIT	2050
725105	DISC:NO. 2 ENGINE - STAGE 5 TURBINE DISC 30A1104 58A146 REF: EMM 72-50-01	MOS HRS/MSC ENC	7500	TSN:0 TSO:0 TSN:6090.3 TSO:0 TSN:4124			19-JUL-2004 6090.3 4124	7500	LIFE LIMIT	2050
725107	COVER:NO. 2 ENGINE - FRONT HIGH PRESSURE TURBINE COVER 30B2748-01 A000KXW0 REF: EMM 72-50-01	MOS HRS/MSC ENC	4800	TSN:0 TSO:0 TSN:1803.5 TSN:1193			19-JUL-2004 6090.3 4124	7731	LIFE LIMIT	2281
725109	COVER:NO. 2 ENGINE - REAR HIGH PRESSURE TURBINE COVER 30B2747-01 A000L1F2 REF: EMM 72-50-01	MOS HRS/MSC ENC	4400	TSN:0 TSN:1803.5 TSN:1193			19-JUL-2004 6090.3 4124	7331	LIFE LIMIT	1881
725111	SEAL:NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR AIR SEAL 30B2793-01 WG000440 REF: EMM 72-50-01	MOS HRS/MSC ENC	4000	TSN:0 TSO:0 TSN:1803.5 TSN:1193			19-JUL-2004 6090.3 4124	6931	LIFE LIMIT	1481
726001	HOUSING:NO. 2 ENGINE - ACCESSORY GEARBOX HOUSING 31B5065-01 6H458 REF: EMM 72-60-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-DEC-1995			
727001	LINER:NO. 2 ENGINE - COMBUSTION CHAMBER LINER PN SN-UNKNOWN REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0			
+ 727001A	LINER:NO. 2 ENGINE - INSPECT COMBUSTION CHAMBER LINER REF: EMM 72-40-01	MOS HRS/MSC ENC	3000				19-JUL-2004 6090.3 4124	(9090.3) 9260		1247.7
727002	LINER ASSEMBLY:NO. 2 ENGINE - INNER COMBUSTION LINER ASSEMBLY 30B4561-01 A001FXWK REF: EMM 72-40-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			19-JUL-2004 6090.3 4124			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3 Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
727003	LINER ASSEMBLY:NO. 2 ENGINE - OUTER COMBUSTION LINER ASSEMBLY								
	30B4562-01	MOS		TSN:0			19-JUL-2004		
	A001EXB2	HRS/MSC	O/C	TSN:0			6090.3		
	REF: EMM 72-40-01	ENC		TSN:0			4124		
CHAPTER 73 ENGINE FUEL AND CONTROL									
731055	CABLE:NO. 1 ENGINE EMERGENCY FUEL SHUTOFF CABLE								
	PN	MOS		TSN:0			01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
731056	CABLE:NO. 2 ENGINE EMERGENCY FUEL SHUTOFF CABLE								
	PN	MOS		TSN:0			01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
733101	TRANSMITTER:LEFT ENGINE FUEL FLOW TRANSMITTER								
	7600021-1	MOS		TSN:0			15-NOV-2007		
	601001	HRS/MSC	O/C	TSN:0			7600.7		
	REF: AMM 73-31-01	AFL		TSN:0			5279		
733102	TRANSMITTER:RIGHT ENGINE FUEL FLOW TRANSMITTER								
	6608488-001	MOS		TSN:0			28-JUN-2001		
	3829	HRS/MSC	O/C	TSN:0			4735.7		
	REF: AMM 73-31-01	AFL		TSN:0			3154		
733103	INDICATOR:LEFT ENGINE FUEL FLOW INDICATOR								
	62000-002	MOS					24-AUG-2008		
	3596	HRS/MSC	O/C				7908.8		
	REF: AMM 73-31-02	AFL					5508		
733104	INDICATOR:RIGHT ENGINE FUEL FLOW INDICATOR								
	62000-002	MOS					24-AUG-2008		
	3829	HRS/MSC	O/C				7908.8		
	REF: AMM 73-31-02	AFL					5508		
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02									
05-P&W-730001	NO. 1 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT								
		MOS	12				07-APR-2009	07-APR-2010	152 d
		HRS/MSC	1200				7773.6	(8973.6) 9143.3	1131
	REF:	ENC					5378		
731001	PUMP:NO. 1 ENGINE - FUEL PUMP								
	30B1910A	MOS		TSO:0			13-JUL-2004		
	MX-560248A	HRS/MSC	O/C	TSO:0			6090.3		
	REF: EMM 73-10-02	ENC		TSO:0			4124		
731002	VALVE:NO. 1 ENGINE - MOTIVE FLOW VALVE								
	3244870-1	MOS		TSO:0			13-JUL-2004		
	C37063	HRS/MSC	O/C	TSO:0			6090.3		
	REF: EMM 73-20-01	ENC		TSO:0			4124		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
731003	SWITCH:NO. 1 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH 30B1669 0353 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-DEC-1995		
731004	FUEL NOZZLE:NO. 1 ENGINE - UPPER PRIMARY FUEL NOZZLE PN SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
731005	FUEL NOZZLE:NO. 1 ENGINE - LOWER PRIMARY FUEL NOZZLE PN SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
731010	VALVE ASSEMBLY:NO. 1 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY 30B1727 SN-UNKNOWN REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
731026	EJECTOR:NO. 1 ENGINE - FUEL WASTE EJECTOR 26100-8 0310 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			13-JUL-2004 6090.3 4124		
731051	VALVE:NO. 1 ENGINE - FUEL START & DUMP VALVE 31B5131-01 0337 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-DEC-1995 0 0		
+ 731120	NO. 1 ENGINE - INSPECT FUEL NOZZLES (EXTENDED TBO AND HSI) REF:	MOS HRS/MSC ENC	3000 +100				13-JUL-2004 6090.3 4124	(9090.3) 9260 9190.3	1247.7
732001	FUEL CONTROL:NO. 1 ENGINE - HYDRO MECHANICAL FUEL CONTROL 1891-11 1891261 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			13-JUL-2004 6090.3 4124		
732003	HARNES:NO. 1 ENGINE - ELECTRICAL FRONT HARNES 31B3718-01 MNA00146 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-DEC-1995		
732004	HARNES:NO. 1 ENGINE - ELECTRICAL REAR HARNES 31B3101-01 MNC00156 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-DEC-1995		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
732101	FADEC:NO. 1 ENGINE - ENGINE FADEC 1240KDC03-005 YM346 REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			06-NOV-1996 305.5 186		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02									
05-P&W-730001	NO. 2 ENGINE - REPLACE ENGINE FUEL FILTER ELEMENT	MOS HRS/MSC ENC	12 1200				07-APR-2009 7773.6 5378	07-APR-2010 (8973.6) 9143.3	152 d 1131
731001	PUMP:NO. 2 ENGINE - FUEL PUMP PF4-038-11C MX-560885A REF: EMM 73-10-02	MOS HRS/MSC ENC		TSO:0 TSO:0 TSO:0			19-JUL-2004 6090.3 4124		
731002	VALVE:NO. 2 ENGINE - MOTIVE FLOW VALVE 3244870-1 C37080 REF: EMM 73-20-01	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			19-JUL-2004 6090.3 4124		
731003	SWITCH:NO. 2 ENGINE - FUEL FILTER BYPASS INDICATOR SWITCH TD330MF058 0101 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			19-JUL-2004 6090.3 4124		
731004	FUEL NOZZLE:NO. 2 ENGINE - UPPER PRIMARY FUEL NOZZLE PN SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
731005	FUEL NOZZLE:NO. 2 ENGINE - LOWER PRIMARY FUEL NOZZLE PN SN-UNKNOWN REF: EMM 73-10-04	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
731010	VALVE ASSEMBLY:NO. 2 ENGINE - FUEL SHUTOFF VALVE ASSEMBLY 30B1727 SN-UNKNOWN REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
731026	EJECTOR:NO. 2 ENGINE - FUEL WASTE EJECTOR 31B5132-01 0309 REF: EMM 73-10-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-DEC-1995 0 0		
731051	VALVE:NO. 2 ENGINE - FUEL START & DUMP VALVE 31B5131-01 0309 REF: EMM 73-10-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-DEC-1995 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								NEXT DUE ACTUAL	MAX LIMIT	
+ 731120	NO. 2 ENGINE - INSPECT FUEL NOZZLES (EXTENDED TBO AND HSI)	MOS					19-JUL-2004			
		HRS/MSC	3000	+100			6090.3	(9090.3) 9260	9190.3	1247.7
	REF:	ENC					4124			
732001	FUEL CONTROL:NO. 2 ENGINE - HYDRO MECHANICAL FUEL CONTROL	MOS					19-JUL-2004			
	1891-11	HRS/MSC	O/C				6090.3			
	1891240	ENC					4124			
	REF: EMM 73-20-01									
732003	HARNES: NO. 2 ENGINE - ELECTRICAL FRONT HARNES	MOS					18-DEC-1995			
	31B3718-01	HRS/MSC	O/C							
	MNA00144	ENC								
	REF: EMM 73-20-03									
732004	HARNES: NO. 2 ENGINE - ELECTRICAL REAR HARNES	MOS					18-DEC-1995			
	31B3101-01	HRS/MSC	O/C							
	MNC00157	ENC								
	REF: EMM 73-20-03									
732101	FADEC:NO. 2 ENGINE - ENGINE FADEC	MOS					21-FEB-1997			
	31B741-04	HRS/MSC	O/C				616			
	YM552	ENC					370			
	REF: EMM 73-20-03									
CHAPTER 74 IGNITION										
743003	BOX:ENGINE WARNING LIGHT BOX	MOS					01-FEB-1996			
	6018314-3	HRS/MSC	O/C				0			
	SN-UNKNOWN	AFL					0			
	REF: AMM 74-30-03									
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02										
741001	EXCITER:NO. 1 ENGINE - NO. 1 IGNITION EXCITER	MOS					25-MAY-2006			
	9047980-21	HRS/MSC	O/C				6757.8			
	90030014	ENC					4626			
	REF: EMM 74-10-01									
741002	EXCITER:NO. 1 ENGINE - NO. 2 IGNITION EXCITER	MOS					25-MAY-2006			
	9047980-21	HRS/MSC	O/C				6757.8			
	NN01149323	ENC					4626			
	REF: EMM 74-10-01									
742025	PLUG:NO. 1 ENGINE - NO. 1 IGNITER PLUG	MOS					07-APR-2009			
	31B5168-01	HRS/MSC	O/C				7773.6			
	SN-UNKNOWN	ENC					5378			
	REF: EMM 74-10-01									
742026	PLUG:NO. 1 ENGINE - NO. 2 IGNITER PLUG	MOS					07-APR-2009			
	31B5168-01	HRS/MSC	O/C				7773.6			
	SN-UNKNOWN	ENC					5378			
	REF: EMM 74-10-01									

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
WORKCARD	PART#/PKG SERIAL #									
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02										
741001	EXCITER:NO. 2 ENGINE - NO. 1 IGNITION EXCITER 31B4636-02 NN95190061 REF: EMM 74-10-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			19-FEB-1996 0 0			
741002	EXCITER:NO. 2 ENGINE - NO. 2 IGNITION EXCITER 31B4636-02 NN95190073 REF: EMM 74-10-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			19-FEB-1996 0 0			
742025	PLUG:NO. 2 ENGINE - NO. 1 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			07-APR-2009 7773.6 5378			
742026	PLUG:NO. 2 ENGINE - NO. 2 IGNITER PLUG 31B5168-01 SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			07-APR-2009 7773.6 5378			

CHAPTER 75 AIR

ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02										
05-P&W-750001	NO. 1 ENGINE - INSPECT AND CLEAN P2.5 & P2.8 BLEED VALVES MOS HRS/MSC 3000 REF: ENC						13-JUL-2004 6090.3 4124	(9090.3) 9260		1247.7
751001	VALVE:NO. 1 ENGINE - ANTI-ICING SOLENOID VALVE 31B5108-01 AL99 REF: EMM 75-10-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			15-APR-1999 2825.3 1795			
753004	ACTUATOR:NO. 1 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR 31B5255-01 2600033 REF: EMM 75-30-02	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			15-DEC-1995			
753005	ACTUATOR:NO. 1 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR 31B5255-01 2600033 REF: EMM 75-30-02	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			15-DEC-1995 0 0			
753081	SOLENOID:NO. 1 ENGINE - COMPRESSOR BLEED VALVE SOLENOID 31B4197-04 889 REF: EMM 75-30-02	MOS HRS/MSC O/C ENC		TSO:0 TSO:0 TSO:0			24-MAR-2009 7773.6 5378			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
753101	VALVE:NO. 1 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 20A984 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			13-JUL-2004 6090.3 4124		
753102	VALVE:NO. 1 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 20A993 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			13-JUL-2004 6090.3 4124		
753105	VALVE:NO. 1 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 21A611 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			13-JUL-2004 6090.3 4124		
754001	TRANSDUCER:NO. 1 ENGINE - PRESSURE P3 TRANSDUCER PN SN-UNKNOWN REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02									
05-P&W-750001	NO. 2 ENGINE - INSPECT AND CLEAN P2.5 & P2.8 BLEED VALVES MOS HRS/MSC REF:	3000 ENC					19-JUL-2004 6090.3 4124	(9090.3) 9260	1247.7
751001	VALVE:NO. 2 ENGINE - ANTI-ICING SOLENOID VALVE 30B1704 SN-UNKNOWN REF: EMM 75-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
753004	ACTUATOR:NO. 2 ENGINE - LINEAR STATOR VANE (POST SB24369) ACTUATOR 2600-1 2600442 REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			19-JUL-2004 6090.3 4124		
753005	ACTUATOR:NO. 2 ENGINE - ROTARY STATOR VANE (PRE SB24369) ACTUATOR 30B1782 SN-UNKNOWN REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
753081	SOLENOID:NO. 2 ENGINE - COMPRESSOR BLEED VALVE SOLENOID 31B4197-04 227 REF: EMM 75-30-02	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			24-MAR-2009 7773.6 5378		
753101	VALVE:NO. 2 ENGINE - INBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 32A590 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			19-JUL-2004 6090.3 4124		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
753102	VALVE:NO. 2 ENGINE - OUTBOARD COMPRESSOR BLEED - P2.5 VALVE 31B5759-01 32A592 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			19-JUL-2004 6090.3 4124		
753105	VALVE:NO. 2 ENGINE - COMPRESSOR BLEED - P2.8 VALVE 31B5756-01 27A086 REF: EMM 75-30-01	MOS HRS/MSC ENC	O/C	TSR:0 TSR:0 TSR:0			19-JUL-2004 6090.3 4124		
754001	TRANSDUCER:NO. 2 ENGINE - PRESSURE P3 TRANSDUCER PN SN-UNKNOWN REF: EMM 75-30-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		

CHAPTER 76 ENGINE CONTROLS

761001	QUADRANT ASSEMBLY:THROTTLE/THRUST REVERSER QUADRANT ASSEMBLY 6015201-3 SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
761003	TRANSFORMER:LEFT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER 3A2-240B SN-UNKNOWN REF: AMM 76-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
761004	TRANSFORMER:RIGHT ENGINE ROTARY VARIABLE DIFFERENTIAL (RVDT) TRANSFORMER 3A2-240A SN-UNKNOWN REF: AMM 76-10-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02

761101	HARNESS:NO. 1 ENGINE - FADEC, ENGINE TAILCONE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
761103	HARNESS:NO. 1 ENGINE - FADEC, ENGINE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
761105	HARNESS:NO. 1 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
761107	HARNESS:NO. 1 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNESS PN SN-UNKNOWN REF: EMM 73-20-03	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE	
WORKCARD	PART#/PKG SERIAL #						ACTUAL	MAX LIMIT	
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02									
761101	HARNES: NO. 2 ENGINE - FADEC, ENGINE TAILCONE HARNES								
	PN	MOS		TSN:0			01-DEC-1995		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-03	ENC		TSN:0			0		
761103	HARNES: NO. 2 ENGINE - FADEC, ENGINE HARNES								
	PN	MOS		TSN:0			01-DEC-1995		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-03	ENC		TSN:0			0		
761105	HARNES: NO. 2 ENGINE - CHANNEL A FADEC, ENGINE NACELLE HARNES								
	PN	MOS		TSN:0			01-DEC-1995		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-03	ENC		TSN:0			0		
761107	HARNES: NO. 2 ENGINE - CHANNEL B FADEC, ENGINE NACELLE HARNES								
	PN	MOS		TSN:0			01-DEC-1995		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-20-03	ENC		TSN:0			0		
CHAPTER 77 ENGINE INDICATING									
771001	INDICATOR: LEFT ENGINE N1 INDICATOR								
	64500-001	MOS		TSN:0			01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 77-10-01	AFL		TSN:0			0		
771002	INDICATOR: RIGHT ENGINE N1 INDICATOR								
	64500-001	MOS		TSN:0			01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 77-10-01	AFL		TSN:0			0		
771003	INDICATOR: LEFT ENGINE N2 INDICATOR								
	64000-001	MOS		TSN:0			01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 77-10-02	AFL		TSN:0			0		
771004	INDICATOR: RIGHT ENGINE N2 INDICATOR								
	64000-001	MOS		TSN:0			01-FEB-1996		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: AMM 77-10-02	AFL		TSN:0			0		
772001	INDICATOR: LEFT ENGINE ITT INDICATOR								
	6608505-001	MOS		TSN:0			13-NOV-2004		
	5889	HRS/MSC	O/C	TSN:0			6386.4		
	REF: AMM 77-20-01	AFL		TSN:0			4385		
772002	INDICATOR: RIGHT ENGINE ITT INDICATOR								
	6608505-001	MOS		TSN:0			16-DEC-2004		
	3438	HRS/MSC	O/C	TSN:0			6386.4		
	REF: AMM 77-20-01	AFL		TSN:0			4385		

?-Insufficient Information (EFF)-Effective C/W

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
772011	BOX:NO. 1 ENGINE N1/T4.5 TERMINAL BOX 30B2749-02 EM63272 REF:	MOS HRS/MSC AFL	O/C	TSN:0			13-JUL-2004		
772012	BOX:NO. 2 ENGINE N1/T4.5 TERMINAL BOX 30B1385 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0			19-JUL-2004		
772013	HARNESS:NO. 1 ENGINE LEFT T4.5 WIRING HARNESS 31B3446-01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
772014	HARNESS:NO. 2 ENGINE LEFT T4.5 WIRING HARNESS 31B3869-01 951051 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-DEC-1995 0 0		
772015	HARNESS:NO. 1 ENGINE RIGHT T4.5 WIRING HARNESS 31B3446-01 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
772016	HARNESS:NO. 2 ENGINE RIGHT T4.5 WIRING HARNESS 31B3869-01 951056 REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			18-DEC-1995 0 0		
774001	DIAGNOSTIC UNIT:EDU (ENGINE DIAGNOSTIC UNIT) 9-361-106 76 REF: AMM 77-40-01	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			28-JAN-2008 7706.7 5364		
774001A	DIAGNOSTIC UNIT:EDS BATTERY REF:	MOS HRS/MSC AFL	36				28-JAN-2008 7706.7 5364	28-JAN-2011	REPLACE 448 d
774002	UNIT:CONTROL AND DISPLAY (CDU) UNIT 622-9576-002 133 REF: AMM 77-40-02	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			17-APR-1999 2829.6 1797		
774003	UNIT:LEFT ENGINE ISOLATION INTERFACE UNIT 9-343-01 SN-UNKNOWN REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
774004	UNIT:RIGHT ENGINE ISOLATION INTERFACE UNIT 9-343-01 SN-UNKNOWN REF: AMM 77-40-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
774101	BOX:SIGNAL CONDITIONING BOX 6600504-3 SN-UNKNOWN REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
774103	ACCELEROMETER:LEFT ENGINE VIBRATION ACCELEROMETER 6600504-2 SN-UNKNOWN REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
774104	ACCELEROMETER:RIGHT ENGINE VIBRATION ACCELEROMETER 6600504-2 SN-UNKNOWN REF: AMM 77-41-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02									
771027	SENSOR:NO. 1 ENGINE - CHANNEL A N1 SPEED SENSOR 31B4915-01 B193 REF: EMM 77-10-01	MOS HRS/MSC ENC	A/R	TSN:0 TSN:0 TSN:0			13-JUL-2004 6090.3 4124		
771028	SENSOR:NO. 1 ENGINE - CHANNEL B N1 SPEED SENSOR 31B4916-01 B100 REF: EMM 77-10-01	MOS HRS/MSC ENC	A/R	TSN:0 TSN:0 TSN:0			13-JUL-2004 6090.3 4124		
771040	SENSOR:NO. 1 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 31B5840-01 WE00480 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-DEC-1995		
771041	SENSOR:NO. 1 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449 CH869 REF: EMM 77-10-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			13-JUL-2004 6090.3 4124		
771110	TRANSDUCER:NO. 1 ENGINE - LOW PRESSURE (N1) TRANSDUCER 63604-410-3 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
771120	TRANSDUCER:NO. 1 ENGINE - HIGH PRESSURE (N2) TRANSDUCER 61472-404-2 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
772010	HARNES: NO. 1 ENGINE - T4.5 THERMOCOUPLE HARNES 30B2749-02 EM63272 REF: EMM 77-20-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			13-JUL-2004 6090.3 4124		
772014	SENSOR: NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
772015	SENSOR: NO. 1 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02									
771027	SENSOR: NO. 2 ENGINE - CHANNEL A N1 SPEED SENSOR 31B4915-01 B106 REF: EMM 77-10-01	MOS HRS/MSC A/R ENC		TSN:0 TSN:0 TSN:0			19-JUL-2004 6090.3 4124		
771028	SENSOR: NO. 2 ENGINE - CHANNEL B N1 SPEED SENSOR 31B4916-01 A998 REF: EMM 77-10-01	MOS HRS/MSC A/R ENC		TSN:0 TSN:0 TSN:0			19-JUL-2004 6090.3 4124		
771040	SENSOR: NO. 2 ENGINE - CHANNEL A N2, TURBINE SPEED SENSOR 30B1449J CH3048 REF: EMM 77-10-01	MOS HRS/MSC O/C ENC		TSO:0 TSO:0 TSO:0			19-JUL-2004 6090.3 4124		
771041	SENSOR: NO. 2 ENGINE - CHANNEL B N2, TURBINE SPEED SENSOR 30B1449G CH864 REF: EMM 77-10-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			19-JUL-2004 6090.3 4124		
771110	TRANSDUCER: NO. 2 ENGINE - LOW PRESSURE (N1) TRANSDUCER 63604-410-3 SN-UNKNOWN REF:	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
771120	TRANSDUCER: NO. 2 ENGINE - HIGH PRESSURE (N2) TRANSDUCER 61472-404-2 SN-UNKNOWN REF:	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
772010	HARNES: NO. 2 ENGINE - T4.5 THERMOCOUPLE HARNES 30B2749-02 EM63355 REF: EMM 77-20-01	MOS HRS/MSC O/C ENC		TSN:0 TSN:0 TSN:0			19-JUL-2004 6090.3 4124		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
772014	SENSOR:NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0			
772015	SENSOR:NO. 2 ENGINE - PRESSURE AND TEMPERATURE SENSOR PN SN-UNKNOWN REF: EMM 77-20-02	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0			
CHAPTER 78 EXHAUST										
780001	THRUST REVERSER:LEFT THRUST REVERSER 282-0052-513 0329 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-DEC-2004 6386.4 4385			
780001A	THRUST REVERSER:REPLACE LEFT THRUST REVERSER DOOR DRIVER LINK BOLTS (NAS6305U18D) REF:	MOS HRS/MSC AFL	O/C				01-FEB-1996 0 0			
780001B	THRUST REVERSER:REPLACE LEFT THRUST REVERSER SUPPORT BEAM DRIVER LINK BOLTS (122450-8A49) (ALT PBF1344-8-49D) REF:	MOS HRS/MSC AFL	O/C				01-FEB-1996 0 0			
780001C	THRUST REVERSER:REPLACE LEFT THRUST REVERSER OVER-CENTER LINK DRIVER BOLTS (NAS6304U20D) REF:	MOS HRS/MSC AFL	O/C				01-FEB-1996 0 0			
780001D	THRUST REVERSER:REPLACE LEFT THRUST REVERSER CARRIAGE ASSEMBLY OVER-CENTER LINK BOLTS (NAS6307U15D) REF:	MOS HRS/MSC AFL	O/C				01-FEB-1996 0 0			
780002	THRUST REVERSER:RIGHT THRUST REVERSER 282-0052-501 CUM97 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			16-DEC-2004 6386.4 4385			
780002A	THRUST REVERSER:REPLACE RIGHT THRUST REVERSER DOOR DRIVER LINK BOLTS (NAS6305U18D) REF:	MOS HRS/MSC AFL	O/C				01-FEB-1996 0 0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
780002B	THRUST REVERSER:REPLACE RIGHT THRUST REVERSER SUPPORT BEAM DRIVER LINK BOLTS (122450-8A49) (ALT PBF1344-8-49D)	MOS					01-FEB-1996			
	REF:	HRS/MSC AFL	O/C				0 0			
780002C	THRUST REVERSER:REPLACE RIGHT THRUST REVERSER OVER-CENTER LINK DRIVER LINK BOLTS (NAS6304U20D)	MOS					01-FEB-1996			
	REF:	HRS/MSC AFL	O/C				0 0			
780002D	THRUST REVERSER:REPLACE RIGHT THRUST REVERSER CARRIAGE ASSEMBLY OVER-CENTER LINK BOLTS (NAS6307U15D)	MOS					01-FEB-1996			
	REF:	HRS/MSC AFL	O/C				0 0			
783001	RELAY BOX:LEFT THRUST REVERSER RELAY BOX 6018425-3	MOS		TSN:0			01-FEB-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 78-30-01	AFL		TSN:0			0			
783002	RELAY BOX:RIGHT THRUST REVERSER RELAY BOX 6018425-017	MOS		TSR:0			29-AUG-2006			
	82909K	HRS/MSC	O/C	TSR:0			7025.6			
	REF: AMM 78-30-01	AFL		TSR:0			4854			
783005	CONTROL UNIT:LEFT THRUST REVERSER HYDRAULIC CONTROL UNIT 282D0007-507	MOS		TSR:0			10-JUL-2009			
	0722	HRS/MSC	O/C	TSR:0			7978.1			
	REF: AMM 78-30-03	AFL		TSR:0			5572			
783006	CONTROL UNIT:RIGHT THRUST REVERSER HYDRAULIC CONTROL UNIT 71335-2	MOS		TSN:0			04-APR-2001			
	0317	HRS/MSC	O/C	TSN:0			4534.4			
	REF: AMM 78-30-03	AFL		TSN:0			3020			
783013	DOOR:LEFT ENGINE THRUST REVERSER UPPER DOOR 266-0003-503	MOS		TSN:0			01-FEB-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 78-30-10	AFL		TSN:0			0			
783014	DOOR:RIGHT ENGINE THRUST REVERSER UPPER DOOR 266-0003-503	MOS		TSN:0			01-FEB-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 78-30-10	AFL		TSN:0			0			
783015	DOOR:LEFT ENGINE THRUST REVERSER LOWER DOOR 266-0004-504	MOS		TSN:0			01-FEB-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 78-30-10	AFL		TSN:0			0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING	
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT		
783016	DOOR:RIGHT ENGINE THRUST REVERSER LOWER DOOR 266-0004-504 SN-UNKNOWN REF: AMM 78-30-10	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783105	ACTUATOR:LEFT OUTBOARD THRUST REVERSER ACTUATOR 282T0006-501 SN-UNKNOWN REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783106	ACTUATOR:LEFT INBOARD THRUST REVERSER ACTUATOR 282T0006-501 SN-UNKNOWN REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783107	ACTUATOR:RIGHT INBOARD THRUST REVERSER ACTUATOR 282T0006-501 SN-UNKNOWN REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783108	ACTUATOR:RIGHT OUTBOARD THRUST REVERSER ACTUATOR 282T0006-501 SN-UNKNOWN REF: AMM 78-31-05	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783115	ACTUATOR:LEFT UPPER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783116	ACTUATOR:RIGHT UPPER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783117	ACTUATOR:LEFT LOWER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783118	ACTUATOR:RIGHT LOWER SECONDARY LOCK ACTUATOR 266D0486-501 SN-UNKNOWN REF: AMM 78-31-15	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0			
783132A	FAIRING ASSEMBLY:INSPECT LEFT OUTBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D REF:	MOS HRS/MSC AFL	24 600				07-APR-2009 7943.3 5534	07-APR-2011 8543.3	8543.3	ICA 517 d 531

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	NEXT DUE MAX LIMIT	
783136A	FAIRING ASSEMBLY:INSPECT RIGHT OUTBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D	MOS	24				07-APR-2009	07-APR-2011		ICA 517 d
	REF:	HRS/MSC	600				7943.3	8543.3		531
		AFL					5534			
783142A	FAIRING ASSEMBLY:INSPECT LEFT INBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D	MOS	24				07-APR-2009	07-APR-2011		ICA 517 d
	REF:	HRS/MSC	600				7943.3	8543.3	8543.3	531
		AFL					5534			
783146A	FAIRING ASSEMBLY:INSPECT RIGHT INBOARD STANG FAIRING ASSEMBLY IAW ST02209AT-D IFCA REV. D	MOS	24				07-APR-2009	07-APR-2011	07-APR-2011	ICA 517 d
	REF:	HRS/MSC	600				7943.3	8543.3		531
		AFL					5534			
E7830010A (s)	INSPECT NO. 1 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION PKG 1	MOS					11-AUG-2004			ENGINE CHANGE
	REF:	HRS/MSC	E/C				6276.7			
		AFL					4299			
E7830010B (s)	INSPECT NO. 2 ENGINE UPPER AND LOWER THRUST REVERSER DOORS FOR CRACKS, EVIDENCE OF DOOR TWISTING, LOOSE OR FAILED FASTENERS, FAIRED POSITION OF DOORS, AND SECURITY OF INSTALLATION PKG 2	MOS					11-AUG-2004			ENGINE CHANGE
	REF:	HRS/MSC	E/C				6276.7			
		AFL					4299			
E7830012A (s)	INSPECT NO. 1 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE PKG 1	MOS					11-AUG-2004			ENGINE CHANGE
	REF:	HRS/MSC	E/C				6276.7			
		AFL					4299			
E7830012B (s)	INSPECT NO. 2 ENGINE THRUST REVERSER BARREL ASSEMBLIES FOR CRACKS, SECURITY, AND DAMAGE TO COMPONENTS ATTACHED TO THE BARREL ASSEMBLY AND SECURITY OF INSTALLATION TO FAN DUCT FLANGE PKG 2	MOS					11-AUG-2004			ENGINE CHANGE
	REF:	HRS/MSC	E/C				6276.7			
		AFL					4299			
CHAPTER 79		OIL								
793001	INDICATOR:LEFT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR									
	30B1882	MOS					18-OCT-1997			
	0423	HRS/MSC	O/C				1284.9			
	REF: AMM 79-30-01	AFL					778			
793002	INDICATOR:RIGHT ENGINE OIL PRESSURE/TEMPERATURE INDICATOR									
	65000-001	MOS					01-FEB-1996			
	SN-UNKNOWN	HRS/MSC	O/C				0			
	REF: AMM 79-30-01	AFL					0			

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
793003	TRANSUCER:LEFT ENGINE OIL PRESSURE TRANSUCER 7600019-1 SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
793004	TRANSUCER:RIGHT ENGINE OIL PRESSURE TRANSUCER 7600019-1 SN-UNKNOWN REF: AMM 79-30-02	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
793005	BULB:LEFT ENGINE OIL TEMPERATURE BULB MS28034-3 SN-UNKNOWN REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		
793006	BULB:RIGHT ENGINE OIL TEMPERATURE BULB MS28034-3 SN-UNKNOWN REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			01-FEB-1996 0 0		

ENGINE NO. 1 Model : PW 305 (CIMMS) Serial # PCE-305272 Part # 31B4067-02

05-P&W-790001	NO. 1 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT MOS 12 HRS/MSC 1200 ENC REF:						07-APR-2009 7773.6 5378	07-APR-2010 (8973.6) 9143.3	152 d 1131
05-P&W-790002	NO. 1 ENGINE - PERFORM ENGINE OIL CHANGE MOS 12 HRS/MSC 600 ENC REF:		+50/-50				21-MAY-2009 7781.7 5386	21-MAY-2010 (8381.7) 8551.4	8431.7 196 d 539.1
792001	PUMP:NO. 1 ENGINE - OIL PUMP 31B6168-01 PWV040219P3 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			13-JUL-2004 6090.3 4124		
792002	HEAT EXCHANGER:NO. 1 ENGINE - FUEL/OIL HEAT EXCHANGER 90020-000-B 0409 REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			13-JUL-2004 6090.3 4124		
792005	SWITCH:NO. 1 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH 30B1506 0348 REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			15-DEC-1995		
792010	SWITCH:NO. 1 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH 695-6-24 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		

Model : LEARJET 60 (CIMMS)
Owner : AIR RESOURCE GROUP
Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	DISPOSITION		TIME REMAINING
							COMPLIANCE (ENH)	NEXT DUE ACTUAL MAX LIMIT	
792020	HOUSING:NO. 1 ENGINE - OIL PUMP HOUSING PN SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
793005	DETECTOR:NO. 1 ENGINE - CHIP DETECTOR PN SN-UNKNOWN REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
ENGINE NO. 2 Model : PW 305 (CIMMS) Serial # PCE-305273 Part # 31B4067-02									
05-P&W-790001	NO. 2 ENGINE - REPLACE ENGINE OIL FILTER ELEMENT MOS HRS/MSC ENC REF:	12 1200					07-APR-2009 7773.6 5378	07-APR-2010 (8973.6) 9143.3	152 d 1131
05-P&W-790002	NO. 2 ENGINE - PERFORM ENGINE OIL CHANGE MOS HRS/MSC ENC REF:	12 600	+50/-50				21-MAY-2009 7781.7 5386	21-MAY-2010 (8381.7) 8551.4	196 d 539.1
792001	PUMP:NO. 2 ENGINE - OIL PUMP 31B6168-01 13A700 REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			19-JUL-2004 6090.3 4124		
792002	HEAT EXCHANGER:NO. 2 ENGINE - FUEL/OIL HEAT EXCHANGER 90020-000B 0414 REF: EMM 79-20-02	MOS HRS/MSC ENC	O/C	TSO:0 TSO:0 TSO:0			19-JUL-2004 6090.3 4124		
792005	SWITCH:NO. 2 ENGINE - OIL PRESSURE DIFFERENTIAL SWITCH 30B1506 0344 REF: EMM 79-20-01	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			18-DEC-1995		
792010	SWITCH:NO. 2 ENGINE - ENGINE OIL PRESSURE LIGHT SWITCH 695-6-24 SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
792020	HOUSING:NO. 2 ENGINE - OIL PUMP HOUSING PN SN-UNKNOWN REF: EMM 79-20-05	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		
793005	DETECTOR:NO. 2 ENGINE - CHIP DETECTOR PN SN-UNKNOWN REF: EMM 72-00-00	MOS HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			01-DEC-1995 0 0		

CHAPTER 80 STARTING

?-Insufficient Information
(EFF)-Effective C/W
06-NOV-2009

+ -Task exists in Inspection Manual

(s)-Suppressed Requirement

(EBT)-Estimated Base Time

*-Estimated Due (New Requirement)

Model : LEARJET 60 (CIMMS)
 Owner : AIR RESOURCE GROUP
 Operator : AIR RESOURCE GROUP

A/C Serial #: 60 076 A/C Reg. #: N494PA

Aircraft HRS: 8012.3

Landings: 5606

TASK NO WORKCARD	TASK DESCRIPTION PART#/PKG SERIAL #	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE (ENH)	DISPOSITION		TIME REMAINING
								ACTUAL	MAX LIMIT	
801001	RELAY BOX:CROSS START RELAY BOX									
	6018421-1	MOS		TSN:0			01-FEB-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 80-10-01	AFL		TSN:0			0			
801002	RELAY BOX:AIR START RELAY BOX									
	6018358-2	MOS		TSN:0			01-FEB-1996			
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0			
	REF: AMM 80-10-02	AFL		TSN:0			0			