




Saint Paul Regional Turbine Center 330 Bravo Lane Saint Paul, MN 55107 Certificate No.: YRR5491L BORESCOPE INSPECTION REPORT

WORK ORDER NUMBER:		PURCHASE ORDER NUMBER:		DATE RECEIVED:	
FS22278				March 4 th 2011	
CUSTOMER:		UNIT NAME:		SERIAL NUMBER:	
Starman Bros Auctions Inc.		Engine Assembly		PCE-DA0417	
TYPE/MODEL:		PART NUMBER:		MANUFACTURER:	
PW530A		N/A		P&WC	
TIME SINCE NEW:	TIME SINCE OVHL:	TIME SINCE REPAIR:	CYC SINCE NEW:	CYC SINCE OVHL:	CYC SINCE REPAIR:
2584.8	-	-	2467	-	-
CUSTOMER REPORTED REASON INSPECTION:					PREVIOUS W.O.:
Customer Requested Borescope of Engine for Condition.					N/A
1. SIGNIFICANT CONDITIONS FOUND DURING BORESCOPE INSPECTION:					
No Visual defects noted with borescope at this date and time.					
2. SUMMARY:					
C/W borescope per customer's request.					
"Given the nature of borescope inspections, it is not possible to directly examine all areas of an engine. Based on this limitation, Dallas Airmotive cannot and does not warrant findings for Inspections against hidden damage not visible by the Dallas Airmotive borescope inspector at the time the work was performed."					
ACTION REQUIRED?		DATE REVIEWED:		BDR NUMBER:	
YES \ NO	$oxed{\boxtimes}$	March 4 th 2011		N/A	
ORIGINATOR:		DATE:		SERVICE REPRESENTATIVE:	
Darrell Capra		March 4 th 2011		Nate Forster	
DISTRIBUTION: W/O FILE _x_ CUSTOMER _x_ BILLING					
QC		ENGR	FILE		





Saint Paul Regional Turbine Center 330 Bravo Lane Saint Paul, MN 55107 Certificate No.: YRR5491L BORESCOPE INSPECTION REPORT







Saint Paul Regional Turbine Center 330 Bravo Lane Saint Paul, MN 55107 Certificate No.: YRR5491L BORESCOPE INSPECTION REPORT