




## Saint Paul Regional Turbine Center 330 Bravo Lane Saint Paul, MN 55107 Certificate No.: YRR5491L BORESCOPE INSPECTION REPORT

| WORK ORDER NUMBER:   |                        | PURCHASE ORDER NUMBER:     |                | DATE RECEIVED:             |                   |
|--|------------------------|----------------------------|----------------|----------------------------|-------------------|
| FS22277  |                        |                            |                | March 4 <sup>th</sup> 2011 |                   |
| CUSTOMER:  |                        | UNIT NAME:                 |                | SERIAL NUMBER:             |                   |
| Starman Bros Auctions Inc.   |                        | Engine Assembly            |                | PCE-DA0416                 |                   |
| TYPE/MODEL:  |                        | PART NUMBER:               |                | MANUFACTURER:              |                   |
| PW530A   |                        | N/A                        |                | P&WC                       |                   |
| TIME SINCE NEW:  | TIME SINCE OVHL:       | TIME SINCE REPAIR:         | CYC SINCE NEW: | CYC SINCE OVHL:            | CYC SINCE REPAIR: |
| 2584.8   | -                      | -                          | 2467           | -                          | -                 |
| CUSTOMER REPORTED REASON INSPECTION:   |                        |                            |                |                            | PREVIOUS W.O.:    |
| Customer Requested Borescope of Engine for Condition.  |                        |                            |                |                            | N/A               |
| SIGNIFICANT CONDITIONS FOUND DURING BORESCOPE INSPECTION:  |                        |                            |                |                            |                   |
|  |                        |                            |                |                            |                   |
| No Visual defects noted with borescope at this date and time.  |                        |                            |                |                            |                   |
| 2. SUMMARY:  |                        |                            |                |                            |                   |
| C/W borescope per customer's request.  |                        |                            |                |                            |                   |
|  |                        |                            |                |                            |                   |
| "Given the nature of borescope inspections, it is not possible to directly examine all areas of an engine. Based on this limitation,   |                        |                            |                |                            |                   |
| Dallas Airmotive cannot and does not warrant findings for Inspections against hidden damage not visible by the Dallas Airmotive borescope inspector at the time the work was performed." |                        |                            |                |                            |                   |
| ·  |                        |                            |                |                            |                   |
| ACTION REQUIRED?   |                        | DATE REVIEWED:             |                | BDR NUMBER:                |                   |
| YES \ NC   | $oxed{egin{array}{c}}$ | March 4 <sup>th</sup> 2011 |                | N/A                        |                   |
| ORIGINATOR:  |                        | DATE:                      |                | SERVICE REPRESENTATIVE:    |                   |
| Darrell Capra  |                        | March 4 <sup>th</sup> 2011 |                | Nate Forster               |                   |
| DISTRIBUTION: W/O FILE _x_ CUSTOMER _x_ BILLING  |                        |                            |                |                            | -                 |
| QC   |                        | ENGR                       | FILE           | _                          |                   |





## Saint Paul Regional Turbine Center 330 Bravo Lane Saint Paul, MN 55107 Certificate No.: YRR5491L BORESCOPE INSPECTION REPORT







## Saint Paul Regional Turbine Center 330 Bravo Lane Saint Paul, MN 55107 Certificate No.: YRR5491L BORESCOPE INSPECTION REPORT

